

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

1. NAME OF FIELD REVISOR	
2. DISTRICT	
3. SANTA FE	☒
4. FILE	☒
5. U.S.G.S.	
6. FIELD OFFICE	
7. OPERATOR	

OIL CONSERVATION DIVISION RECEIVED

P. O. BOX 20811

SANTA FE, NEW MEXICO 87501 OCT 1 - 1984

Form C-103
Revised 12-1

OIL CONSERVATION DIVISION

8. Indicate Type of Lease	☐
9. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG A WELL IN A DIFFERENT RESERVOIR.
USE APPLICATION FOR PERMIT - 1 (FORM C-101) FOR SUCH PROPOSALS.)

1. WELL BELL ☐ GAS WELL ☒ OTHER C02	7. Unit Agreement Name Bravo Dome Carbon Dioxide Gas Unit
2. Name of Operator Amoco Production Company	8. Name of Lease (Name) Bravo Dome Carbon Dioxide Gas Unit
3. Address of Operator P.O. Box 606, Clayton, NM 88415	9. Well No. 1933 331G
4. Location of Well WELL LETTER G 1650 FEET FROM THE North LINE AND 1650 FEET FROM East LINE, SECTION 33 TOWNSHIP 19-N RANGE 33-E N.M.P.M.	10. Field and Pool or Wildcat Bravo Dome Carbon Dioxide Gas Unit 640-Acre Area
11. Elevation (Show whether DF, RT, CR, etc.) 4805' G.L.	12. County Harding

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIATION WORK ☐
COMMENCE DRILLING OPERATIONS ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASINGS ☐
PLUG AND ABANDONMENT ☐

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work, SEE RULE 1103.)

Propose to plug and abandon the subject well. Trip in hole with open ended 3 1/2" drill pipe to 2470' and spot a 200' plug with 83 sacks 22 BBL cement from 2470-2270' at the top of the granite. Cement is Class H with additives. Pulled up to 1908' and spot 200' plug with 110 sacks 29 BBL from 1908-1708' across top of the Glorieta at 1808'. Pull up to 846' and spot a 200' plug 66 sacks 17 BBL Class H cement from 646'-846' across casing shoe at 746'. Pull 5 strands and pump 10 bbl mud to ensure DP is free of cement, continue to pull out of hole. Spot 10 sacks surface plug and erect a P&A marker. Use a fresh water spacer ahead and behind each of the above plugs to keep mud from contaminating cement. Pump 10 BBL ahead and 1 BBL behind cement. All plugs are to be balanced. Pull up out of each plug slowly to minimize cement contamination.

0+2-NMOCDSF 1-J.R.Barnett HOU.Rm.21.156 1-F.J.Nash HOU RM.4.206 1-WF,C 1-WF,H 1-Susp
1-JSM 1-Amerada Hess 1-Amerigas 1-Cities Service 1-Conoco 1-C02 in Action 1-Sun
1-Excelsior 1-Tex 1-Exxon

14. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>John S. McElyea</u>	TITLE <u>Asst. Adm. Analyst</u>	DATE <u>9-26-84</u>
APPROVED BY <u>Roy E. Johnson</u>	TITLE <u>DISTRICT SUPERVISOR</u>	DATE <u>10-2-84</u>
CONDITIONS OF APPROVAL, IF ANY:		