NO. OF COPIES RECEIVED					Form C-103
DISTRIBUTION					Supersedes Old C-102 and C-103
SANTA FE	NEW.	MEXICO OIL CONSI	ERVATION COMMISSION		Effective 1-1-65
FILE					
U.S.G.S.				1	5a. Indicate Type of Lease
LAND OFFICE				<u> </u> _	State Fee. X
OPERATOR					5. State Oil & Gas Lease No.
					mmmmm
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)					
1. OIL GAS OTHER. X					7. Unit Agreement Name
2. Name of Operator					8. Farm or Lease Name
Brooks Exploration Incorporated					Clyde Berlier
3. Address of Operator 1005 Western Federal Savings Building					
718 17th Street, Denver, Colorado 80202					#L 10. Field and Pool, or Wildcat
UNIT LETTER, 990 t FEET FROM THE South LINE AND 990 t FEET FROM					Wildcat
THE West LINE, SECTION 14 TOWNSHIP 21N RANGE 21E NMPM.					
15. Elevation (Show whether DF, RT, GR, etc.)					12. County
6178' GR (est.)					Mora (((((())))
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
		LUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
PERFORM REMEDIAL WORK	•	LOG AND ABANDON [7]	COMMENCE DRILLING OPNS.	Ħ	PLUG AND ABANDONMENT
TEMPORARILY ABANDON		HANGE PLANS	CASING TEST AND CEMENT JOE	,	And Abandonisen
PULL OR ALTER CASING	C	HANGE PLANS	OTHER	, L	
27.152			OTREK		
OTHER					
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.					
This test was spudded 12:10 PM on 9-16-75. A 13-3/4" surface hole was drilled to 40'. 40' of 10-3/4" 40# casing was mudded in at 40'. A 8-3/4" hole was then drilled to 327' where 326' of 7", 24#, casing was run. Halliburton cemented with 50 sacks regular cement, circulated, but cement later fell lower in annulus. WOC 24 hours. Drill out below 7" with 6-1/4" diameter hole to depth of 434' in Dakota Sand. At this point, well blowing gas with low volume. Well was then shut-in and next day gas coming from annulus indicating bad cement job. A bridge plug was then set in open hole @ 327' with one sack cement on top. Well was recemented with 8 sacks regular cement. After cement set, plug was drilled, finding cement scattered down hole. Presently ready to fill hole with cement and plug & abandon (10-7-75).					
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNED TO	on	TITLE F	resident		DATE 10-7-75
APPROVED BY CONDITIONS OF APPROVAL, II	alung FANY:	TITLE	emor peroleum Geol	ggist	DATE 10-10-75