

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NRM2015743815
District RP	
Facility ID	
Application ID	

Release Notification

Not Accepted

Responsible Party

Responsible Party: Cimarex Energy Co.	OGRID: 215099
Contact Name: Laci Luig	Contact Telephone: (432) 571-7800
Contact email: lluig@cimarex.com	Incident # (assigned by OCD)
Contact mailing address: 600 N Marienfeld Street, Ste. 600 Midland, TX 79701	

Location of Release Source

Latitude 32.155416 _____ Longitude -104.227949 _____
(NAD 83 in decimal degrees to 5 decimal places)

Site Name: Scoter 6-31 Federal Com 7H,43H,44H Battery	Site Type: Battery Pad
Date Release Discovered: 5/24/2020	API# (if applicable)

Unit Letter	Section	Township	Range	County
M	6	25S	27E	Eddy

Surface Owner: State Federal Tribal Private (Name: _____)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 85 bbls	Volume Recovered (bbls) 1 bbls
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release: Mechanical Failure

We found that the 2" X 1" reducer on top of the discharge side of the transfer pump had broken in the 1" thread. We determined the spilled volume to be 85 barrels of produced water and we recovered 1 barrel. We replaced the discharge piping on the pump with stainless steel and realigned the pump skid. We will work on a kill and alarm system to shut pumps down when there is a low discharge pressure reading. We used a hydrovac to remove impacted soil and will delineate the area and determine pathway forward.

