Form 3160-5 (September 2001)

Oil Cons. N.M. DIV-Dist. 2

DEPARTMENT OF THE INTER 201 W. Grand Avenue BUREAU OF LAND MANAGEME Artesia, NM 88210

FORM APPROVED OMB No. 1004-0135 Expires January 31, 2004

SUNDRY NOTICES AND REPORTS ON WELLS

5. Lease Serial No.

Do not use this form for proposals to drill or re enter an				NM-045275
an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverses 1777				7 If Unit or CA/Agreement, Name and/or No.
1 Type of Well			237410.077870	
1 Type of Well X Oil well Gas Well Other			(C)	8. Well Name and No.
2 Name of Operator Values Petroleum Corporation			Make Toolah 12.1	CONOCO AGK FEDERAL #2
3a. Address	COTPOTACTOR	3b Phone No (49 clude	PECENED IN AN	9. API Well No. 30-015-20457
3a. Address 105 S.4th St-Artesia, NM 88210 4 Location of Well (Footage, Sec. I. R. M. OR Survey Description)			a area code) ARIESTI	10. Field and Pool, or Exploratory Area
4 Location of Well	(Footage, Sec.,T.,R.,M.,	OR Survey Description)	- GU	DAGGER DRAW UPPER PENN SOUTH
UNIT G 1980' FNL, 19		Γ20S-R24E	1505628717800	11. County or Parish, State
12 CHECK APPRO	DDIATE BOY/EO)	TO INDIONTE MAT	TIDE OF HOUSE	EDDY, NM
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOT TYPE OF SUBMISSION				ORT, OR OTHER DATA
	ION		TYPE OF ACTION	
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat	Reclamation	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	Other
	Change Plans	X Plug and Abandon	Temporarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	
testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have completed, and the operator has determined that the site is ready for final inspection.) YATES PETROLEUM CORPORATION RESPECTFULLY REQUESTS TO PLUG & ABANDON AS FOLLOWS: Call BLM 24 hours before commencing operations. Call OCD 24 hours before commencing operations. 1. MIRU WSU & all safety equipment. 2. POH w/ tubing +/- 2769'. TIH w/ overshot wash pipe to fish for rods @ +/- 2500'. Attempt to unset pump & POH. If pump will not come free, pull rods into & POH. TIH w/ overshot to fish out tubing & stuck tubing anchor @ +/- 7475'. 3. TIH w/ tubing to set 45 sk Class C cement plug from 7459'-7744' across Cisco perfs. WOC 4 hrs & tag plug reset if necessary. 4. TIH w/ tubing & set 15 sk plug from 5399'-5499' across Wolfcamp top; pull tbg up hole & circ clean.				
5. TIH w/ tbg & set 15 sk p 6. MIRU WL to run free po casing stub @ +/- 2700'.; 7. Set 40 sk plug from 200	plug from 5015'-5115 pint. Cut casing @ fro POH. WOC & tag plo 78'-2178' across Glog	i' across Abo top. Pul ee point & pull csg. T ug, raset if necessary getta. Reverse circ tb	I tbg up hole & circ clean. IH w/ tbg & set 40 sk plug a g clean & POH. WOC & tag	cross
14 I hereby certify that the forego	pidg from 909 - 1909	across intermediate	casing shoe; POH. WOC &	
Name (Printed/Typed)	"Cc ₆ he		Title	continued on next page
DONNA CLACK			REGUI	LATORY COMPLIANCE TECH
Signature Anna (Anh			Date	
March 27, 2005				
		R FEDERAL OR STATE	OFFICE USE	
Approved by ORIG SGD.) ALEXIS C. SWOBODA PETROLEUM Conditions of approval, if any, are attached. Approval of this notice does not warrant or				INEER Date APR 1 0 2003
certify that the applicant holds legal or equitable title to those rights in the subject lease			Office	
Which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willbully to make to any department or agency of the United				
States any false, fictitious or fraudulent	43 U.S.C. Section 1212, make t statements or representations	it a crime for any person knowit as to any matter within its juris	ngly and willbully to make to any departm diction	ent or agency of the United

continued:

CONOCO AGK FEDERAL #2 SEC 26 T20S R24E EDDY COUNTY, NM

- 9. TIH w/ tubing & set 40 sk plug from 361'-461' across surface casing shoe; POH. WOC & tag plug, reset if needed. 10. Spot 15 sk Class C cement plug at surface. 11. Remove all surface equipment & weld dry hole marker per regulations.



