

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010**SUNDRY NOTICES AND REPORTS ON WELLS**
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.

NM90807

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☒ Oil Well☐ Gas Well☒ Other

2. Name of Operator

SM Energy Company

3a. Address

3300 N. A Street, Bldg 7, Suite 200 Midland, TX 79701-3268-1789

3b. Phone No. (include area code)

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.

Osage Federal 34-09

9. API Well No.

30-015-26157

10. Field and Pool or Exploratory Area

Parkway Bone Spring & Wolfcamp

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec. 34-T19S-R29E

990' FNL & 1980' FEL (ULB)

11. Country or Parish, State

Eddy Co.

New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomple in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Contact BLM in Carlsbad @ (575) 887-6544 24 hrs prior to MIRU

TOH w/ tbg. PU pkr and tih. Set pkr @ approx. 4000' and est inj rate

Pump an estimated 300 to 400 sxs on cmt after establishing inj rate. Do not add any accelerator (CaCl₂) in the cmt.Repeat the process until a squeeze pressure is obtained. *Tag Top of Cmt @ 4000'*

Rel pkr toh and free point csg. Cut off and pull 5-1/2" csg attempt to cut off 50' below the 8-5/8" shoe. If csg is not free 50' below shoe contact BLM for instruction

Tih and circulate well with 10 ppg gal fluid containing 20 lbs gel per 1000 gals.

Spot a 100' plug 50' inside and outside of 5-1/2" stub *130' plug (50' in / 80' out) woc Tag 3150*

Spot a 100' plug inside the 8-5/8" csg from 1200 to 1100' across the base of the salt and tag

Perforate the 8-5/8" in casing @ 450' and spot a balanced plug from 450 to 293'. This plug will cover the 20" shoe and the top of salt. Tag plug

Perforate the 8-5/8" csg @ 60 and spot a surface plug inside and out the 8-5/8" csg.

Cut off the wh 3' below ground level. Verify cmt to surface and weld a steel plate on top. Cut a hole in the steel plate and weld a 2" 1500 psi ball valve over the hole. Fill the valve body with lubricating grease and shut.

Install a DHM and fill in the cellar.

Received verbal approval from BLM Engineer Wesley Ingram on 7/07/11

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Donna Huddleston

Title Engineering Tech

Signature

Donna Huddleston

Date 07/07/2011

RECLAMATION PROCEDURE
ATTACHED

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

James A. Brown

Title

SEPS

Date

8-30-11


Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

CFD

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

*9/7/2011*Accepted for record
NMOCD


WELLBORE DIAGRAM

Osage Federal #9

LEASE: Osage
LOCATION: 990' FNL & 1980' FEL
FIELD: Osage
CURRENT STAT. PROD

WELL NO. 9
SEC: 34 T: 19S R: 29E
GL: 3319' CT/ST: EDDY,NM
KB: 3327'

API # : 30-015-26157
SPUD: 8/3/89
COMP: 9/15/90
INITIAL FROM: BoneSpring & WolfCamp



WELL HISTORY

- 9/7/1989 Run GR/CCL/CBL & Perf 7790-8002'
Acidize w/ 2750g 15% HCl
dropping 66 BS's balling out
3 BPM @ 1450-2000 psi
Frac w/ 72,000g 30# XL, 179,680#16/30 Ottawa
& 31,760# 16/30 RCS30BPM@ 1450 psi
- 10/12/1989 Perf 7654-7667 w/ 17 perfs
acidized w/2500 2500g 20% HCL
Broke at 1600 psi and 4 BPM
- 10/14/1989 Perf 6972-7188 w/38 perfs
Acidize w/3000g 15% NEFE
at 4 BPM and 1300 psi balled out
frac w/133,000g 30#XL, 341,000# 16/30
Ottown, 70,000 16/30# RCS @ 49 BPM.
IPF 200 BO & 300 BW
- 9/15/1990 Perf Wolfcamp 9256-9281 (2 SPF)
No record of any stimulation
- 9/1/1991 Comingle BoneSprings and WolfCamp
- 2/2/2001 Change to Plunger lift
- 10/1/2010 5 Bo, 5 Bw, 110 Mcf
- 11/1/2010 shut in due to tubing blockage
- 12/10/2010 Unable to free TAC @ 9135'. Found tbg. Stuck @ 4000'. Cut tbg @ 3973'. TOOH. Latch on to fish at 3973'. Jarred on fish for 3 hours w/o success. Cut tbg. @ 4098' below fish. Latch on to fish @ 3973' jarred for 3.5 hours pulling up to 50 points w/o success.
- 6/7/2011 RIH w/ shoe. Wash over fish @ 3998'. Cut down to 4032'. TOH w/ 27' tbg. and 8' sliver of csg. RIH cut down to 4064'. TOH RIH w/ impression block. Looks like cutting into formation. TOH. SIW

DATE: 12/12/2010
PREPARED BY:
MHK

PBTD: 9358'
TD: 9400'

WELLBORE DIAGRAM


Osage Federal #34-9

PROPOSED PA

LEASE: Osage
LOCATION: 990' FNL & 1980' FEL
FIELD: Osage
CURRENT STAT. PROD

WELL NO. 9
SEC: 34 T: 19S R: 29E
GL: 3319' CT/ST: EDDY,NM
KB: 3327'

API # : 30-015-26157
SPUD: 8/3/89
COMP: 9/15/90
INITIAL FROM: BoneSpring & WolfCamp



WELL HISTORY

- 9/7/1989 Run GR/CCL/CBL & Perf 7790-8002'
Acidize w/ 2750g 15% HCl
dropping 66 BS's balling out
3 BPM @ 1450-2000 psi
Frac w/ 72,000g 30# XL, 179,680#16/30 Ottawa & 31,760# 16/30 RCS30BPM@ 1450 psi
- 10/12/1989 Perf 7654-7667 w/ 17 perfs
acidized w/2500 2500g 20% HCL
Broke at 1600 psi and 4 BPM
- 10/14/1989 Perf 6972-7188 w/38 perfs
Acidize w/3000g 15% NEFE
at 4 BPM and 1300 psi balled out
frac w/133,000g 30#XL, 341,000# 16/30 Ottown, 70,000 16/30# RCS @ 49 BPM.
IPF 200 BO & 300 BW
- 9/15/1990 Perf Wolfcamp 9256-9281 (2 SPF)
No record of any stimulation
- 9/1/1991 Comingle BoneSprings and WolfCamp
- 2/2/2001 Change to Plunger lift
- 10/1/2010 5 Bo, 5 Bw, 110 Mcf
- 11/1/2010 shut in due to tubing blockage
- 12/10/2010 Unable to free TAC @ 9135'. Found tbg. Stuck @ 4000'. Cut tbg @ 3973'. TOOH. Latch on to fish at 3973'. Jarred on fish for 3 hours w/o success. Cut tbg. @ 4098' below fish. Latch on to fish @ 3973' jarred for 3.5 hours pulling up to 50 points w/o success.
- 6/7/2011 RIH w/ shoe. Wash over fish @ 3998'. Cut down to 4032'. TOH w/ 27' tbg. and 8' sliver of csg. RIH cut down to 4064'. TOH RIH w/ impression block. Looks like cutting into formation. TOH. SIW

DATE: 12/12/2010
PREPARED BY:
MHK

PBTD: 9358'
TD: 9400'

**BUREAU OF LAND MANAGEMENT
Carlsbad Field Office
620 East Greene Street
Carlsbad, New Mexico 88220
575-234-5972**

**Permanent Abandonment of Federal Wells
Conditions of Approval**

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within **ninety (90)** days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. **Notification:** Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. **Blowout Preventers:** A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. **Mud Requirement:** Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. **Cement Requirement:** Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). **The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.**

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. Subsequent Plugging Reporting: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

8. Trash: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.

J. Amos 3/6/11



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office
620 E. Greene St
Carlsbad, New Mexico 88220-6292
www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its pre-disturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos
Supervisory Environmental Protection Specialist
575-234-5909, 575-361-2648 (Cell)

Cody Layton
Natural Resource Specialist
575-234-5959

Terry Gregston
Environmental Protection Specialist
575-234-5958

Trishia Bad Bear
Natural Resource Specialist
575-393-3612

Bobby Ballard
Environmental Protection Specialist
575-234-2230

Todd Suter
Surface Protection Specialist
575-234-5987

Randy Rust
Environmental Protection Specialist
575-234-5943

Doug Hoag
Civil Engineering Technician
575-234-5979

Linda Denniston
Environmental Protection Specialist
575-234-5974

Jennifer Van Curen
Environmental Protection Specialist
575-234-5905

Justin Frye
Environmental Protection Specialist
575-234-5922