Form 3160-5

UNITED STATES

COPY

FORM APROVED

(February 2005)		TMENT OF THE INTERIOR U OF LAND MANAGEMENT	(· · · · · ·), 1004-0137 March 31, 2007	
		ICES AND REPORTS ON WEL	LLS		5. Lease Serial No.	1	
Do not use this form for proposals to drill or to re-enter an				NMNM 97885			
abandoned well. Use Form 3160-3 (APD) for such proposals					6. If Indian, Allottee or 1	ribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2					2 11 1 62 1		
4 Type of Well					7. Unit or CA Agreeme	nt Name and No.	
1. Type of Well] Oil Well [] Gas W	ell 🗹 Other SWD WELL			8 Well Name and No.		
2. Name of Operator					CAM	PANA 1	
DEV	ON ENERGY PRODUC	TION COMPANY, LP			9. API Well No		
3a, Address			3b. Phone No. (include area code)		30-015-21098		
20 North Broady	vay, Ste 1500, Oklahon	na City, OK 73102	405-552-4615		10. Field and Pool, or Exploratory Area		
	4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					CABIN LAKE	
1980 FNL 660 FWL 6 T22S R31E				11. County or Parish, State			
					Eddy	NM	
TVDE A		(APPROPRIATE BOX(es) TO I					
11750	SSUBMISSION		······	E OF ACTION			
✓ Notice o	f Intent	Acidize	Deepen Fracture Treat	-	tion (Start/Resume)	Water Shut-Off	
Subsequ	ent Report	Alter Casing Casing Repair	Fracture Treat New Construction	Reclamation Recommendation	<u></u>	Well Integrity Other	
	andonment Notice	Change Plans	✓ Plug and Abandon		rarily Abandon] Outci	
		Convert to Injection	Plug Back	Water [Disposal		
deepen directionally or the Bond No on file wi interval, a Form 3160-	r recomplete honzontally, give si ith BLM/BIA Required subsequ 4 shall be filed once testing has	Diearly state all pertinent details, and give pubsurface location and measured and true lent reports shall be filed within 30 days foll been completed Final Abandonment Noti	e vertical depths of all pertinent mai illowing completion of the involved of	rkers and zones A	Attach the Bond under which the operation results in a multiple com	work will be performed or provide	
PROPOSED PLUG & ABANDONMENT 1. MIRU. POOH w/3-1/2" Injection tubing and packer from 2. Circulate wellbore w/9.5# mud. 3. Set CIBP @ 5920'. Spot 25 sx cmt on top. Calc. TOC 4. Spot 70 sx cmt @ 3750'. WOC & Tag. (Calc. TOC @ 5. Spot 60 sx cmt @ 595'. WOC & Tag. (Calc. TOC @ 6. Circ 50 sx surface plug from 120' to surface. 7. Cut wellhead off 3' BGL. Set P&A marker. (proposed schemat attached)			C @ 5795'. 〕3465')			CEIVED C 0 8 2011 CD ARTESIA	
(proposed s	schemat attached)			/2 Ac	2/21/201 FAD cepted for recor	lacle	
					NMOCD		

14. I hereby certify that the foregoing is true and correct Name: Ronnie Slack Title **Operations Technician** Signature Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Date Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would Office entitle the applicant to conduct or operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212 make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictilious or fraudulent statements or representations as to any matter within its junsdiction

Ļ

