Office	State of New M			Form C-103
District I	Energy, Minerals and Natu	ral Resources		March 4, 2004
1625 N. French Dr., Hobbs, NM 87240			WELL API NO.	20
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION		30-015-339	
District III	1220 South St. Fr		5. Indicate Type of Le	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 8	37505	STATE	FEE 🗆
1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lea	ase No.
SLINDRY NOTICE	ES AND REPORTS ON WE		7. Lease Name or Unit	t Agreement Name:
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	SALS TO DRILL OR TO DEEPEN	OR PLUG BACK TO A	Salt Draw 10 State	
1. Type of Well:		RECEIVED	8. Well Number	
Oil Well Gas Well X	Other		1	
2. Name of Operator		APR 1 3 2005	9. OGRID Number	
Nearburg Producing Company		CULTANTERIA	015742	
3. Address of Operator			10. Pool name or Wild	dcat
3300 N A St., Bldg 2, Ste	120, Midland, TX 79705		Salt Draw: Atoka	
4. Well Location				
Unit LetterA :	840feet from theNor	rth line and	660 feet from th	ne <u>East</u> line
Section 10	Township 25S	Range 28E	NMPM C	County Eddy
	11. Elevation (Show whether			county Ludy
		DK, KKD, K1, GK, eR 2962		
Pit or Below-grade Tank Application (For p			q)	
Pit location: UL Sect Twp				ament freeh resotan reall
_		=		
Distance from nearest surface water_			. Twp Rng	;
feet from the line a	nd feet from the	line		
10 01 1 4	nnuantiata Day ta Indiaata	Noture of Notice	Domant on Other De	ata .
12. Check A	DDEODHAIE DOX 10 INCICAR	analine of nonce.	Kedori, or Ulber 12	ala
•	ppropriate Box to Indicate	1 ·	•	
NOTICE OF INTE	NTION TO:	SUB	SEQUENT REPO	RT OF:
•	NTION TO:	1 ·	SEQUENT REPO	
NOTICE OF INTE	NTION TO:	SUB	SEQUENT REPOI A NG OPNS. F	RT OF: ALTERING CASING PLUG AND
NOTICE OF INTE	NTION TO: PLUG AND ABANDON	SUB:	SEQUENT REPOI A NG OPNS. F	RT OF: ALTERING CASING —
NOTICE OF INTE	NTION TO: PLUG AND ABANDON CHANGE PLANS	SUBS REMEDIAL WORK COMMENCE DRILLII CASING TEST AND	SEQUENT REPOI A NG OPNS. A	RT OF: ALTERING CASING PLUG AND
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	NTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	SUBSTREMEDIAL WORK COMMENCE DRILLING CASING TEST AND CEMENT JOB OTHER: 7" csg an	SEQUENT REPORT AND	RT OF: ALTERING CASING PLUG AND ABANDONMENT
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work).	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION d operations. (Clearly state all	SUBS REMEDIAL WORK COMMENCE DRILLII CASING TEST AND CEMENT JOB OTHER: 7" csg an pertinent details, and g	SEQUENT REPORE A NG OPNS. A C d cmt ive pertinent dates, includes	RT OF: ALTERING CASING PLUG AND ABANDONMENT X uding estimated date
NOTICE OF INTEPERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION d operations. (Clearly state all	SUBS REMEDIAL WORK COMMENCE DRILLII CASING TEST AND CEMENT JOB OTHER: 7" csg an pertinent details, and g	SEQUENT REPORE A NG OPNS. A C d cmt ive pertinent dates, includes	RT OF: ALTERING CASING PLUG AND ABANDONMENT X uding estimated date
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work). or recompletion.	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION d operations. (Clearly state all SEE RULE 1103. For Multiple	SUBSTREMEDIAL WORK COMMENCE DRILLII CASING TEST AND CEMENT JOB OTHER: 7" csg an pertinent details, and get Completions: Attach	SEQUENT REPORMENT AND	RT OF: ALTERING CASING PLUG AND ABANDONMENT Adding estimated date oposed completion
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work). or recompletion. Drld to 11076 and lost par	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION d operations. (Clearly state all SEE RULE 1103. For Multiple tial returns. Mix LCM pi	SUBSTREMEDIAL WORK COMMENCE DRILLII CASING TEST AND CEMENT JOB OTHER: 7" csg an pertinent details, and ge Completions: Attach	SEQUENT REPORMENT AND	RT OF: ALTERING CASING PLUG AND ABANDONMENT Adding estimated date oposed completion eak, well
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work). or recompletion. Drld to 11076 and lost par flowing. Circ well on chk	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION d operations. (Clearly state all SEE RULE 1103. For Multiple tial returns. Mix LCM pi , displace w/ brine and 1	SUBSTREMEDIAL WORK COMMENCE DRILLII CASING TEST AND CEMENT JOB OTHER: 7" csg an pertinent details, and ge completions: Attach	SEQUENT REPORMENT AND	RT OF: ALTERING CASING PLUG AND ABANDONMENT Luding estimated date oposed completion eak, well Build mud
NOTICE OF INTER PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work). or recompletion. Drld to 11076 and lost par flowing. Circ well on chk weight and drld to 11525 m	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION d operations. (Clearly state all SEE RULE 1103. For Multipl tial returns. Mix LCM pi , displace w/ brine and l ixing LCM and building mu	SUBSTREMEDIAL WORK COMMENCE DRILLII CASING TEST AND CEMENT JOB OTHER: 7" csg an pertinent details, and ge completions: Attach	SEQUENT REPORE NG OPNS.	RT OF: ALTERING CASING PLUG AND ABANDONMENT IX Uding estimated date oposed completion eak, well Build mud d circ gas out of
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work). or recompletion. Drld to 11076 and lost par flowing. Circ well on chk	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION d operations. (Clearly state all SEE RULE 1103. For Multiple tial returns. Mix LCM pi , displace w/ brine and 1 ixing LCM and building mu 273 jts 7" 29# P110 and	SUBSTREMEDIAL WORK COMMENCE DRILLII CASING TEST AND CEMENT JOB OTHER: 7" csg an pertinent details, and ge e Completions: Attach 11. Drl to 11337 ost fulls returns. d weight. Drld to N80 LTC csg. Set	SEQUENT REPORMENT AND	RT OF: ALTERING CASING PLUG AND ABANDONMENT Ix Iding estimated date oposed completion eak, well Build mud d circ gas out of ollows: Lead
NOTICE OF INTER PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work). or recompletion. Drld to 11076 and lost par flowing. Circ well on chk weight and drld to 11525 m hole. RU csg crew and ran slurry - 735 sxs BJ H + ad	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION doperations. (Clearly state all SEE RULE 1103. For Multiple tial returns. Mix LCM pi , displace w/ brine and 1 ixing LCM and building mu 273 jts 7" 29# P110 and ditives. Tail slurry - 4	SUBSTREMEDIAL WORK COMMENCE DRILLII CASING TEST AND CEMENT JOB OTHER: 7" csg an pertinent details, and ge e Completions: Attach 11. Drl to 11337 ost fulls returns. d weight. Drld to N80 LTC csg. Set 00 sxs 15/61 + add	SEQUENT REPORMENT AND	RT OF: ALTERING CASING PLUG AND ABANDONMENT Iding estimated date oposed completion eak, well Build mud d circ gas out of ollows: Lead . TOC @ 4100'
NOTICE OF INTER PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work). or recompletion. Drld to 11076 and lost par flowing. Circ well on chk weight and drld to 11525 m hole. RU csg crew and ran	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION doperations. (Clearly state all SEE RULE 1103. For Multipl tial returns. Mix LCM pi , displace w/ brine and l ixing LCM and building mu 273 jts 7" 29# P110 and ditives. Tail slurry - 4 csg clips, install tbg he	REMEDIAL WORK COMMENCE DRILLII CASING TEST AND CEMENT JOB OTHER: 7" csg an pertinent details, and ge completions: Attach 11. Drl to 11337 ost fulls returns. d weight. Drld to N80 LTC csg. Set (00 sxs 15/61 + add ad and test to 1506	SEQUENT REPORMENT AND	RT OF: ALTERING CASING PLUG AND ABANDONMENT Iding estimated date oposed completion eak, well Build mud d circ gas out of ollows: Lead . TOC @ 4100'
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work). or recompletion. Drld to 11076 and lost par flowing. Circ well on chk weight and drld to 11525 m hole. RU csg crew and ran slurry - 735 sxs BJ H + ad per temp survey. ND, set	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION doperations. (Clearly state all SEE RULE 1103. For Multipl tial returns. Mix LCM pi , displace w/ brine and l ixing LCM and building mu 273 jts 7" 29# P110 and ditives. Tail slurry - 4 csg clips, install tbg he	REMEDIAL WORK COMMENCE DRILLII CASING TEST AND CEMENT JOB OTHER: 7" csg an pertinent details, and ge completions: Attach 11. Drl to 11337 ost fulls returns. d weight. Drld to N80 LTC csg. Set (00 sxs 15/61 + add ad and test to 1506	SEQUENT REPORMENT AND	RT OF: ALTERING CASING PLUG AND ABANDONMENT Iding estimated date oposed completion eak, well Build mud d circ gas out of ollows: Lead . TOC @ 4100'
NOTICE OF INTER PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work). or recompletion. Drld to 11076 and lost par flowing. Circ well on chk weight and drld to 11525 m hole. RU csg crew and ran slurry - 735 sxs BJ H + ad per temp survey. ND, set test. PU slimhole drillst	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION d operations. (Clearly state all SEE RULE 1103. For Multipl tial returns. Mix LCM pi , displace w/ brine and l ixing LCM and building mu 273 jts 7" 29# P110 and ditives. Tail slurry - 4 csg clips, install tbg he ring and TIH w/ drlg asse	REMEDIAL WORK COMMENCE DRILLII CASING TEST AND CEMENT JOB OTHER: 7" csg an pertinent details, and ge completions: Attach 11. Drl to 11337 ost fulls returns. d weight. Drld to N80 LTC csg. Set (00 sxs 15/61 + add ad and test to 1500 mbly. Cont. drlg.	SEQUENT REPORE ANG OPNS. A A A A A A A A A A A A A	RT OF: ALTERING CASING PLUG AND ABANDONMENT Ix Uding estimated date oposed completion eak, well Build mud d circ gas out of follows: Lead . TOC @ 4100' OK. NU BOPE and
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work). or recompletion. Drld to 11076 and lost par flowing. Circ well on chk weight and drld to 11525 m hole. RU csg crew and ran slurry - 735 sxs BJ H + ad per temp survey. ND, set	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION d operations. (Clearly state all SEE RULE 1103. For Multiple tial returns. Mix LCM pi , displace w/ brine and l ixing LCM and building mu 273 jts 7" 29# P110 and ditives. Tail slurry - 4 csg clips, install tbg he ring and TIH w/ drlg asse	REMEDIAL WORK COMMENCE DRILLII CASING TEST AND CEMENT JOB OTHER: 7" csg an pertinent details, and ge completions: Attach 11. Drl to 11337 ost fulls returns. d weight. Drld to N80 LTC csg. Set (00 sxs 15/61 + add ad and test to 1500 mbly. Cont. drlg.	SEQUENT REPORT AND	RT OF: ALTERING CASING DELUG AND ABANDONMENT It is a stimated date oposed completion eak, well Build mud doirc gas out of collows: Lead Toc @ 4100' OK. NU BOPE and
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work). or recompletion. Drld to 11076 and lost par flowing. Circ well on chk weight and drld to 11525 m hole. RU csg crew and ran slurry - 735 sxs BJ H + ad per temp survey. ND, set test. PU slimhole drillst I hereby certify that the information ab grade tank has been/will be constructed or cl	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION d operations. (Clearly state all SEE RULE 1103. For Multiple tial returns. Mix LCM pi , displace w/ brine and l ixing LCM and building mu 273 jts 7" 29# P110 and ditives. Tail slurry - 4 csg clips, install tbg he ring and TIH w/ drlg asse	REMEDIAL WORK COMMENCE DRILLII CASING TEST AND CEMENT JOB OTHER: 7" csg an pertinent details, and ge completions: Attach 11. Drl to 11337 ost fulls returns. d weight. Drld to N80 LTC csg. Set 00 sxs 15/61 + add ad and test to 1500 mbly. Cont. drlg. best of my knowledge cs , a general permit	SEQUENT REPORMANG OPNS. A Of cmt ive pertinent dates, inclusive diagram of proceeding and had drilling brown and had drilling brown and had drilling brown and circ. 11700, cond mud and 11700'. Cmt as for itives. WOC 68 hrs opsi for 30 mins and belief. I further certification and lattached) alternation.	RT OF: ALTERING CASING DELUG AND ABANDONMENT Luding estimated date oposed completion eak, well Build mud d circ gas out of follows: Lead . TOC @ 4100' OK. NU BOPE and
NOTICE OF INTER PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work). or recompletion. Drld to 11076 and lost par flowing. Circ well on chk weight and drld to 11525 m hole. RU csg crew and ran slurry - 735 sxs BJ H + ad per temp survey. ND, set test. PU slimhole drillst	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION d operations. (Clearly state all SEE RULE 1103. For Multiple tial returns. Mix LCM pi , displace w/ brine and l ixing LCM and building mu 273 jts 7" 29# P110 and ditives. Tail slurry - 4 csg clips, install tbg he ring and TIH w/ drlg asse	REMEDIAL WORK COMMENCE DRILLII CASING TEST AND CEMENT JOB OTHER: 7" csg an pertinent details, and ge completions: Attach 11. Drl to 11337 ost fulls returns. d weight. Drld to N80 LTC csg. Set 00 sxs 15/61 + add ad and test to 1500 mbly. Cont. drlg. best of my knowledge s, a general permit [T.E	SEQUENT REPORT AND	RT OF: ALTERING CASING DELUG AND ABANDONMENT Luding estimated date oposed completion eak, well Build mud d circ gas out of follows: Lead TOC @ 4100' OK. NU BOPE and lify that any pit or belowive OCD-approved plan LTE 4/12/05
NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work). or recompletion. Drld to 11076 and lost par flowing. Circ well on chk weight and drld to 11525 m hole. RU csg crew and ran slurry - 735 sxs BJ H + ad per temp survey. ND, set test. PU slimhole drillst I hereby certify that the information ab grade tank has been/will be constructed or cl	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION d operations. (Clearly state all SEE RULE 1103. For Multiple tial returns. Mix LCM pi , displace w/ brine and l ixing LCM and building mu 273 jts 7" 29# P110 and ditives. Tail slurry - 4 csg clips, install tbg he ring and TIH w/ drlg asse	REMEDIAL WORK COMMENCE DRILLII CASING TEST AND CEMENT JOB OTHER: 7" csg an pertinent details, and ge completions: Attach 11. Drl to 11337 ost fulls returns. d weight. Drld to N80 LTC csg. Set 00 sxs 15/61 + add ad and test to 1500 mbly. Cont. drlg. best of my knowledge s, a general permit [T.E	SEQUENT REPORMANCE AND A SJORDANG PROPOSE AND A SEQUENT REPORMANCE AND	RT OF: ALTERING CASING DELUG AND ABANDONMENT Luding estimated date oposed completion eak, well Build mud d circ gas out of follows: Lead TOC @ 4100' OK. NU BOPE and lify that any pit or belowive OCD-approved plan LTE 4/12/05

____ TITLE____

APPROVED BY___

Conditions of approval, if any:

____DATE _