Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135

Expires: July 31, 2010

Lease Serial No. NMLC029395B

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

	·	,	•				
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
Type of Well Gas Well ☐ Oth			8. Well Name and No. TURNER B 101				
Name of Operator LINN OPERATING INCORPO	LLAHAN		9 API Well No. 30-015-26695-00-S1				
3a. Address 600 TRAVIS STREET SUITE HOUSTON, TX 77002	3b Phone No. Ph: 281-840	(include area code)-4272	e)	10. Field and Pool, or Exploratory GRAYBURG			
4. Location of Well (Footage, Sec., T			11. County or Parish, and State				
Sec 20 T17S R31E NWNW 990FNL 1150FWL			EDDY COUNTY, NM				
12. CHECK APPR	ROPRIATE BOX(ES) TO) INDICATE	NATURE OF	NOTICE, RE	EPORT, OR O	THER DA	Τ A
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi Workover Procedures 6/18/2012 ? Spud in, RU. ND 500 psi. Ready to drill CIBP p rack TIH w/ bit as follows; 4 3/ up tbg. off rack. Tag fill/ CIBP Sulfate, CIBP @2818' drill on 6/19/2012 - Crew drove to loc.	ally or recomplete horizontally, it will be performed or provide operations. If the operation resondonment Notices shall be fil inal inspection. WH NUBOP and catch per BLM. Pick up 6-3 1/2' 4' bit, X-over, 45-jts 2 7/8 @2800'. RU Lucky Reveplug well kick off continued continue to drill out CIBI	New Plug Plug Plug int details, including give subsurface I the Bond No. on sults in a multiple ed only after all r an. MIT test we drill collars. a stres Unit. State to drill. Lay	ure Treat Construction and Abandon Back Ing estimated startion ocations and meas file with BLM/BI completion or recequirements, including the startion of t	Reclama Recomp Recomp Tempora Water D ng date of any p ured and true ve A. Required sul completion in a a iding reclamation aul Swartz of ver, off to pick O' fill Iron H 3-stands.	lete arily Abandon bisposal roposed work and rtical depths of all bsequent reports sl new interval, a For n, have been comp	approximate pertinent mahall be filed wm 3160-4 shableted, and the	rkers and zones. Athin 30 days all be filed once
6/20/2012 - TIH w/ 11 stds, tag plug @ 3180?, RU swivel. Drill on plug @ 3180? iron sulfate in the							D APTEGIO
14. Thereby certify that the foregoing is	true and correct. Electronic Submission # For LINN OPERA mitted to AFMSS for proce	TING INCORP	PŘÁTED, sent t	o the Carisba	ď		
Name (Printed/Typed) TERRY B	CALLAHAN	- ,	Title REGUI	LATORY SPE	ECIALIST III	LROad	0 9/18/12
Signature (Electronic Submission)			Date 07/30/2012 Accepted for record NMOCD				
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE US	SE		
Approved By ACCEPTED			JAMES A TitleSUPERV		Date 09/02/201		
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conduction	Office Carlsba						
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulents	U.S.C. Section 1212, make it a	crime for any pe	rson knowingly ar	id willfully to m	ake to any departn	nent or agenc	y of the United

Additional data for EC transaction #144154 that would not fit on the form

32. Additional remarks, continued

returns. Cont to drill iron sulfate and bearing in returns. RD swivel. TOH w/ all tbg & bit. Cones on bit worn out. Run new bit.

6/21/2012 - Kill well, start drilling w/ new bit drilled 3180'-3481'.

6/22/2012 - TIH tag fill @3350' lost 130' over night. Start circulating tbg plugged off TOH w/ tbg and collars, bit and collars plugged clean out TIH w/ bit, collars and tbg tag and start drill @3350' drill out to 3450' pull above perf.

6/25/2012 - TIH w/ bit, collars and tbg tag fill at 3693' broke circulation & clean dwn to 3819'. Circulate well clean TOH w/ all tbg lay dwn collars and bit, RD Lucky Reveres Unit.

6/26/2012 ? RiH w/ pkr & tbg. Set pkr @ 2676?, acidize well, flowback well.

6/27/2012 - Open up well to flow back tank flowed back 260bbl. all water. Release pkr TOH LD w/ 115-jts of 2 7/8" workstring. RU TIH w/ BHA-tbg as follows: 2 7/8"x32.50' MA @3714', 2 7/8"x4' perf. sub., 2 7/8" SN @3677', 31-jtsx1007', 2 7/8"x5 1/2"x3.40'-TAC @2669', 82-jts x2666' to surface. ND catch pan, B.O.P. Set TAC 12pnt.

6/28/2012 - PU pump & RIH with rods. Tagged with total of 132 rods in tubing (tight spot @3350'). POOH with rods & pump. ND wellhead, NU BOP, POOH with tubing.

6/29/2012 - PU assembly & RIH with production tbg and BHP, tag fill @3735' . ND BOP , set TAC & landed tubing. PU pump & RIH with rods. Space well out & hung well on. Well pumped up to 500# no bleed off. Well online. RD