Submit 3 Copies To Appropriate District  Office  State of New Mex		Form C-103
District I Energy, Minerals and Natur 1625 N. French Dr., Hobbs, NM 88240	ral Resources	May 27, 200 WELL API NO.
District II OIL CONCEDIVATION		30-01.7 5
1301 W. Grand Ave., Artesia, NM 88210  District III  1220 South St. Fran		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE 6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505		o. State Off & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	Ī	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO	D CHCH	Henry 26
PROPOSALS.)		8. Well Number 2
1. Type of Well: Oil Well ☐ Gas Well ☐ Other  2. Name of Operator		9. OGRID Number
Devon Energy Production Company, LP		6137
3. Address of Operator		10. Pool name or Wildcat
	5) 552-7802	
4. Well Location		
Unit Letter_B_:910feet from theNorth		<del></del>
Section 26 Township 22S Range 27E	NMPM	County Eddy
11. Elevation (Show whether DR, 3086'	RKB, RI, GR, etc.)	<b>维华的新国际资本的</b> 基本
Pit or Below-grade Tank Application □ or Closure □	-	
Pit typeDepth to GroundwaterDistance from nearest fresh w	ater well Dista	nce from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volume	bbls; Con	struction Material
12. Check Appropriate Box to Indicate N	ature of Notice, F	Report or Other Data
NOTICE OF INTENTION TO:	SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK   PLUG AND ABANDON	REMEDIAL WORK	
TEMPORARILY ABANDON	COMMENCE DRIL	<u>=</u>
PULL OR ALTER CASING   MULTIPLE COMPL	CASING/CEMENT	JOB
OTHER:		OMPLETION 🛛
13. Describe proposed or completed operations. (Clearly state all p		
of starting any proposed work). SEE RULE 1103. For Multipl or recompletion.	le Completions: Atta	ach wellbore diagram of proposed completi
•		
05/30/05 MIRU. TIH drill dv tool @ 8516'. Drill out tool, tst csg to 3000# - ok. PBTD	_	RECEIVED
06/04/05 TH w/tbg, sd & spot 15 bbls of 2% KCL w/10% menthanol. Set pkr. Peri fm (		373'- 11882'.
06/04/05 TIH w/tbg, sd & spot 15 bbls of 2% KCL w/10% menthanol. Set pkr. Perf fm (06/07/05 Rls pkr, TiH set pkr @ 11,755'.	<u>@</u> 11,826'-11, 832'; 11,8	. 🔾
• •	<u>@</u> 11,826'-11, 832'; 11,8	373'- 11882'.
06/07/05 Rls pkr, TiH set pkr @ 11,755'. 06/09/05 Acidize Morrow fm 11,826'-11,882' w/2000 gals of 7.5% HCL & 60 7/8" ball s 06/15/05 Unseat pkr, POOH w/DHA & tbg. CIBP @ 11,775'; 35' of cmt on CIBP. 06/16/05 Perf Strawn fm 10,544'-10,552'; (6SPF) 48 holes. Set pkr @ 10,449'.	@ 11,826'-11, 832'; 11,8 sealers. Swab.	SEP - 8 2005 COD-ARTESIA
06/07/05 Rls pkr, TiH set pkr @ 11,755'. 06/09/05 Acidize Morrow fm 11,826'-11,882' w/2000 gals of 7.5% HCL & 60 7/8" ball s 06/15/05 Unseat pkr, POOH w/DHA & tbg. CIBP @ 11,775'; 35' of cmt on CIBP. 06/16/05 Perf Strawn fm 10,544'-10,552'; (6SPF) 48 holes. Set pkr @ 10,449'. 06/17/05 PBTD/CIBP w/37' cmt @ 11,755'. Swab. CIBP @ 11,755'. Dmp'd 37' cmt o 06/21/05 Acidize Strawn fm 10,544'-10,552' w/2000 gals of 15% HCL w/35 ball sealers.	@ 11,826'-11, 832'; 11,8 sealers. Swab. n CIBP. PBTD @ 11,378	SEP - 8 2005 COD-ARTESIA
06/07/05 Rls pkr, TiH set pkr @ 11,755'. 06/09/05 Acidize Morrow fm 11,826'-11,882' w/2000 gals of 7.5% HCL & 60 7/8" ball s 06/15/05 Unseat pkr, POOH w/DHA & tbg. CIBP @ 11,775'; 35' of cmt on CIBP. 06/16/05 Perf Strawn fm 10,544'-10,552'; (6SPF) 48 holes. Set pkr @ 10,449'. 06/17/05 PBTD/CIBP w/37' cmt @ 11,755'. Swab. CIBP @ 11,755'. Dmp'd 37' cmt o 06/21/05 Acidize Strawn fm 10,544'-10,552' w/2000 gals of 15% HCL w/35 ball sealers. 06/27/05 Perf Strawn @ 10,584'-10,590'; (6SF) 36 holes.	@ 11,826'-11, 832'; 11,8 sealers. Swab. n CIBP. PBTD @ 11,378 Swab.	SEP - 8 2005 COD-ARTESIA 8'.
06/07/05 Rls pkr, TiH set pkr @ 11,755'. 06/09/05 Acidize Morrow fm 11,826'-11,882' w/2000 gals of 7.5% HCL & 60 7/8" ball s 06/15/05 Unseat pkr, POOH w/DHA & tbg. CIBP @ 11,775'; 35' of cmt on CIBP. 06/16/05 Perf Strawn fm 10,544'-10,552'; (6SPF) 48 holes. Set pkr @ 10,449'. 06/17/05 PBTD/CIBP w/37' cmt @ 11,755'. Swab. CIBP @ 11,755'. Dmp'd 37' cmt o 06/21/05 Acidize Strawn fm 10,544'-10,552' w/2000 gals of 15% HCL w/35 ball sealers. 06/27/05 Perf Strawn @ 10,584'-10,590'; (6SF) 36 holes. 06/29/05 Rls ON/OFF tool. Latch onto pkr. POOH w/tbg & BHA. RIH & set CIBP at 1 CIBP, csg, BOP to 3000# - ok. Perf Wolfcamp fm @ 9740'-9758'; 9806'-9816'; 9846'-	@ 11,826'-11, 832'; 11,8 sealers. Swab. n CIBP. PBTD @ 11,378 Swab. 0,500 to isolate Strawn p	SEP - 8 2005  COD-ARTESIA  8'.  erfs. Dmp'd 35' cmt on CIBP. PBTD @ 10,465'. Tst
06/07/05 Rls pkr, TiH set pkr @ 11,755'. 06/09/05 Acidize Morrow fm 11,826'-11,882' w/2000 gals of 7.5% HCL & 60 7/8" ball s 06/15/05 Unseat pkr, POOH w/DHA & tbg. CIBP @ 11,775'; 35' of cmt on CIBP. 06/16/05 Perf Strawn fm 10,544'-10,552'; (6SPF) 48 holes. Set pkr @ 10,449'. 06/17/05 PBTD/CIBP w/37' cmt @ 11,755'. Swab. CIBP @ 11,755'. Dmp'd 37' cmt o 06/21/05 Acidize Strawn fm 10,544'-10,552' w/2000 gals of 15% HCL w/35 ball sealers. 06/27/05 Perf Strawn @ 10,584'-10,590'; (6SF) 36 holes. 06/29/05 Rls ON/OFF tool. Latch onto pkr. POOH w/tbg & BHA. RIH & set CIBP at 1	@ 11,826'-11, 832'; 11,8 sealers. Swab.  n CIBP. PBTD @ 11,378 Swab.  0,500 to isolate Strawn p. 9872'; (3SPF) 162 holes.	SEP - 8 2005  COD-ARTESIA  8'.  erfs. Dmp'd 35' cmt on CIBP. PBTD @ 10,465'. Tst
06/07/05 Rls pkr, TiH set pkr @ 11,755'. 06/09/05 Acidize Morrow fm 11,826'-11,882' w/2000 gals of 7.5% HCL & 60 7/8" ball s 06/15/05 Unseat pkr, POOH w/DHA & tbg. CIBP @ 11,775'; 35' of cmt on CIBP. 06/16/05 Perf Strawn fm 10,544'-10,552'; (6SPF) 48 holes. Set pkr @ 10,449'. 06/17/05 PBTD/CIBP w/37' cmt @ 11,755'. Swab. CIBP @ 11,755'. Dmp'd 37' cmt o 06/21/05 Acidize Strawn fm 10,544'-10,552' w/2000 gals of 15% HCL w/35 ball sealers. 06/27/05 Perf Strawn @ 10,584'-10,590'; (6SF) 36 holes. 06/29/05 Rls ON/OFF tool. Latch onto pkr. POOH w/tbg & BHA. RlH & set CIBP at 1 CIBP, csg, BOP to 3000# - ok. Perf Wolfcamp fm @ 9740'-9758'; 9806'-9816'; 9846'-Set pkr @ 9,682'. Tested csg to 2500# - ok. Swab. 07/01/05 Acidize Wolfcamp perfs 9,740'-9,872' w/5000 gals 15% HCL acid & 360 ball s 07/02/05 Rls pkr & TOOH.	@ 11,826'-11, 832'; 11,8 sealers. Swab.  n CIBP. PBTD @ 11,378 Swab.  0,500 to isolate Strawn pr 9872'; (3SPF) 162 holes. scalers. Swab.	SEP - 8 2005  COD-ARTESIA  8'.  erfs. Dmp'd 35' cmt on CIBP. PBTD @ 10,465'. Tsi No flow after perf. 3 <sup>rd</sup> perf run 9740'-9750', no flow
06/07/05 Rls pkr, TiH set pkr @ 11,755'. 06/09/05 Acidize Morrow fm 11,826'-11,882' w/2000 gals of 7.5% HCL & 60 7/8" ball s 06/15/05 Unseat pkr, POOH w/DHA & tbg. CIBP @ 11,775'; 35' of cmt on CIBP. 06/16/05 Perf Strawn fm 10,544'-10,552'; (6SPF) 48 holes. Set pkr @ 10,449'. 06/17/05 PBTD/CIBP w/37' cmt @ 11,755'. Swab. CIBP @ 11,755'. Dmp'd 37' cmt o 06/21/05 Acidize Strawn fm 10,544'-10,552' w/2000 gals of 15% HCL w/35 ball sealers. 06/27/05 Perf Strawn @ 10,584'-10,590'; (6SF) 36 holes. 06/29/05 Rls ON/OFF tool. Latch onto pkr. POOH w/tbg & BHA. RIH & set CIBP at 1 CIBP, csg, BOP to 3000# - ok. Perf Wolfcamp fm @ 9740'-9758'; 9806'-9816'; 9846'-Set pkr @ 9,682'. Tested csg to 2500# - ok. Swab. 07/01/05 Acidize Wolfcamp perfs 9,740'-9,872' w/5000 gals 15% HCL acid & 360 ball s 07/02/05 Rls pkr & TOOH. 07/04/05 Began fracturing treatment to Wolfcamp fm @ 9,740'-9,872'. Fracture treatments come out, 26.6K# in form. Flow back, tag up on sn fill, w/o. Swab.	@ 11,826'-11, 832'; 11,8 sealers. Swab.  n CIBP. PBTD @ 11,378 Swab.  0,500 to isolate Strawn pp 9872'; (3SPF) 162 holes. scalers. Swab.  nt w/43,016 gal Spectra S	SEP - 8 2005  COD-ARTESIA  8'.  erfs. Dmp'd 35' cmt on CIBP. PBTD @ 10,465'. Tst No flow after perf. 3 <sup>rd</sup> perf run 9740'-9750', no flow  star cross linked gel & 51,267# 16/30 SB Excel Sn.
06/07/05 Rls pkr, TiH set pkr @ 11,755'. 06/09/05 Acidize Morrow fm 11,826'-11,882' w/2000 gals of 7.5% HCL & 60 7/8" ball s 06/15/05 Unseat pkr, POOH w/DHA & tbg. CIBP @ 11,775'; 35' of cmt on CIBP. 06/16/05 Perf Strawn fm 10,544'-10,552'; (6SPF) 48 holes. Set pkr @ 10,449'. 06/17/05 PBTD/CIBP w/37' cmt @ 11,755'. Swab. CIBP @ 11,755'. Dmp'd 37' cmt o 06/21/05 Acidize Strawn fm 10,544'-10,552' w/2000 gals of 15% HCL w/35 ball sealers. 06/27/05 Perf Strawn @ 10,584'-10,590'; (6SF) 36 holes. 06/29/05 Rls ON/OFF tool. Latch onto pkr. POOH w/tbg & BHA. RlH & set CIBP at 1 CIBP, csg, BOP to 3000# - ok. Perf Wolfcamp fm @ 9740'-9758'; 9806'-9816'; 9846'-Set pkr @ 9,682'. Tested csg to 2500# - ok. Swab. 07/01/05 Acidize Wolfcamp perfs 9,740'-9,872' w/5000 gals 15% HCL acid & 360 ball s 07/02/05 Rls pkr & TOOH. 07/04/05 Began fracturing treatment to Wolfcamp fm @ 9,740'-9,872'. Fracture treatment Screen out, 26.6K# in form. Flow back, tag up on sn fill, w/o. Swab. 07/08/05 TIH w/2 7/8" tbg, pmp out plug, 2 7/8" API seating nipple, 305 jts 2 7/8" L-80 to 10.5 time form.	@ 11,826'-11, 832'; 11,8 sealers. Swab.  n CIBP. PBTD @ 11,378 Swab.  0,500 to isolate Strawn pp 9872'; (3SPF) 162 holes. scalers. Swab.  nt w/43,016 gal Spectra S	SEP - 8 2005  COD-ARTESIA  8'.  erfs. Dmp'd 35' cmt on CIBP. PBTD @ 10,465'. Tst No flow after perf. 3 <sup>rd</sup> perf run 9740'-9750', no flow  star cross linked gel & 51,267# 16/30 SB Excel Sn.
06/07/05 Rls pkr, TiH set pkr @ 11,755'. 06/09/05 Acidize Morrow fm 11,826'-11,882' w/2000 gals of 7.5% HCL & 60 7/8" ball s 06/15/05 Unseat pkr, POOH w/DHA & tbg. CIBP @ 11,775'; 35' of cmt on CIBP. 06/16/05 Perf Strawn fm 10,544'-10,552'; (6SPF) 48 holes. Set pkr @ 10,449'. 06/17/05 PBTD/CIBP w/37' cmt @ 11,755'. Swab. CIBP @ 11,755'. Dmp'd 37' cmt o 06/21/05 Acidize Strawn fm 10,544'-10,552' w/2000 gals of 15% HCL w/35 ball sealers. 06/27/05 Perf Strawn @ 10,584'-10,590'; (6SF) 36 holes. 06/29/05 Rls ON/OFF tool. Latch onto pkr. POOH w/tbg & BHA. RlH & set CIBP at 1 CIBP, csg, BOP to 3000# - ok. Perf Wolfcamp fm @ 9740'-9758'; 9806'-9816'; 9846'-Set pkr @ 9,682'. Tested csg to 2500# - ok. Swab. 07/01/05 Acidize Wolfcamp perfs 9,740'-9,872' w/5000 gals 15% HCL acid & 360 ball s 07/02/05 Rls pkr & TOOH. 07/04/05 Began fracturing treatment to Wolfcamp fm @ 9,740'-9,872'. Fracture treatment Screen out, 26.6K# in form. Flow back, tag up on sn fill, w/o. Swab. 07/08/05 TIH w/2 7/8" tbg, pmp out plug, 2 7/8" API seating nipple, 305 jts 2 7/8" L-80 to 07/27/05 Turned well to sales.	@ 11,826'-11, 832'; 11,8 sealers. Swab.  n CIBP. PBTD @ 11,378    Swab.  0,500 to isolate Strawn pp 9872'; (3SPF) 162 holes. scalers. Swab.  nt w/43,016 gal Spectra S tbg. Bttm tbg assembly @	SEP - 8 2005  COD-ARTESIA  8'.  erfs. Dmp'd 35' cmt on CIBP. PBTD @ 10,465'. Tst  No flow after perf. 3 <sup>rd</sup> perf run 9740'-9750', no flow  star cross linked gel & 51,267# 16/30 SB Excel Sn.  2 9716'. Swab.
06/07/05 Rls pkr, TiH set pkr @ 11,755'. 06/09/05 Acidize Morrow fm 11,826'-11,882' w/2000 gals of 7.5% HCL & 60 7/8" ball s 06/15/05 Unseat pkr, POOH w/DHA & tbg. CIBP @ 11,775'; 35' of cmt on CIBP. 06/16/05 Perf Strawn fm 10,544'-10,552'; (6SPF) 48 holes. Set pkr @ 10,449'. 06/17/05 PBTD/CIBP w/37' cmt @ 11,755'. Swab. CIBP @ 11,755'. Dmp'd 37' cmt o 06/21/05 Acidize Strawn fm 10,544'-10,552' w/2000 gals of 15% HCL w/35 ball sealers. 06/27/05 Perf Strawn @ 10,584'-10,590'; (6SF) 36 holes. 06/29/05 Rls ON/OFF tool. Latch onto pkr. POOH w/tbg & BHA. RlH & set CIBP at 1 CIBP, csg, BOP to 3000# - ok. Perf Wolfcamp fm @ 9740'-9758'; 9806'-9816'; 9846'-Set pkr @ 9,682'. Tested csg to 2500# - ok. Swab. 07/01/05 Acidize Wolfcamp perfs 9,740'-9,872' w/5000 gals 15% HCL acid & 360 ball s 07/02/05 Rls pkr & TOOH. 07/04/05 Began fracturing treatment to Wolfcamp fm @ 9,740'-9,872'. Fracture treatment Screen out, 26.6K# in form. Flow back, tag up on sn fill, w/o. Swab. 07/08/05 TIH w/2 7/8" tbg, pmp out plug, 2 7/8" API seating nipple, 305 jts 2 7/8" L-80 to 10.5 time form.	@ 11,826'-11, 832'; 11,8 sealers. Swab.  n CIBP. PBTD @ 11,378    Swab.  0,500 to isolate Strawn pp 9872'; (3SPF) 162 holes. scalers. Swab.  nt w/43,016 gal Spectra S dbg. Bttm tbg assembly @ est of my knowledge	SEP - 8 2005  COD-AFITESIA  8'.  erfs. Dmp'd 35' cmt on CIBP. PBTD @ 10,465'. Tst No flow after perf. 3 <sup>rd</sup> perf run 9740'-9750', no flow star cross linked gel & 51,267# 16/30 SB Excel Sn.  2 9716'. Swab.
06/07/05 Rls pkr, TiH set pkr @ 11,755'. 06/09/05 Acidize Morrow fm 11,826'-11,882' w/2000 gals of 7.5% HCL & 60 7/8" ball s 06/15/05 Unseat pkr, POOH w/DHA & tbg. CIBP @ 11,775'; 35' of cmt on CIBP. 06/16/05 Perf Strawn fm 10,544'-10,552'; (6SPF) 48 holes. Set pkr @ 10,449'. 06/17/05 PBTD/CIBP w/37' cmt @ 11,755'. Swab. CIBP @ 11,755'. Dmp'd 37' cmt o 06/21/05 Acidize Strawn fm 10,544'-10,552' w/2000 gals of 15% HCL w/35 ball sealers. 06/27/05 Perf Strawn @ 10,584'-10,590'; (6SF) 36 holes. 06/29/05 Rls ON/OFF tool. Latch onto pkr. POOH w/tbg & BHA. RlH & set CIBP at 1 CIBP, csg, BOP to 3000# - ok. Perf Wolfcamp fm @ 9740'-9758'; 9806'-9816'; 9846'-Set pkr @ 9,682'. Tested csg to 2500# - ok. Swab. 07/01/05 Acidize Wolfcamp perfs 9,740'-9,872' w/5000 gals 15% HCL acid & 360 ball s 07/02/05 Rls pkr & TOOH. 07/04/05 Began fracturing treatment to Wolfcamp fm @ 9,740'-9,872'. Fracture treatment Screen out, 26.6K# in form. Flow back, tag up on sn fill, w/o. Swab. 07/08/05 TIH w/2 7/8" tbg, pmp out plug, 2 7/8" API seating nipple, 305 jts 2 7/8" L-80 to 07/27/05 Turned well to sales.  I hereby certify that the information above is true and complete to the begrade tank has been/will be constructed or closed according to NMOCD guidelines	@ 11,826'-11, 832'; 11,8 sealers. Swab.  n CIBP. PBTD @ 11,378    Swab.  0,500 to isolate Strawn pp 9872'; (3SPF) 162 holes. scalers. Swab.  nt w/43,016 gal Spectra S dbg. Bttm tbg assembly @ est of my knowledge	SEP - 8 2005  COD-ARTESIA  8'.  erfs. Dmp'd 35' cmt on CIBP. PBTD @ 10,465'. Tst  No flow after perf. 3 <sup>rd</sup> perf run 9740'-9750', no flow  star cross linked gel & 51,267# 16/30 SB Excel Sn.  9716'. Swab.
06/07/05 Rls pkr, TiH set pkr @ 11,755'. 06/09/05 Acidize Morrow fm 11,826'-11,882' w/2000 gals of 7.5% HCL & 60 7/8" ball s 06/15/05 Unseat pkr, POOH w/DHA & tbg. CIBP @ 11,775'; 35' of cmt on CIBP. 06/16/05 Perf Strawn fm 10,544'-10,552'; (6SPF) 48 holes. Set pkr @ 10,449'. 06/17/05 PBTD/CIBP w/37' cmt @ 11,755'. Swab. CIBP @ 11,755'. Dmp'd 37' cmt o 06/21/05 Acidize Strawn fm 10,544'-10,552' w/2000 gals of 15% HCL w/35 ball sealers. 06/27/05 Perf Strawn @ 10,584'-10,552' w/2000 gals of 15% HCL w/35 ball sealers. 06/27/05 Rls ON/OFF tool. Latch onto pkr. POOH w/tbg & BHA. RlH & set CIBP at 1 CIBP, csg, BOP to 3000# - ok. Perf Wolfcamp fm @ 9740'-9758'; 9806'-9816'; 9846'-Set pkr @ 9,682'. Tested csg to 2500# - ok. Swab. 07/01/05 Acidize Wolfcamp perfs 9,740'-9,872' w/5000 gals 15% HCL acid & 360 ball s 07/02/05 Rls pkr & TOOH. 07/04/05 Began fracturing treatment to Wolfcamp fm @ 9,740'-9,872'. Fracture treatment Screen out, 26.6K# in form. Flow back, tag up on sn fill, w/o. Swab. 07/08/05 TIH w/2 7/8" tbg, pmp out plug, 2 7/8" API seating nipple, 305 jts 2 7/8" L-80 to 07/27/05 Turned well to sales.  I hereby certify that the infotration above is true and complete to the begrade tank has been/will be constructed or closed according to NMOCD guidelines are structed or closed according to NMOCD guidelines are structed or closed according to NMOCD guidelines are structed or posed according to NMOCD guidelines.  TITLE S	@ 11,826'-11, 832'; 11,8 sealers. Swab.  n CIBP. PBTD @ 11,378 Swab.  0,500 to isolate Strawn pr 9872'; (3SPF) 162 holes. scalers. Swab.  nt w/43,016 gal Spectra S dbg. Bttm tbg assembly @ est of my knowledge ], a general permit  of Genior Engineering T	SEP - 8 2005  COD-ARTESIA  8'.  erfs. Dmp'd 35' cmt on CIBP. PBTD @ 10,465'. Tst  No flow after perf. 3rd perf run 9740'-9750', no flow  star cross linked gel & 51,267# 16/30 SB Excel Sn.  2 9716'. Swab.  and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan  Cechnician DATE 8/30/05
06/07/05 Rls pkr, TiH set pkr @ 11,755'. 06/09/05 Acidize Morrow fm 11,826'-11,882' w/2000 gals of 7.5% HCL & 60 7/8" ball s 06/15/05 Unseat pkr, POOH w/DHA & tbg. CIBP @ 11,775'; 35' of cmt on CIBP. 06/16/05 Perf Strawn fm 10,544'-10,552'; (6SPF) 48 holes. Set pkr @ 10,449'. 06/17/05 PBTD/CIBP w/37' cmt @ 11,755'. Swab. CIBP @ 11,755'. Dmp'd 37' cmt o 06/21/05 Acidize Strawn fm 10,544'-10,552' w/2000 gals of 15% HCL w/35 ball sealers. 06/27/05 Perf Strawn @ 10,584'-10,552' w/2000 gals of 15% HCL w/35 ball sealers. 06/29/05 Rls ON/OFF tool. Latch onto pkr. POOH w/tbg & BHA. RlH & set CIBP at 1 CIBP, csg, BOP to 3000# - ok. Perf Wolfcamp fm @ 9740'-9758'; 9806'-9816'; 9846'-Set pkr @ 9,682'. Tested csg to 2500# - ok. Swab. 07/01/05 Acidize Wolfcamp perfs 9,740'-9,872' w/5000 gals 15% HCL acid & 360 ball s 07/02/05 Rls pkr & TOOH. 07/04/05 Began fracturing treatment to Wolfcamp fm @ 9,740'-9,872'. Fracture treatment Screen out, 26.6K# in form. Flow back, tag up on sn fill, w/o. Swab. 07/08/05 TIH w/2 7/8" tbg, pmp out plug, 2 7/8" API seating nipple, 305 jts 2 7/8" L-80 to 07/27/05 Turned well to sales.  I hereby certify that the infotmation above is true and complete to the begrade tank has been/will be constructed or closed according to NMOCD guidelines [SIGNATURE]  TITLE S  Type or print name Stephanie A. Ysasaga E-mail address: Stephanie A. Ysasaga E-mail address: Stephanie A. Ysasaga	@ 11,826'-11, 832'; 11,8 sealers. Swab.  n CIBP. PBTD @ 11,378 Swab.  0,500 to isolate Strawn pr 9872'; (3SPF) 162 holes. scalers. Swab.  nt w/43,016 gal Spectra S dbg. Bttm tbg assembly @ est of my knowledge ], a general permit  of Genior Engineering T	SEP - 8 2005  COD-ARTESIA  8'.  erfs. Dmp'd 35' cmt on CIBP. PBTD @ 10,465'. Tst  No flow after perf. 3rd perf run 9740'-9750', no flow  star cross linked gel & 51,267# 16/30 SB Excel Sn.  2 9716'. Swab.  and belief. I further certify that any pit or belover an (attached) alternative OCD-approved plan  Cechnician DATE 8/30/05  vn.com Telephone No. (405) 552-7802
06/07/05 Rls pkr, TiH set pkr @ 11,755'. 06/09/05 Acidize Morrow fm 11,826'-11,882' w/2000 gals of 7.5% HCL & 60 7/8" ball s 06/15/05 Unseat pkr, POOH w/DHA & tbg. CIBP @ 11,775'; 35' of cmt on CIBP. 06/16/05 Perf Strawn fm 10,544'-10,552'; (6SPF) 48 holes. Set pkr @ 10,449'. 06/17/05 PBTD/CIBP w/37' cmt @ 11,755'. Swab. CIBP @ 11,755'. Dmp'd 37' cmt o 06/21/05 Acidize Strawn fm 10,544'-10,552' w/2000 gals of 15% HCL w/35 ball sealers. 06/27/05 Perf Strawn @ 10,584'-10,590'; (6SF) 36 holes. 06/27/05 Rls ON/OFF tool. Latch onto pkr. POOH w/tbg & BHA. RIH & set CIBP at 1 CIBP, csg, BOP to 3000# - ok. Perf Wolfcamp fm @ 9740'-9758'; 9806'-9816'; 9846'-Set pkr @ 9,682'. Tested csg to 2500# - ok. Swab. 07/01/05 Acidize Wolfcamp perfs 9,740'-9,872' w/5000 gals 15% HCL acid & 360 ball s 07/02/05 Rls pkr & TOOH. 07/04/05 Began fracturing treatment to Wolfcamp fm @ 9,740'-9,872'. Fracture treatment Screen out, 26.6K# in form. Flow back, tag up on sn fill, w/o. Swab. 07/08/05 TIH w/2 7/8" tbg, pmp out plug, 2 7/8" API seating nipple, 305 jts 2 7/8" L-80 to 07/27/05 Turned well to sales.  I hereby certify that the infotribation above is true and complete to the begrade tank has been/will be constructed or closed according to NMOCD guidelines [SIGNATURE]  TITLE S  Type or print name Stephanie A. Ysasaga E-mail address: Ste	@ 11,826'-11, 832'; 11,8 sealers. Swab.  n CIBP. PBTD @ 11,378 Swab.  0,500 to isolate Strawn pr 9872'; (3SPF) 162 holes. scalers. Swab.  nt w/43,016 gal Spectra S dbg. Bttm tbg assembly @ est of my knowledge ], a general permit  of Genior Engineering T	SEP - 8 2005  COD-ARTESIA  8'.  erfs. Dmp'd 35' cmt on CIBP. PBTD @ 10,465'. Tst  No flow after perf. 3rd perf run 9740'-9750', no flow  star cross linked gel & 51,267# 16/30 SB Excel Sn.  2 9716'. Swab.  and belief. I further certify that any pit or belover an (attached) alternative OCD-approved plan  Cechnician DATE 8/30/05