DATE

APPROVED BY:

Conditions of Approval (if any):

See Attached

AMICHE
--------

LEASE NAME	B B State Com	
WELL#	#1	
API#	30-015-32070	
COUNTY	Eddy	

WELL	RORE	INFO

0

17 1/2" Hole 13 3/8" 48# @ 345' w/500 sx to surf

1010

12 1/4" Hole 9 5/8" 36# @ 1712' w/ 590 sx to surf

2020

3030

4040

5050

6060


7070

8080

9090

10100

8 3/4" Hole 5 1/2" 17# @ 10,100' w/ 2450 sx to surf DVT @ 7817'



Morrow Perfs @ 9601'-9880'

(6/05) CIBP @ 9786'



 LEASE NAME
 B B State Com

 WELL #
 #1

 API #
 30-015-32070

 COUNTY
 Eddy

### PROPOSED PROCEDURE

**WELL BORE INFO.** 0 17 1/2" Hole 13 3/8" 48# @ 345' w/500 sx to surf 1010 12 1/4" Hole 9 5/8" 36# @ 1712' w/ 590 sx to surf 2020 3030 4040 5050 6060 7070 DVT @ 7817' 8080 9090

8 3/4" Hole

5 1/2" 17# @ 10,100"

w/ 2450 sx to surf

10100

<sup>2</sup>BTD @ 10,054

TD @ 10,100°

8 PUH & spot 40 sx Class "C" cmt from 395' to surf. (Shoe & Water Board)

7. PUH & spot 25 sx Class "C" cmt from 1762'-1512' WOC/TAG (Shoe)

6. PUH & spot 25 sx Class "C" cmt from 3374'-3124' (Yeso & Glorieta)

PUH & spot 25 sx Class "C" cmt from 5164'-4914'
 (Abo)

 PUH & spot 25 sx Class "C" cmt from 6609'-6359' (Wolfcamp)

 PUH & spot 30 sx Class "C" cmt from 7912'-7612' (Cisco & DVT)

2. PUH & spot 25 sx Class "H" cmt from 8759'-8509' (Strawn)

 MIRU P&A unit. RIH w/WL & guage ring & set CIBP @ 9550'. POOH w/WL. RIH w/TBG & CIRC w/MLF & spot 40 sx Class "H" cmt (CIBP & Atoka & Morrow perfs)

# NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

## CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: Apache
Well Name & Number: BB State Com #1
API#: 30-015-32070

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 1 year of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.

11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 8-12-2014

APPROVED BY: Reside

### GUIDELINES FOR PLUGGING AND ABANDONMENT

#### DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
  - o Fusselman
  - o Devonian
  - o Morrow
  - o Wolfcamp
  - o Bone Spring
  - o Delaware
  - Any Salt Section (Plug at top and bottom)
  - o Abo
  - o Glorieta
  - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).