Office Office of Companies and Natural Resources  Different Dr., Hobbs, 70d 8240  Dr.,	3
Digital Internal Art. Astron. NM 87410   Digital Internal Intern	<u>*</u>
South And Anna, America, America, Mar 1970   Samta Fe, NM 87505   Samt	1
120 South St. Francis Dr.   State Fig.   F	-
Santa Pr. Sant	_} .
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS PROHE FOR PREPORDAL TO DEMPENOR FULL BACK TO A DIFFERENT RESERVOR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROFOSALS)  1. Type of Well: Oil Well Seas Well Cother  2. Name of Operator Merit Energy Company 3. Address of Operator Werlt Energy Company 4. Well Location  Unit Letter 13.727 Noel Road, Stephology Stephology 10. Elevation (Show whether Dr. RES. RT. GR. etc.)  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUS AND ABANDON COMPLETION  TEMPORARILY ABANDON CHANGE PLANS COMPLETION  COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  12. Describe proposed or completed operations. (Clearly state all perfinent details, and give pertinent dates, including estimated date or starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.  1. Move in & R/U pulling unit. 2. N/D wellhead & N/U BOP's. 3. POOH with tubing and pump. 4. RIH with bit and scraper and clean out well to PBTD @ 4421', POOH. 5. Set RBP @ 3270' and test casing to 4000s. 6. R/U electric line and perforate Queen formation from 2857' - 2871' & 2896' - 2903' 7. Move in & R/U By Pumping Services and frac well as per Bj treatment proposal. 8. R/D Bj Service and clean out to RBP. 9. R/U & swab test Queen formation, establish production rate. 10. RIH, pull RBP, & R/H with pump & tubing. 11. R/D pulling unit and put well on production.  1 Telephone No. 9. 77 6.286	7
DO NOT USE THE FORM FOR PROPOSALS TO DEBLOR TO DEBLOR TO DEBLO ACT TO A DEPTENDIN RESERVOR. USE "APPLICATION FOR PRINTS (FORM C-101) FOR SUCH  PROPOSALS)  1. Type of Well:  Oil Well S Gas Well Other  Nor if Forg Company  8. Well No. 85  3. Address of Operator  Unit Letter	
2. Name of Operator Merit Energy Company 3. Address of Operator 13727 Noel Road 5+2500 3. Pool name or Wildest Grayland 5-2500 3. Pool name or Wildest Grayland 5-2500 4. Well Location  Unit Letter 2. 2014 feet from the South line and 2021 feet from the West line Section 3. Township 175 Range 315 NMPM County Edd y  10. Elevation (Show whether DR RKB, RT, GR, etc.)  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDON   CASING TEST AND COMMENT OF SET	
3. Address of Operator 13727 Noel Road 5+2500 9. Pool name or Wildcat Status and Status	┧.
3. Address of Operator    3 727   No e   Road   Stepheno   9. Pool name or Wildeat Graybon   SR-DN-28-5.   Well Location   Unit Letter   2014 feet from the Socth   time and 2021 feet from the West   time	
Unit Letter    Section   County   Feet from the   South   time and   262   foot from the   West   time	^
Township   7.5 Range 3   E NMPM    10. Elevation (Show whether DR RKB, RT, GR, etc.)  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE   CASING TEST AND   CEMENT JOB    OTHER: Perfere Queen   Change Plans   CHANGE PLANS   PLUG AND ABANDONMENT    OTHER: Perfere Queen   Completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.  1. Move in & R/U pulling unit.  2. N/D wellhead & N/U BOP's.  3. POOH with tubing and pump.  4. RIH with bit and scraper and clean out well to PBTD @ 4421', POOH.  5. Set RBP @ 3270' and test casing to 4000\$.  6. R/U electric line and perforate Queen formation from 2857' - 2871' & 2896' - 2903'  7. Move in & R/U BJ Pumping Services and frac well as per BJ treatment proposal.  8. R/D BJ Service and clean out to RBP.  9. R/U & swab test Queen formation, establish production rate.  10. RIH, pull RBP, & RIH with pump & tubing.  11. R/D pulling unit and put well on production.  11. Mereby certify that the information above is true and complete to the best of my knowledge and better.  SIGNATURE	7
Township   7.5 Range 3   E NMPM    10. Elevation (Show whether DR RKB, RT, GR, etc.)  11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE   CASING TEST AND   CEMENT JOB    OTHER: Perf   Frac Queen   OTHER:   DATE    2. Describe proposed or completed operations. (Clearly state all pertnent details, and give pertinent dates, including estimated date or starting any proposed or completion or recompletion.  1. Move in & R/U pulling unit.  2. N/D wellhead & N/U BOP's.  3. POOH with tubing and pump.  4. RIH with bit and scraper and clean out well to PBTD @ 4421', POOH.  5. Set RBP @ 3270' and test casing to 4000#.  6. R/U electric line and perforate Queen formation from 2857' - 2871' & 2896' - 2903'  7. Move in & R/U BJ Pumping Services and frac well as per BJ treatment proposal.  8. R/D BJ Service and clean out to RBP.  9. R/U & swab test Queen formation, establish production rate.  10. RIH, pull RBP, & RIH with pump & tubing.  11. R/D pulling unit and put well on production.  hereby certify that the information above is true and complete to the best of my knowledge and benefit.  SIGNATURE   Market Language   Market Lang	.
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE   CASING TEST AND   CASING TEST AND    COMPLETION   CASING TEST AND   CASING TEST AND    COMPLETION   CASING TEST AND   COMMENT JOB    OTHER: Perf   Free Queen   Casing test and give pertinent dates, including estimated date of starting any proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed or completion.  1. Move in & R/U pulling unit.  2. N/D wellhead & N/U BOP's.  3. POOH with tubing and pump.  4. RIH with bit and scraper and clean out well to PBTD @ 4421', POOH.  5. Set RBP @ 3270' and test casing to 4000s.  6. R/U electric line and perforate Queen formation from 2857' - 2871' & 2896' - 2903'.  7. Move in & R/U BJ Fumping Services and frac well as per BJ treatment proposal.  8. R/D BJ Service and clean out to RBP.  9. R/U & swab test Queen formation, establish production rate.  10. RIH, pull RBP, & RIH with pump & tubing.  11. R/D pulling unit and put well on production.  hereby certify that the information above is true and complete to the best of my knowledge and bauer.  SIGNATURE   Hat first all   First	
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE   CASING TEST AND   CASING TEST AND    COMPLETION   CASING TEST AND   CASING TEST AND    COMPLETION   CASING TEST AND   COMMENT JOB    OTHER: Perf   Free Queen   Casing test and give pertinent dates, including estimated date of starting any proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed or completion.  1. Move in & R/U pulling unit.  2. N/D wellhead & N/U BOP's.  3. POOH with tubing and pump.  4. RIH with bit and scraper and clean out well to PBTD @ 4421', POOH.  5. Set RBP @ 3270' and test casing to 4000s.  6. R/U electric line and perforate Queen formation from 2857' - 2871' & 2896' - 2903'.  7. Move in & R/U BJ Fumping Services and frac well as per BJ treatment proposal.  8. R/D BJ Service and clean out to RBP.  9. R/U & swab test Queen formation, establish production rate.  10. RIH, pull RBP, & RIH with pump & tubing.  11. R/D pulling unit and put well on production.  hereby certify that the information above is true and complete to the best of my knowledge and bauer.  SIGNATURE   Hat first all   First	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE   CASING TEST AND   CEMENT JOB    OTHER: Perfera Gyzen   SX OTHER:   CASING TEST AND   CEMENT JOB    OTHER: Perfera Gyzen   SX OTHER:   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    CASING TEST AND   CEMENT JOB    OTHER:   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    CASING TEST AND   CEMENT JOB    OTHER:   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    CASING TEST AND   CEMENT JOB   CEMENT JOB    OTHER:   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    CASING TEST AND   CASING TEST AND   CEMENT JOB    CASING TEST AND   CASING TEST AND   CASING TEST AND   CEMENT JOB    CASING TEST AND   CASING TEST AND   CASING TEST AND   CEMENT JOB    CASING TEST AND   CASING TEST AND   CASING TEST AND   CEMENT JOB    CASING TEST AND   CASING TEST AND   CASING TEST AND   CASING TEST AND   CEMENT JOB    CASING TEST AND   CA	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE   CASING TEST AND   CEMENT JOB    OTHER: Perfera Gyzen   SX OTHER:   CASING TEST AND   CEMENT JOB    OTHER: Perfera Gyzen   SX OTHER:   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    CASING TEST AND   CEMENT JOB    OTHER:   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    CASING TEST AND   CEMENT JOB    OTHER:   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    CASING TEST AND   CEMENT JOB   CEMENT JOB    OTHER:   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    CASING TEST AND   CASING TEST AND   CEMENT JOB    CASING TEST AND   CASING TEST AND   CASING TEST AND   CEMENT JOB    CASING TEST AND   CASING TEST AND   CASING TEST AND   CEMENT JOB    CASING TEST AND   CASING TEST AND   CASING TEST AND   CEMENT JOB    CASING TEST AND   CASING TEST AND   CASING TEST AND   CASING TEST AND   CEMENT JOB    CASING TEST AND   CA	_ '
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING    TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   PLUG AND ABANDONMENT    PULL OR ALTER CASING   MULTIPLE   CASING TEST AND   CEMENT JOB    OTHER: Perf   Frac Cycen   Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date or starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.  1. Move in & R/U pulling unit. 2. N/D wellhead & N/U BOP's. 3. POOH with tubing and pump. 4. RIH with bit and scraper and clean out well to PBTD @ 4421', POOH. 5. Set RBP @ 3270' and test casing to 4000\$. 6. R/U electric line and perforate Queen formation from 2857' - 2871' & 2896' - 2903'. 7. Move in & R/U BJ Pumping Services and frac well as per BJ treatment proposal. 8. R/D BJ Service and clean out to RBP. 9. R/U & swab test Queen formation, establish production rate. 10. RIH, pull RBP, & RIH with pump & tubing. 11. R/D pulling unit and put well on production.  hereby certify that the information above is true and complete to the best of my knowledge and benefit.  IGNATURE	
ABANDONMENT  ABANDONMENT  CASING TEST AND  CEMENT JOB  OTHER: Perffrac Gucen  Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.  1. Move in & R/U pulling unit. 2. N/D wellhead & N/U BOP's. 3. POOH with tubing and pump. 4. RIH with bit and scraper and clean out well to PBTD @ 4421', POOH. 5. Set RBP @ 3270' and test casing to 4009. 6. R/U electric line and perforate Queen formation from 2857' - 2871' & 2896' - 2903'  7. Move in & R/U BJ Pumping Services and frac well as per BJ treatment proposal. 8. R/D BJ Service and clean out to RBP. 9. R/U & swab test Queen formation, establish production rate. 10. RIH, pull RBP, & RIH with pump & tubing. 11. R/D pulling unit and put well on production.  hereby certify that the information above is true and complete to the best of my knowledge and bener.  IGNATURE  TITLE Regardator Market DATE 5-27-0.  Telephone No. 972 628'	]
CASING TEST AND CEMENT JOB  OTHER: Perf / Frac Queen  OTHER: Perf / Frac Queen  OTHER: OTHER:  OTHER:	l
2. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.  1. Move in & R/U pulling unit. 2. N/D wellhead & N/U BOP's. 3. POOH with tubing and pump. 4. RIH with bit and scraper and clean out well to PBTD @ 4421', POOH. 5. Set RBP @ 3270' and test casing to 4000\$. 6. R/U electric line and perforate Queen formation from 2857' - 2871' & 2896' - 2903' 7. Move in & R/U BJ Pumping Services and frac well as per BJ treatment proposal. 8. R/D BJ Service and clean out to RBP. 9. R/U & swab test Queen formation, establish production rate. 10. RIH, pull RBP, & RIH with pump & tubing. 11. R/D pulling unit and put well on production.  Thereby certify that the information above is true and complete to the best of my knowledge and bener.  SIGNATURE  TITLE Regal a to reflection to Telephone No. 972628' Telephone No. 972628'	
2. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.  1. Move in & R/U pulling unit. 2. N/D wellhead & N/U BOP's. 3. POOH with tubing and pump. 4. RIH with bit and scraper and clean out well to PBTD @ 4421', POOH. 5. Set RBP @ 3270' and test casing to 4000#. 6. R/U electric line and perforate Queen formation from 2857' - 2871' & 2896' - 2903'. 7. Move in & R/U BJ Pumping Services and frac well as per BJ treatment proposal. 8. R/D BJ Service and clean out to RBP. 9. R/U & swab test Queen formation, establish production rate. 10. RIH, pull RBP, & RIH with pump & tubing. 11. R/D pulling unit and put well on production.  hereby certify that the information above is true and complete to the best of my knowledge and better.  IGNATURE    Regarda to reflect the part of the complete to the best of my knowledge and better.    RIH with bit and scraper and complete to the best of my knowledge and better.   RIH with pump & tubing   TITLE   Regarda to reflect to PATE 5-27-0   Telephone No. 972628'	l
2. N/D wellhead & N/U BOP's.  3. POOH with tubing and pump.  4. RIH with bit and scraper and clean out well to PBTD @ 4421', POOH.  5. Set RBP @ 3270' and test casing to 4000\$.  6. R/U electric line and perforate Queen formation from 2857' - 2871' & 2896' - 2903'.  7. Move in & R/U BJ Pumping Services and frac well as per BJ treatment proposal.  8. R/D BJ Service and clean out to RBP.  9. R/U & swab test Queen formation, establish production rate.  10. RIH, pull RBP, & RIH with pump & tubing.  11. R/D pulling unit and put well on production.  Thereby certify that the information above is true and complete to the best of my knowledge and benef.  SIGNATURE  December 10. 1716 Pegglator Malest DATE 5-27-0.  Telephone No. 972628'  Telephone No. 972628'	<u>if</u>
2. N/D wellhead & N/U BOP's.  3. POOH with tubing and pump.  4. RIH with hit and scraper and clean out well to PBTD @ 4421', POOH.  5. Set RBP @ 3270' and test casing to 4000%.  6. R/U electric line and perforate Queen formation from 2857' - 2871' & 2896' - 2903'.  7. Move in & R/U BJ Pumping Services and frac well as per BJ treatment proposal.  8. R/D BJ Service and clean out to RBP.  9. R/U & swab test Queen formation, establish production rate.  10. RIH, pull RBP, & RIH with pump & tubing.  11. R/D pulling unit and put well on production.  hereby certify that the information above is true and complete to the best of my knowledge and benefit.  SIGNATURE  TITLE  Regalator Malest DATE 5-27-0  Telephone No. 972628'  Telephone No. 972628'	
4. RIH with bit and scraper and clean out well to PBTD @ 4421', POOH.  5. Set RBP @ 3270' and test casing to 4000#.  6. R/U electric line and perforate Queen formation from 2857' - 2871' & 2896' - 2903'.  7. Move in & R/U BJ Pumping Services and frac well as per BJ treatment proposal.  8. R/D BJ Service and clean out to RBP.  9. R/U & swab test Queen formation, establish production rate.  10. RIH, pull RBP, & RIH with pump & tubing.  11. R/D pulling unit and put well on production.  hereby certify that the information above is true and complete to the best of my knowledge and better.  IGNATURE  TITLE  Regalator Malest DATE 5-27-0  Telephone No. 972628'	
4. RIH with bit and scraper and clean out well to PBTD @ 4421', POOH.  5. Set RBP @ 3270' and test casing to 4000#.  6. R/U electric line and perforate Queen formation from 2857' - 2871' & 2896' - 2903'.  7. Move in & R/U BJ Pumping Services and frac well as per BJ treatment proposal.  8. R/D BJ Service and clean out to RBP.  9. R/U & swab test Queen formation, establish production rate.  10. RIH, pull RBP, & RIH with pump & tubing.  11. R/D pulling unit and put well on production.  hereby certify that the information above is true and complete to the best of my knowledge and better.  IGNATURE  TITLE  Regalator Malest DATE 5-27-0  Telephone No. 972628'	
5. Set RBP @ 3270' and test casing to 4000#.  6. R/U electric line and perforate Queen formation from 2857' - 2871' & 2896' - 2903'  7. Move in & R/U BJ Pumping Services and frac well as per BJ treatment proposal.  8. R/D BJ Service and clean out to RBP.  9. R/U & swab test Queen formation, establish production rate.  10. RIH, pull RBP, & RIH with pump & tubing.  11. R/D pulling unit and put well on production.  hereby certify that the information above is true and complete to the best of my knowledge and bener.  IGNATURE  TITLE  Regalator fladest DATE  5-27-0  Toleobone No. 972628'	
6. R/U electric line and perforate Queen formation from 2857' - 2871' & 2896' - 2903' 7. Move in & R/U BJ Pumping Services and frac well as per BJ treatment proposal. 8. R/D BJ Service and clean out to RBP. 9. R/U & swab test Queen formation, establish production rate. 10. RIH, pull RBP, & RIH with pump & tubing. 11. R/D pulling unit and put well on production.  hereby certify that the information above is true and complete to the best of my knowledge and better.  IGNATURE  TITLE  Regalator fladest DATE 5-27-0  Toleobone No. 972628'	
8. R/D BJ Service and clean out to RBP.  9. R/U & swab test Queen formation, establish production rate.  10. RIH, pull RBP, & RIH with pump & tubing.  11. R/D pulling unit and put well on production.  hereby certify that the information above is true and complete to the best of my knowledge and bener.  SIGNATURE  TITLE  Regalator fladest DATE 5-27-0  Toleobone No. 972628	
8. ND B) Service and clean out to RBP.  9. R/U & swab test Queen formation, establish production rate.  10. RIH, pull RBP, & RIH with pump & tubing.  11. R/D pulling unit and put well on production.  hereby certify that the information above is true and complete to the best of my knowledge and bener.  SIGNATURE  Super or print name  Perelogy Hat field  Telephone No. 972628	
9. R/U & swab test Queen formation, establish production rate.  10. RIH, pull RBP, & RIH with pump & tubing.  11. R/D pulling unit and put well on production.  hereby certify that the information above is true and complete to the best of my knowledge and bener.  SIGNATURE  Superal Hatfield  TITLE Regalator fladest DATE 5-27-0  Toleobone No. 972628	
10. RIH, pull RBP, & RIH with pump & tubing.  11. ND pulling unit and put well on production.  hereby certify that the information above is true and complete to the best of my knowledge and better.  SIGNATURE  Stype or print name  Developed Hatfield  Telephone No. 972628	
11. R/D pulling unit and put well on production.  hereby certify that the information above is true and complete to the best of my knowledge and better.  SIGNATURE  Sure Later Hat field  Toleobone No. 972628	
hereby certify that the information above is true and complete to the best of my knowledge and better.  SIGNATURE  Sure Logical TITLE Regulator Stralust DATE 5-27-0  Type or print name  Bever log Hatfield  Telephone No. 972628	
SIGNATURE Buel Hatfield HTLE Regulator Gralyst DATE 5-27-0 Type or print manne Beverly Hatfield Telephone No. 972628	—
Type or print name Beverly Hatfield Telephone No. 972628	3
This space for State use)	
√- 11 λ	<u>~~</u> ~
APPPROVED BY DATE TITLE WINTER SIGNATURE	Z7 🥻

State of New Mexico
Energy, Minerals & Natural Resources Department
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe. NM 87505

Form C-102
Revised August 15, 2000
Submit to Appropriate District Office
State Lease - 4 Copies
Fee Lease - 3 Copies

☐ AMENDED REPORT				20, 11						
		ATION PLA Pool Na	LL LOCATION AND ACREAGE DEDICATION IN PROCESSION OF THE PROPERTY OF THE PROPER				API Number			
Well Number	<del></del>	Property Name					300/528387			
Elevation			H.E. West "B"  Operator Name  Terit Energy Company					020058   OGRID No.		
396/			ompany		<u> + En</u>	Pleri			01495	
Ram/West line County	Ran	Feet from the	Location North/South line	Feet from the	Lot Idn	Range	Township	Section	UL or let se.	
West Eddy	We	2621	South	2614	<u></u>	315	175	3	K	
East/West line County	) B	n Surface Feet from the	F Different From	e Location I	ttom Hol	II Bo	Township	Santan	UL or lot no.	
ABBI West line County		1464 ILOUE AND	MOLENADOUS INTE	Nedt Claser ras		samp.	Township	24000	OL or lot 20,	
				rder No.	Code III O	Consolidation	r India	Joint o	E Dedicated Acres	
ATOR CERTIFICATION that the tiplomation contained herein is true the base of my providedge and beller.  Hat final description of the light of the well location shown on this plas was in that the same is true and correct to the	ERATO THE HATO THE HA	17 OPF   herdry car and-complete   herdry car and-complete   herdry car   herdry car   Title   Duan   18 SUR'   herdry car   plotted from	EN APPROVED I	UNIT HAS BE	INDARD	NON-STA			16	
al of Professional Surveyor:	•	Date of Surv Signature an								

AP

Well: Field:

County:

State:

H.E. West "B" #85 Grayburg-Jackson

Grayburg-Ja Eddy

New Mexico

Location:


Elevation: GL API #:

S3-T17S-R31E GL - 3961' // KB 3975'

30-025-28387

Workover-Perforate & frac Queen formation

## Wellbore Information:



Spud: 3/10/1995


8-5/8" // 24.00# // J-55 // STC @ 643' w/ 300 sks Burst: 2950# // Collapse: 1370#

5-1/2" // 15.50# // J-55 @ 4469' w/ 965 sks Burst: 4810# // Collapse: 3120#

## Procedure:

- 1. Move in & R/U pulling unit.
- 2. N/D wellhead & N/U BOP's.
- 3. POOH with tubing and pump.
- 4. RIH with bit and scraper and clean out well to PBTD @ 4421', POOH.
- 5. Set RBP @ 3270' and test casing to 4000#.
- 6. R/U electric line and perforate Queen formation from 2857' 2871' & 2896' 2903'.
- 7. Move in & R/U BJ Pumping Services and frac well as per BJ treatment proposal.
- 8. R/D BJ Service and clean out to RBP.
- 9. R/U & swab test Queen formation, establish production rate.
- 10. RIH, pull RBP, & RIH with pump & tubing.
- 11. R/D pulling unit and put well on production.





SEAT NIPPLE @ 4235

•

PBTD @ 4421\*
5 1/2" CASING @ 4469" W/985 EXIS, TOC @ SURFACE
TD @ 4470\*

PERFORATIONS: 3328'- 4237' (OA) - 56 HOLES

(NOTE: BOLD PERF DEPTH @ 2 SHOTS/INTERVAL)