

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

DEC 13 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.
RECEIVED

Release Notification and Corrective Action

NAB1034938164		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company WPX Energy Inc/RKI 246289		Contact Karolina Blaney			
Address 5315 Buena Vista Dr.		Telephone No. 970 589 0743			
Facility Name: RDX 15-11		Facility Type: Well Pad			
Surface Owner: Federal		Mineral Owner: Federal		API No. 30-015-37093	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	15	26S	30E	2200	FNL	1500	FWL	Eddy

Latitude: 32.043733284 N Longitude: -103.872277755 W

NATURE OF RELEASE

Type of Release: Produced Water and Oil	Volume of Release: 120 Bbls	Volume Recovered: 0 Bbls
Source of Release Heater Treater	Date and Hour of Occurrence 12/4/2016	Date and Hour of Discovery 12/4/2016 - 9:45 hrs MT
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Heather Patterson & Michael Bratcher, BLM Shelly Tucker	
By Whom? Karolina Blaney	Date and Hour: 12/05/16 - 3:40 hrs MT	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* The cause of this spill is malfunction of the heater treater. The treater and separator caught on fire which resulted in a produced water and oil spill (less than 1 bbl of oil). The majority of the spill was contained inside the SPCC containment berm; approximately 1-2 bbls of water misted outside of the containment. The impacted area was mapped with Trimble.		
Describe Area Affected and Cleanup Action Taken.* The damaged equipment, which was located on the north side of the containment, was removed. Two grab surface samples were collected from the impacted area and are being analyzed for TPH, BTEX and chlorides in accordance with NM OCD Guidelines for Remediation of Leaks, Spills, and Releases. Further remediation will be based on these results.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: Karolina Blaney	OIL CONSERVATION DIVISION	
Printed Name: Karolina Blaney	Signed By: Mike Bratcher Approved by Environmental Specialist	
Title: Environmental Specialist	Approval Date: 12/13/16	Expiration Date: N/A
E-mail Address: Karolina.blaney@wpenergy.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: 12/13/2016	Phone: 970-589-0743	

* Attach Additional Sheets If Necessary

2RP-4032