Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NMOCD Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

5. Lease Serial No. NMNM0488813

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN T	7. If Unit or CA/Agr	eement, Name and/or No.			
1. Type of Well		8. Well Name and No. CAMERON 31 1			
Oil Well Gas Well Other 2. Name of Operator			9. API Well No. 30-015-20007-	9. API Well No. 30-015-20907-00-C1	
3a. Address 3b. Phone No. (include area code)					
6101 HOLIDAY HILL ROAD MIDLAND, TX 79707		Ph: 432-556-8661	WILDCAT	Yeso	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish	, State	
Sec 31 T20S R25E NWSE 1650FSL 1650FEL			EDDY COUNT	Y, NM	
12. CHECK THE AP	PROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent ■ Notice of Intent Not	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off	
	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	Reclamation	
☐ Subsequent Report	Casing Repair	☐ New Construction	☐ Recomplete	Other	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	Workover Operation	
	Convert to Injection	Plug Back	☐ Water Disposal		
determined that the site is ready for fi Fasken Oil and Ranch, Ltd. pla production. Please see attache	ans to add perfs to the Ye	d proposed wellbore diagram	is.		
	M OIL CONSERVATION	1			
Accepted for record . NMOCO			ARTESIA DISTRICT		
	•		SEP 1 3 2017		
Add pay			RECEIVED)	
14. I hereby certify that the foregoing is Com Name (Printed Typed) ADDISON	#Electronic Submission #3 For FASKEN Oli imitted to AFMSS for proce	81158 verified by the BLM We L&RANCH LIMITED, sent to t ssing by PRISCILLA PEREZ o Title REGUL	héCarlsbad		
Signature (Electronic S	ubmission)	Date 07/12/2	APPROVED		
	THIS SPACE FO	R FEDERAL OR STATE	OFFICE USE	Mag	
			- 1 100 (9/PK)		
_Approved By		Title	SUDFAL OF LAND HAVE AND FRANK	Tate NT	
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct to con	itable title to those rights in the		BUREAU OF LAND MANAGEME CARLSBAD LETT DEFICE		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a tatements or representations as	crime for any person knowingly and to any matter within as jurisdiction.	willfully to make to any department o	or agency of the United	
(Instructions on page 2) ** BLM REVI	SED ** BLM REVISED	** BLM REVISED ** BLM	N REVISED ** BLM REVISE	ED **	

Recommended Workover Procedure Cameron "31" Federal No. 1 1650' FSL & 1650' FEL Sec 31, T20S, R25E

Objective: Add Upper Yeso and fracture stimulate.

API: 30-015-20907 KB: 3723'; GL: 3708' Completed 11-5-73

TD: 9,880'

PBTD: 3178' 8-5/8" shoe plug 10-1-2010.

Casing: 13-3/8" 48#/ft @ 198' cmt w/250 sx, Circ to surf. 8-5/8" 24# & 32#/ft @ 3250'w/1200sx, Circ to surf.

4-1/2" 11.6#/ft N-80 TD to 7033', J-55 7033'-1689', N-80 1690'-surf w/450 sx "C". TOC 7860'

Plug3 8-5/8" shoe plug 60 sx "C" 3178'-3400', tagged (10-1-10)

Plug2 60 sx "C" 6357'-6530'. Plug1 62 sx "H" 6809'-7286' Cutoff 4-1/2" csg 9-28-10.

Perfs: Yeso (10-2-10) 2848'-58' (11h),2900'-10'(11h), 2942'-52'(11h),2974'-84' (11h),3012'-22'(11h)

CIBP 8425' w/35' cmt (9-25-10)

Penn (9-28-02) 8475'-79'(5h), 8633'-40' (8h), 8826'-34' (9h), 9046'-58' (13h, 3-12-03)

CIBP: 9395' w/35' cmt (8-1-02)

Morrow 9472'-9482', 9560'-9626', 9632'-9644', 9648'-9654'

Tubing: 1-2-7/8"x4' PS and collar (4.60'), 2-7/8" 8rd SN (1.10'), 2-7/8" EUE rd J55 tbg TK-99 IPC pump jt (32.50'), 86 jts

EUE 8rd J55 tbg (2,789.91'), 6 its 2-7/8" EUE 8rd J55 (YB) tbg (194.26'), EOT 3034.37' KB.

Rods: 2.5"x1.5"x16' RWBC pmp w2" strainer and 1' lift sub (17.00'), 14-1.5" Flexbar C K-bars w/3/4" pins and SHSM

cplgs (350.00'), 96-7/8" Norris N90 rods w/FHSM cplgs (2400.00') new, 9-7/8" Norris N90 rods w/FHSM cplgs (225.00') reran, 2-7/8" Norris 90 pony rods (6' & 4') w/ FHSM cplgs (10.00'), 1-1/4"x16' polish rod w/1-1/2" x 8'

liner (16.00'), total 3018'.

Prod: May-Jun 2017 avg - 5 bopd, 52 bwpd, 7 mcfd

- 1. Test mast anchors and have tank permits in hand before RUPU; notify BLM 24 hrs before starting.
- 2. RUPU. POW with rods and tubing (see detail above).
- 3. RU pump truck and kill well with 20 bfw containing clay stabilizer, oxygen scavenger and biocide.
- 4. NDWH and NU BOP. POW with 2-7/8" tubing and BHA (see detail above).
- 1. RU wireline lubricator. Set 8-5/8" CIBP at 2750'. Dump bail 2 sx Class "C" cement on CIBP (PBTD 2743') RD wireline.
- 2. RU pump truck, fill casing with fresh water containing clay stabilizer, oxygen scavenger and biocide. Pressure test CIBP and casing to 2360 psi (80% of 8-5/8" 24#/ft K-55 burst).
- 3. RIW with 2-7/8" tubing to 2713' and spot 500 gals 15% HCL double inhibited NEFE acid from 2713'- 2518' FS.
- 4. RIW with 4" slick guns and perforate Upper Yeso zone through 8-5/8" casing 2 JSPF, 120° phasing using select fire @ 2620'-25' (20h), 2652'-57' (20h), and 2708'-13' (20h), total 60 holes. POW with guns and note that all shots fired. RDWL.
- 5. RIW with 8-5/8" HD packer, SN, and 2-7/8" EUE 8rd tubing to +/-2500'. Reverse 5 bfw. Set packer in 10 points compression.
- 6. Displace 500 gal spot acid with fresh water at max pressure 2360 psi (80% of 8-5/8" 24#/ft burst) flushing to bottom perf 2713'.


- 7. RU pumping service and acidize perfs 2620'-2713' (60 holes) with 1750 gal 15% NEFE acid with 4 gpt Ferrotrol 280L, 1gpt CI-27, and 1 gpt:NE-940 BJ additives (or equivalent). Pump 250 gals acid followed by 1500 gals acid dropping 66 1.3 s.g. ball sealers evenly spaced. Attempt to achieve ball out with maximum pressure 2360 psi. Displace acid with fresh water containing clay stabilizer and oxygen scavenger. Record ISIP 5, 10 and 15 minute SITP. Bleed pressure off annulus and RD pumping service.
- 8. Swab back load and acid water and evaluate.
- 9. Kill well if necessary with fresh water containing clay stabilizer, oxygen scavenger and biocide. Release 8-5/8" HD packer and RIW to below bottom perf at 2713'. POW with 2-7/8" tubing, SN and packer.
- 10. ND BOP. RDPU.
- 11. NU 5K frac valve. Set frac tanks and fill per stimulation company recommendation with fresh water with biocide.RU stimulation service. Frac Upper Yeso perfs 2620'-2713' (60 holes) via 8-5/8" casing with with 200,000 gal slick water + 100,000 lbs 20/40 sand, maximum pressure 2360 psi (80% of 8-5/8" 24#/ft K-55 burst). Flush to top perf 2620'.
- 12. Flow back until well is dead. ND frac valve.
- 13. RUPU and NU BOP with 2-7/8" pipe rams and blind rams.
- 14. RU reverse unit and RIW with 7-1/2" bit, bit sub, 6 3-/12" DC's and 2-7/8' EUE 8rd J-55 workstring and drill out CIBP at 2750' using fresh water containing clay stabilizer, oxygen scavenger and biocide.
- 15. Clean out to PBTD +/-3178', circulate well clean and POW 2-7/8" tubing and BHA.
- 16. RIW with 2-7/8" bull plugged MA, 2-7/8 " perforated sub and 2-7/8" SN and 2-7/8" EUE 8rd 6.5#/ft J-55 tubing to +/-2550' above top perf @ 2620'.
- 17. Run rods and pump per ALS recommendation to be included with procedure.
- 18. RDPU, clean location and release all rental equipment.
- 19. Return well to production and report on daily drilling reports to Midland office.

CWB/SRF

7-11-17


(Cameron31Fed1 afe 3532 Add U Yeso cwb_srf 7-11-17.doc)

Cameron "31" Federal No. 1



Froducing 3 bopd, 32 bwpd, 7 mck

Cameron "31" Federal No. 1



cwb 7-11-17 Cameron31Fed1 wb diagram.xls