i i i i i i i i i i i i i i i i i i i	NOV 7 2000
Submit 3 Copies To Appropriate District State of New Mexico	NOV - 7 2008 Form C-103
Office Energy, Minerals and Natural Resources	
District I 1625 N French Dr., Hobbs, NM 87240	WELL API NO.
District II 1301 W. Grand Ave. Artesia, NM 88210 OIL CONSERVATION DIVISION	N - <u>30-015-22808</u>
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	STATE x FEE
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. E-7833
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well 🕱 Gas Well 🗌 Other	8. Well Number 156
2. Name of Operator	9. OGRID Number
BP America Production Company	00778
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 1089 Eunice NM 88231	Empire Abo
4. Well Location	
Unit Letter <u>O</u> : <u>600</u> feet from the <u>S</u> line a	nd <u>1330</u> feet from the <u>E</u> line
	7E NMPM County Eddy
11. Elevation (Show whether DR, RKB, RT,	<i>GR</i> , <i>etc.</i>)
3574.8' GR	
Pit or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Co	To any work done.
12. Check Appropriate Box to Indicate Nature of N NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W TEMPORARILY ABANDON CHANGE PLANS COMMENCE	SUBSEQUENT REPORT OF:
PULL OR ALTER CASING AUTIPLE CASING TES COMPLETION CEMENT JOE	T AND Approval Granted providing Vork
	Is complete by
OTHER: OTHER:	
 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 	
 MIRU PU and ancillary plugging equip. Check tbg, 5 1/2" csg and surface pipe for pressures - bleed any fluids into containment. Press test 5 1/2" csg above pkr 0'-5854' w/ 500 psi. (note: if test fails, will need to locate leaks before proceeding with setting plugs.) 	
2. RU swab equipment and make trip with swab mandrel without cu	
paraffin (SN @ 5849').	
3. Kill well down tbg w/ freshwater. Monitor well and assure th	
Release Lok-Set pkr & POH. Visually inspect tbg and replace Continued on page 2.	any joints not usable for P&A operations.
I hereby certify that the information above is true and complete to the best of my kno grade tank has been/wit be constructed or closed according to NMOCD guidelines, a general	
SIGNATURE TITLE Area O E-mail address:	perations Team Lead DATE 11/6/08
Type or print name Barry C. Price	barry.price@bp.com Telephone No. 575-394-1648
For State Use_Only	i . /
APPROVED BY The and TITLE IN	DATE 11/10/08
Conditions of Approval, if any:	

••

Form C-103 Empire Abo Unit L-156 30-015-22808 Continued from Page 1

- 4. TIH w/ 5½" 15.5# CIBP on 2 3/8" tubing and set @ approx 5875' = 45' above top perf @ 5920'. Load hole w freshwater & test csg and CIBP w/ 500 psi . (If test fails, must find source of leak before proceeding with setting plugs.)
- 5. Spot 25 sx Class "C" onto top of CIBP plug set approx 5875' 5630'.
- 6. Circulate and load hole w/ mud laden fluid (minimum of 9.0 ppg with twenty-five 50# sacks of gel per 100 bbls of fluid) and test plug and casing to 500 psi.
- 7. <u>POH & LD tbg to approximately 4125' and spot 25 sx Class "C" from 4125' -</u> <u>3880'</u>, which covers DV tool @ 4004'.
- POH & LD tbg to 3450' (estimated top of Glorieta = 3326'). Spot 25 sack cmt plug from 3450' – 3205'. Pull above cement, WOC and tag plug - If top of plug OK (tagged above 3346'), POH & LD tbg to 1120'.
- 9. <u>Spot 25 sx Class "C" from 1120' 880'</u>, which covers top of Queen @ 1030' and 85/8" surface casing shoe @ 1000'. Pull above cement, WOC & tag plug if top of plug OK (tagged above 950'), POH & LD tbg to 250'.
- 10. Circulate Class "C" cmt from 250' to 0' (estimated 26 sx), which covers top of Yates @ 190' and provides top plug.
- 11. POH & LD tbg. ND BOP and fill casing to 3' below GL if necessary after POH w/ tbg. Clean location of debris from P&A operations.
- 12. RD & RPU. Notify Darryl Sonnier (432 / 557-8713) of completion of work and that cut-off operations can be scheduled.
- Dig out WH and cut-off casingheads to 3' below original GL or at base of cellar, whichever is deeper, and install regulation Dry Hole Marker (4" OD pipe x 10' long with the following permanently inscribed information: (1) well name & number; (2) Operator name; (3) lease serial number E-7833; (4) survey data: quarter quarter section, section, township, range; and (5) date of final abandonment.



ÿ.



,

ء

.