

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

MAY 15 2009

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-34574
1. Type of Well: Oil Well ☐ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator XOG OPERATING, LLC		6. State Oil & Gas Lease No.
3. Address of Operator 1801 W. Texas Ave., Midland, TX 79701		7. Lease Name or Unit Agreement Name CATCLAW 18
4. Well Location Unit Letter P 660 feet from the S line and 660 feet from the E line Section 18 Township 21S Range 26E NMPM Eddy County NM		8. Well Number 001
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3304' GR		9. OGRID Number 236790
		10. Pool name or Wildcat Catclaw Draw; Morrow, W. Gas

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT ☐

**Notify OCB 24 hrs. prior
to any work done.**

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Approval Granted providing work
is complete by 5/18/09

- 1) MIRU Pulling Unit. ND WH, NU BOP. TIH w/tbg to 8,100'.
- 2) Spot 100' cmt plug 8,100'-8,000' (Top of Walfcamp). TOH to 4,100'.
- 3) Spot 100' cmt plug 4,100'-4,000' (Top of Delaware). TOH to 2,205'.
- 4) Spot 100' cmt plug 2,205'-2,105' (csg shoe). Tag
- 5) TOH w/ tbg. ND BOP. ND WH. Pull Stretch on 5 1/2" csg and calculate free point.
- 6) Cut csg @ free point (1600' by Temp Survey). LD 5 1/2" csg. TIH w/tbg to 1700'.
- 7) Spot 100' cmt plug 1,700'-1,600'. TOH w/tbg. Tag
- 8) Spot 100' cmt surface plug. 60' * 100' cmt 600'-500' TAC. (CSC. shoe) 13 3/8"
- 9) Install dry hole marker. Clean and restore location.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Engineer

DATE 5/12/09

Type or print name Nick Hood

E-mail address: NHood@xogoperating.com

PHONE: 432-683-3171

For State Use Only

APPROVED BY:

TITLE

DATE 5/18/09

Conditions of Approval (if any):

- * SPOT 100' cmt plug. 3930' - 3830' (Top of Bone Spring)
- * SPOT 100' cmt plug 1985' - 1885' (Top of Yates)



XOG OPERATING, LLC

1801 W. Texas

P. O. Box 352


Midland, Texas 79702

Catclaw Draw 18-1

660' FSL & 660' FEL Sec 18, T21S, R26E

Eddy Co. NM

API # 30-015-32329



5/12/2009