Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

RECEIVED

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

DEC 2 3 2003

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-entite

5. Lease Serial No. LC-028784B

abandoned well. Use Form 3160-3 (APD) for such proposals.				o. If indian, Another of Title Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side				7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well				8. Well Name and No.	
Oil Well Gas Well Other Plug & Abandon				Burch Keely Unit #22	
2. Name of Operator Marbob Energy Company				9. API Well No.	
3a. Address P. O. Box 227 3b. Phone No. (include area code)				30-015-21658	
Artesia, NM 88211-0227 505-748-				10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				GB Jackson-SR-Q-GB-SA	
2615' FSL & 3985' FEL of Section 18-T17S-R30E				11. County or Parish, State	
Unit L, NWSW				Eddy Co., NM	
12. CHECK AP	PROPRIATE BOX(ES) TO	INDICATE NAT	TURE OF NOTICE, RE	EPORT, OR	OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION					
					Water Shut-Off
Notice of Intent) —	Deepen Fracture Treat	Reclamation		Well Integrity
	! _	New Construction	_ `		Other
Subsequent Report		Plug and Abando		-	
Final Abandonment Notice	,		Water Disposal	***************************************	
	· -				k and approximate duration thereof.
testing has been completed. Ff determined that the site is ready 11-5-2003 - Moved Rigged up rod equ 11-6-2003 - Finis Nippled down well POOH with 2-3/8" and rigged down w 11-7-2003 - Circutop of CIBP at 23 POOH with 52 join 11-8-10-2003 - RI wireline. RIH an RIH with packer a	inal Abandonment Notices shall be for final inspection.) I in and rigged up in inspection. POOH with the POOH with 73 3 head and nippled up tubing. Rigged up vireline. RIH with plated hole with plated hole with plated hole with plate. Shut well in the With tubing and and perforated 5-1/2 and tubing to 697'.	pulling uni 54 3/4" ro /4" rods an p BOP. Rig wireline. tubing and ugging mud. le to 1660' for night. tagged plug " casing at	t and plugging ds. Shut well dpump. Rigged ged up floor at RIH with CIBP tagged CIBP. Spotted 25 st. Spotted 25 woc. at 1403'. Pool with 60 sacks	equipment in for a didown rond 2-3/8 and set Shut we acks Classacks Classack	night. od equipment. " tubing equipment. CIBP at 2390'. POOH ll in for night. ss C Neat cement on ass C Neat cement. tubing. Rigged up
14. I hereby certify that the foregoi					
Name (Printed/Typed) Rusty Klein			Title Agent		
Signature			Date December 10, 2003		
	THIS SPACE FO	or federal of	RSTATE OFFICE USE		entre Branching Charles
Approved by			Title	Da	te .
Conditions of approval, if any, are attached. Approval of this notice does not wa				126	
certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.			Office		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter with the jurisdiction.

MARBOB ENERGY COMPANY Burch Keely Unit #22 Section 18-T17S-R30E Eddy County, New Mexico

SUNDRY NOTICE CONTINUED:

11-21-2003 - Rigged up Rotary Wireline. Freepoint tubing. POOH with wireline. Cut tubing at 501'. POOH with wireline. Worked tubing - could not pull. Run freepoint tool. Found that tubing did not cut. Tubing stuck at 465'. POOH with wireline. RIH with chemical cutter and cut at 465'. POOH with wireline. Pulled tubing free. Rigged down wireline. POOH with tubing. Rigged down floor. Changed out BOP. Rigged up floor. Rigged up pump and pumped down 8-5/8" casing. Holes close to surface to bad to do so pumped down 5-1/2" casing. Could increase flow. Met with Halliburton. Shut well in for night.

11-22-24-2003 - RIH with packer and tubing to 414'. Tried to get injection rate - 1/4 BPM at 2200 psi. Dug out cellar. Found hole in 8-5/8" casing 8' down. POOH with packer. Put clamp on casing. Rigged up Halliburton - clamp leaked. Pulled off clamp and cleaned casing. Put extra rubber with clamp. Still leaked. Pumped 88 sacks cement down 5-1/2" casing and displaced with 8 bbls (which is 1 bbl past perforations). Flow was stopped on 8-5/8" casing. Shut well in for night.

11-25-2003 - Opened up well - 8-5/8" casing dead. Had slight blow on 5-1/2" casing then dead. RIH with tubing and tagged cement at 285'. POOH with tubing. Waiting on reverse unit. RIH with 4-3/4" bit, collars and tubing and drilled cement to 355'. Circulated clean. Shut well in for night.

11-26-2003 - Drilled cement to top of tubing at 465'. Circulated clean. POOH with bit. RIH with mill and washpipe. Milled to 469'. Circulated clean. Getting cement, metal and some flocheck back. Pulled up hole 30'. Shut well in for night.

11-27-2003 - drilled from 469' to 499' and washpipe plugged up. POOH. Recovered 20' of tubing. Shut well in for holidays.

12-2-2003 - Called BLM and got approval from Jim to squeeze at 500'. Laid down drill collars and washpipe. RIH with packer and tubing and set packer at 472'. Had hole above packer. POOH and reset packer at 440'. Established pump in rate of 2-1/2 BPM at 200 psi - no flow out 5-1/2" casing. POOH with packer. RIH with cement retainer and set retainer at 440'. Mixed and pumped 500 gallons Super flush, 212 sacks cement with 3% CaCl2, 12# calseal, 3% CBL and 100 sacks Class C with 2% CaCl2. Flushed with 1 bbl water. Sting out of retainer and POOH. Shut well in for night.

water. Sting out of retainer and Poor. Shut well in for hight.

12-3-2003 - Opened up well - no flow. Rigged up wireline. RIH and tagged plug at 416'.

POOH with wireline. RIH and perforate 5-1/2" casing with 4 shots at 414'. POOH with wireline and rigged down wireline. RIH with packer and tubing to 320'. Pressured up to 1650 psi. Held for 15 minutes. Lost about 50 psi. POOH with packer. Nippled down BOP. RIH open ended to 416'. Circulated 50 sacks Class C Neat cement from 416' to surface. POOH with tubing. Rigged down tubing equipment an dfloor. Rigged down pulling unit and plugging equipment. Installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed December 2, 2003.

Rusty Klein

Agent

December 10, 2003