	State of New Mexico Energy, Minerals and Natural Resources			Form C-103 October 13, 2009		
District I Energy, Witherars and Natural Resources 1628 N. French Dr., Hobbs, NM 88240		W	WELL API NO.			
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION)-015-26795		
District III 1220 South St. Francis Dr.			5.	Indicate Type of Lease		
1000 Rto Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505			6	STATE FEE State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505		,		- 1	G-1525	
	CES AND REPORTS				Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSED DIFFERENT RESERVOIR USE "APPLICATION OF THE PROPOSED PROPOSED IN THE PROPOSED PROPOSE					ate CO Com	
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well O	heREC	EIVED	8.	Well Number	
2. Name of Operator			3 2009	t i	OGRID Number	
Yates Petroleum Corporation 3. Address of Operator					25575 D. Pool name or Wildcat	
105 South Fourth Street, Artesia, N	M 88210	NMOCD	ARTESIA	1 1	orth Dagger Draw Upper Penn	,
4. Well Location Unit Letter H:	1980 feet from the	North	line and	660	feet from the East lin	e
Section 36	Township	19S Rai	nge 24E	N	MPM Eddy County	
	11. Elevation (Show					1364
COLUMN TO THE PARTY OF THE PART		3582	GR			
12. Check A	Appropriate Box to	Indicate N	ature of Notic	ce. Re	port or Other Data	
	,				•	
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WOR			'∩RK	QUENT REPORT OF: ALTERING CASING [7	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI			DRILLI	NG#OPNS.□ PANDA □	7	
TEMPORARILY ABANDON			ENT JO	OB VOINT	_	
DOWNHOLE COMMINGLE					TO CO 24	٠,,
OTHER:			OTHER:		WORL DEST	7
13. Describe proposed or comp	leted operations. (Clea	arly state all r	pertinent details.	and gi	ve pertinent dates, including simated of	⊒_ late
of starting any proposed we	IK). SEE KULE 19.1.	5.7.14 NMAC	C. For Multiple	Comple	etions: Attach wellbore diagram of	
proposed completion or rec	ompletion.					
	•	ic well ac foll	OWe.			
Yates Petroleum Corporation plans t	o plug and abandon th			ill be att	empted.	
	o plug and abandon the afety equipment as ne			ill be att	empted.	
Yates Petroleum Corporation plans t 1. MIRU WSU. NU BOP. RU all s 2. Set a CIBP at 7654' with 35' cer 3. Spot 160' plug from 5504'-5664'	o plug and abandon the afety equipment as new lent on top. across the DV tool.	eded. No cas		ill be att	empted.	
Yates Petroleum Corporation plans t 1. MIRU WSU. NU BOP. RU all s 2. Set a CIBP at 7654' with 35' cer 3. Spot 160' plug from 5504'-5664' 4. Spot 130' plug from 3296'-3426'	o plug and abandon the afety equipment as new lent on top. across the DV tool. across Bone Spring to	eded. No cas		ill be att	rempted.	
Yates Petroleum Corporation plans t 1. MIRU WSU. NU BOP. RU all s 2. Set a CIBP at 7654' with 35' cer 3. Spot 160' plug from 5504'-5664' 4. Spot 130' plug from 3296'-3426' 5. Spot 120' plug from 2021'-2141'	o plug and abandon the afety equipment as newent on top. across the DV tool. across Bone Spring to across Glorieta top.	eded. No cas	ing recovery wi			
Yates Petroleum Corporation plans t 1. MIRU WSU. NU BOP. RU all s 2. Set a CIBP at 7654' with 35' cem 3. Spot 160' plug from 5504'-5664' 4. Spot 130' plug from 3296'-3426' 5. Spot 120' plug from 2021'-2141' 6. Perforate 4 squeeze holes at 1140 circulation cannot be established, set	o plug and abandon the afety equipment as newent on top. across the DV tool. across Bone Spring to across Glorieta top. 'Attempt to establish 100' plug across the s	eded. No cas pp. a circulation to surface casing	ing recovery wing the 7" x 9-5/8 shoe from 104	3" annu 0'-1140	lus, but do not exceed 500 psi. If '. WOC and tag, reset plug if necessary	
Yates Petroleum Corporation plans to 1. MIRU WSU. NU BOP. RU all so 2. Set a CIBP at 7654' with 35' cert 3. Spot 160' plug from 5504'-5664' 4. Spot 130' plug from 3296'-3426' 5. Spot 120' plug from 2021'-2141' 6. Perforate 4 squeeze holes at 1140 circulation cannot be established, set 7. Perforate 4 squeeze holes at 150'.	o plug and abandon the afety equipment as nevent on top. across the DV tool. across Bone Spring to across Glorieta top. 'Attempt to establish 100' plug across the s Attempt to establish	eded. No cas op. n circulation usurface casing circulation up	up the 7" x 9-5/8 shoe from 1040 the 7" x 9-5/8"	3" annu 0'-1140 ' annulu	lus, but do not exceed 500 psi. If '. WOC and tag, reset plug if necessary us, but do not exceed 500 psi. If circular	
Yates Petroleum Corporation plans to 1. MIRU WSU. NU BOP. RU all so 2. Set a CIBP at 7654' with 35' cert 3. Spot 160' plug from 5504'-5664' 4. Spot 130' plug from 3296'-3426' 5. Spot 120' plug from 2021'-2141' 6. Perforate 4 squeeze holes at 1140 circulation cannot be established, set 7. Perforate 4 squeeze holes at 150' cannot be established, set 150' plug from 2021'-2141'	o plug and abandon the afety equipment as nevent on top. across the DV tool. across Bone Spring to across Glorieta top. '. Attempt to establish 100' plug across the s Attempt to establish to the surface. If circu	eded. No cas op. n circulation usurface casing circulation up lation is estat	up the 7" x 9-5/8 shoe from 1040 the 7" x 9-5/8 slished, tie onto	3" annu 0'-1140 ' annulu	lus, but do not exceed 500 psi. If '. WOC and tag, reset plug if necessary	
Yates Petroleum Corporation plans to 1. MIRU WSU. NU BOP. RU all so 2. Set a CIBP at 7654' with 35' cert 3. Spot 160' plug from 5504'-5664' 4. Spot 130' plug from 3296'-3426' 5. Spot 120' plug from 2021'-2141' 6. Perforate 4 squeeze holes at 1140 circulation cannot be established, set 7. Perforate 4 squeeze holes at 150'.	o plug and abandon the afety equipment as nevent on top. across the DV tool. across Bone Spring to across Glorieta top. '. Attempt to establish 100' plug across the s Attempt to establish to the surface. If circuing. WOC and tag, resident	eded. No cas op. n circulation usurface casing circulation up lation is estab set if necessar	ing recovery wing the 7" x 9-5/8 shoe from 1040 the 7" x 9-5/8 blished, tie onto	3" annu 0'-1140 ' annulu	lus, but do not exceed 500 psi. If '. WOC and tag, reset plug if necessary us, but do not exceed 500 psi. If circular	
Yates Petroleum Corporation plans to 1. MIRU WSU. NU BOP. RU all so 2. Set a CIBP at 7654' with 35' cerrors. Spot 160' plug from 5504'-5664' 4. Spot 130' plug from 3296'-3426' 5. Spot 120' plug from 2021'-2141' 6. Perforate 4 squeeze holes at 1140 circulation cannot be established, set 7. Perforate 4 squeeze holes at 150' cannot be established, set 150' plug 150' inside and outside of the 7" cas	o plug and abandon the afety equipment as nevent on top. across the DV tool. across Bone Spring to across Glorieta top. '. Attempt to establish 100' plug across the setablish to the surface. If circuing. WOC and tag, resid weld dry hole market	op. op. ocirculation usurface casing circulation uplation is establed if necessar or per regulation	up the 7" x 9-5/8 shoe from 1040 the 7" x 9-5/8' blished, tie onto y.	3" annu 0'-1140 ' annulu	lus, but do not exceed 500 psi. If '. WOC and tag, reset plug if necessary us, but do not exceed 500 psi. If circular	
Yates Petroleum Corporation plans to 1. MIRU WSU. NU BOP. RU all so 2. Set a CIBP at 7654' with 35' cerrors. Spot 160' plug from 5504'-5664' 4. Spot 130' plug from 3296'-3426' 5. Spot 120' plug from 2021'-2141' 6. Perforate 4 squeeze holes at 1140 circulation cannot be established, set 7. Perforate 4 squeeze holes at 150' cannot be established, set 150' plug 150' inside and outside of the 7" cas 8. Remove all surface equipment an NOTE: Yates Petroleum Corporation	o plug and abandon the afety equipment as nevent on top. across the DV tool. across Bone Spring to across Glorieta top. 'Attempt to establish 100' plug across the sufface. If circuing. WOC and tag, resid weld dry hole market in will use steel pits an	op. n circulation usurface casing circulation uplation is establed if necessary per regulation of the control	up the 7" x 9-5/8 shoe from 1040 the 7" x 9-5/8 blished, tie onto y. ons.	3" annu 0'-1140 ' annulu	lus, but do not exceed 500 psi. If '. WOC and tag, reset plug if necessary us, but do not exceed 500 psi. If circular	
Yates Petroleum Corporation plans t 1. MIRU WSU. NU BOP. RU all s 2. Set a CIBP at 7654' with 35' cer 3. Spot 160' plug from 5504'-5664' 4. Spot 130' plug from 3296'-3426' 5. Spot 120' plug from 2021'-2141' 6. Perforate 4 squeeze holes at 1140 circulation cannot be established, set 7. Perforate 4 squeeze holes at 150' cannot be established, set 150' plug 150' inside and outside of the 7" cas 8. Remove all surface equipment an	o plug and abandon the afety equipment as nevent on top. across the DV tool. across Bone Spring to across Glorieta top. 'Attempt to establish 100' plug across the sufface. If circuing. WOC and tag, resid weld dry hole market in will use steel pits an	op. op. ocirculation usurface casing circulation uplation is establed if necessar or per regulation	up the 7" x 9-5/8 shoe from 1040 the 7" x 9-5/8 blished, tie onto y. ons.	3" annu 0'-1140 ' annulu	lus, but do not exceed 500 psi. If '. WOC and tag, reset plug if necessary us, but do not exceed 500 psi. If circular	
Yates Petroleum Corporation plans to 1. MIRU WSU. NU BOP. RU all so 2. Set a CIBP at 7654' with 35' cerrors. Spot 160' plug from 5504'-5664' 4. Spot 130' plug from 3296'-3426' 5. Spot 120' plug from 2021'-2141' 6. Perforate 4 squeeze holes at 1140 circulation cannot be established, set 7. Perforate 4 squeeze holes at 150' cannot be established, set 150' plug 150' inside and outside of the 7" cas 8. Remove all surface equipment an NOTE: Yates Petroleum Corporation	o plug and abandon the afety equipment as nevent on top. across the DV tool. across Bone Spring to across Glorieta top. 'Attempt to establish 100' plug across the sufface. If circuing. WOC and tag, resid weld dry hole market in will use steel pits an	op. n circulation usurface casing circulation uplation is establed if necessary per regulation of the control	up the 7" x 9-5/8 shoe from 1040 the 7" x 9-5/8 blished, tie onto y.	3" annu 0'-1140 ' annulu	lus, but do not exceed 500 psi. If '. WOC and tag, reset plug if necessary us, but do not exceed 500 psi. If circular	
Yates Petroleum Corporation plans to 1. MIRU WSU. NU BOP. RU all so 2. Set a CIBP at 7654' with 35' cerrors. Spot 160' plug from 5504'-5664' 4. Spot 130' plug from 3296'-3426' 5. Spot 120' plug from 2021'-2141' 6. Perforate 4 squeeze holes at 1140 circulation cannot be established, set 7. Perforate 4 squeeze holes at 150' cannot be established, set 150' plug 150' inside and outside of the 7" cas 8. Remove all surface equipment an NOTE: Yates Petroleum Corporation	o plug and abandon the afety equipment as nevent on top. across the DV tool. across Bone Spring to across Glorieta top. '. Attempt to establish 100' plug across the search Attempt to establish to the surface. If circuing. WOC and tag, resid weld dry hole marke mill use steel pits an	op. n circulation usurface casing circulation usustation is establed if necessary per regulation of no earth pictig Release Da	up the 7" x 9-5/8 shoe from 1040 the 7" x 9-5/8 olished, tie onto y. ons.	3" annu 0'-1140 ' annulu the 7" (lus, but do not exceed 500 psi. If '. WOC and tag, reset plug if necessary is, but do not exceed 500 psi. If circular casing and pump a plug from surface to	
Yates Petroleum Corporation plans to 1. MIRU WSU. NU BOP. RU all so 2. Set a CIBP at 7654' with 35' cerrors. Spot 160' plug from 5504'-5664' 4. Spot 130' plug from 3296'-3426' 5. Spot 120' plug from 2021'-2141' 6. Perforate 4 squeeze holes at 1140 circulation cannot be established, set 7. Perforate 4 squeeze holes at 150' cannot be established, set 150' inside and outside of the 7" cas 8. Remove all surface equipment an NOTE: Yates Petroleum Corporation Spud Date:	o plug and abandon the afety equipment as nevent on top. across the DV tool. across Bone Spring to across Glorieta top. '. Attempt to establish 100' plug across the search Attempt to establish to the surface. If circuing. WOC and tag, resid weld dry hole marke mill use steel pits an	op. n circulation usurface casing circulation usustation is establed if necessary per regulation of no earth pictig Release Da	up the 7" x 9-5/8 shoe from 1040 the 7" x 9-5/8 olished, tie onto y. ons.	3" annu 0'-1140 ' annulu the 7" (lus, but do not exceed 500 psi. If '. WOC and tag, reset plug if necessary is, but do not exceed 500 psi. If circular casing and pump a plug from surface to	
Yates Petroleum Corporation plans to 1. MIRU WSU. NU BOP. RU all so 2. Set a CIBP at 7654' with 35' cerrors. Spot 160' plug from 5504'-5664' 4. Spot 130' plug from 3296'-3426' 5. Spot 120' plug from 2021'-2141' 6. Perforate 4 squeeze holes at 1140 circulation cannot be established, set 7. Perforate 4 squeeze holes at 150' cannot be established, set 150' inside and outside of the 7" cas 8. Remove all surface equipment an NOTE: Yates Petroleum Corporation Spud Date:	o plug and abandon the afety equipment as never to top. across the DV tool. across Bone Spring to across Glorieta top. 'Attempt to establish 100' plug across the sattempt to establish to the surface. If circuing. WOC and tag, resid weld dry hole marked will use steel pits an Riabove is true and comparabove is true an	op. n circulation usurface casing circulation usurfact if necessary per regulation of the per regulation of t	ap the 7" x 9-5/8 shoe from 1040 the 7" x 9-5/8 olished, tie onto by. te: est of my knowledge the street of the	3" annu. 0'-1140 ' annulu the 7" o	lus, but do not exceed 500 psi. If '. WOC and tag, reset plug if necessary is, but do not exceed 500 psi. If circular casing and pump a plug from surface to	tion
Yates Petroleum Corporation plans to 1. MIRU WSU. NU BOP. RU all so 2. Set a CIBP at 7654' with 35' cerrors. Spot 160' plug from 5504'-5664' 4. Spot 130' plug from 3296'-3426' 5. Spot 120' plug from 2021'-2141' 6. Perforate 4 squeeze holes at 1140 circulation cannot be established, set 7. Perforate 4 squeeze holes at 150' cannot be established, set 150' plug 150' inside and outside of the 7" cas 8. Remove all surface equipment an NOTE: Yates Petroleum Corporation Spud Date: I hereby certify that the information SIGNATURE Type or print name Tina Hue	o plug and abandon the afety equipment as nevent on top. across the DV tool. across Bone Spring to across Glorieta top. '. Attempt to establish 100' plug across the setablish to the surface. If circuing. WOC and tag, resid weld dry hole market in will use steel pits and Riabove is true and compared where the surface of the surface. If circuing work and well are steel pits and the surface of well use steel pits and the surface of the surface.	p. n circulation usurface casing circulation usulation is establed if necessary per regulation of the control	ap the 7" x 9-5/8 shoe from 1040 the 7" x 9-5/8 olished, tie onto by. te: est of my knowledge the street of the	3" annu 0'-1140 ' annult the 7" (dus, but do not exceed 500 psi. If '. WOC and tag, reset plug if necessary is, but do not exceed 500 psi. If circulate casing and pump a plug from surface to delete. d belief. DATENovember 10, 2009	tion
Yates Petroleum Corporation plans to 1. MIRU WSU. NU BOP. RU all so 2. Set a CIBP at 7654' with 35' cerrors. Spot 160' plug from 5504'-5664' 4. Spot 130' plug from 3296'-3426' 5. Spot 120' plug from 2021'-2141' 6. Perforate 4 squeeze holes at 1140 circulation cannot be established, set 7. Perforate 4 squeeze holes at 150' cannot be established, set 150' plug 150' inside and outside of the 7" cas 8. Remove all surface equipment an NOTE: Yates Petroleum Corporation Spud Date:	o plug and abandon the afety equipment as nevent on top. across the DV tool. across Bone Spring to across Glorieta top. '. Attempt to establish 100' plug across the setablish to the surface. If circuing. WOC and tag, resid weld dry hole market in will use steel pits and Riabove is true and compared where the surface of the surface. If circuing work and well are steel pits and the surface of well use steel pits and the surface of the surface.	p. n circulation usurface casing circulation usurface if necessary per regulation of the per regulation of th	ing recovery wing the 7" x 9-5/8 shoe from 1040 the 7" x 9-5/8 blished, tie onto y. ons.	3" annu 0'-1140 ' annuly the 7" o	dus, but do not exceed 500 psi. If '. WOC and tag, reset plug if necessary is, but do not exceed 500 psi. If circulate casing and pump a plug from surface to d belief. pervisor DATE November 10, 2009 m PHONE: 575-748-4168	tion
Yates Petroleum Corporation plans to 1. MIRU WSU. NU BOP. RU all so 2. Set a CIBP at 7654' with 35' cerrors. Spot 160' plug from 5504'-5664' 4. Spot 130' plug from 3296'-3426' 5. Spot 120' plug from 2021'-2141' 6. Perforate 4 squeeze holes at 1140 circulation cannot be established, set 7. Perforate 4 squeeze holes at 150' cannot be established, set 150' plug 150' inside and outside of the 7" cas 8. Remove all surface equipment an NOTE: Yates Petroleum Corporation Spud Date: I hereby certify that the information SIGNATURE Type or print name Tina Hue	o plug and abandon the afety equipment as nevent on top. across the DV tool. across Bone Spring to across Glorieta top. '. Attempt to establish 100' plug across the set Attempt to establish to the surface. If circuing. WOC and tag, resid weld dry hole marked will use steel pits an Right above is true and compared to the surface. The surface of the surface of the surface of the surface of the surface. The surface of the sur	p. n circulation usurface casing circulation usurface if necessar per regulation of the	ing recovery wing the 7" x 9-5/8 shoe from 1040 the 7" x 9-5/8 blished, tie onto ry. ons. ts te:	3" annu 0'-1140 ' annuly the 7" o	dus, but do not exceed 500 psi. If '. WOC and tag, reset plug if necessary is, but do not exceed 500 psi. If circulate casing and pump a plug from surface to d belief. pervisor DATE November 10, 2009 m PHONE: 575-748-4168	tion



