DISTRIBUTION	1	1							Form C-103	
DISTRIBUTION							1 C F7		Supersedes (C-102 and C-	
SANTAFE	T		N	EW MEXIC	o oir cqi	SERVATION C	OMMISSION		Effective 1-1	
FILE	1							_		
U.S.G.S.						DEC 14	1979		5a. Indicate Typ	e of Lease
LAND OFFICE						OLO (4	1070		State 🔼	Fee,
OPERATOR	1					Security Security	F-41		5. State Oil & G	as Leαse No.
						O.C.	retre		2-31	105
(DO NOT USE THIS FO	SU ORM FO	NDRY	NOTICES	SAND RE	PORTS C	N WELLS G BACK TO A DIFFE SUCH PROPOSALS.)	RENT RESERVOI	R.		
							•		7. Unit Agreeme	nt Name
OIL GAS	ـ 🗶 ـا ـا		OTHER-							
2. Name of Operator					···				8. Farm or Leas	e Name
	1	ERSE	Y & COM	PANY			· · · · · · · · · · · · · · · · · · ·		State	₫. K.
3. Address of Operator									9. Well No.	
9 6 A	• 12	A-4	N	lew Mex I	co 3321	Ç.			\$	
Location of Well) 10	, AF-L	0510,						10. Field and Pa	ool, or Wildcat
2		66	n		North	LINE AND	1980	_ FEET FROM	FREN SEVE	IN RIVERS
UNIT LETTER	<u> </u>		9 FE	ET FROM THE	1101 50	LINE AND		FEET FROM	millin	
THE EAST	LINE,	SECTION	16	TOWNS	энтр <u>17</u> 5	RANGE _	318	NMPM.		
mmm	m	m	///// ₁₅	Elevation	(Show wheth	ner DF, RT, GR, e	etc.)	· · · ·	12. County	. XXXXXXX
		/////	<i>/////</i>	. LIGYGLION	JIVOW WILELI	,, 011, 6	/			
	777,	11111	7777					-	Eddy	
i6.		•	propriat		Indicate	Nature of No	-		ier Data REPORT OF	:
1401								, ,		
	7			PLUG AND	ABANDON	REMEDIAL WO	DR K	\Box	ALTE	RING CASING
PERFORM REMEDIAL WORK	=			PEGG AND	ABA112011 _	→ ···································		H		AND ABANDONMENT
						COMMENCE D	BILLING ORNS.			
TEMPORARILY ABANDON	=				Г	 1	RILLING OPNS.	<u>, H</u>	PLUG	AND ABANDONMENT
TEMPORARILY ABANDON PULL OR ALTER CASING				CHANGE P	LANS	CASING TEST	AND CEMENT JO			AND ABANDONMENT
Ē				CHANGE P	LANS	CASING TEST	AND CEMENT JO		e-complete	AND ABANDONWENT
Ē				CHANGE P	LANS	CASING TEST	AND CEMENT JO			
other 17. Describe Proposed or C work) SEE RULE 1103	•			arly state al	ll pertinent o	CASING TEST OTHER details, and give	Plum ha	s, including	estimated date of	starting any propo
other 17. Describe Proposed or C work) SEE RULE 1103 Set cast log and Set a cas Ren Tempo 2234 - 23 After set	iro foun ment eret 244: bing abba	n bri d com rete ure 1 , 6) set ng do	dging pent can liner at liner at liurvey a loles; Tension ment the men rele	arly state at the back to 2450 - to packet well to back to bac	3075'. to 2500 and squad census 2252, : at 220 sted 8	casing test other details, and give Put 40' c befor sections t came up 2 holes; 2	pertinent dates pertin	s, including ug on to ing at 3 cament 1 Perfo 97. 8 h th 3500 th a sm	estimated date of plug 2475' with behind the orated cas oles. gallons of plug 2475' with behind the orated cas oles.	starting any proposed. Ran Bond 3 shots. casing. ing as follows. f 15% Acid. of oil.
other 17. Describe Proposed or C work) SEE RULE 1103 Set Cast log and 1 Set a Gas Ren Tempo 2234 - 2: On 2" Tul After set back to	iro foun nent pret 244: bing obbi 2410	n brid com rets ure 5 , 6 i set ng do ng do i em	dging pent can iner at	arly state all ling at me back 2450 ind four 2250 - packer well to based the based to be and complete and com	3075'. to 2500 and squad certer 2252, 3 at 220 at 2251 at 220 at	CASING TEST OTHER DETAILS, and give Put 40' C Serfor Hozed 50 at Came up C holes; 2 O' and aci NCF jas pe	pertinent dates pertin	s, including ug on to ing at 2 coment 1 Perfo 97. 3 h th 3500 th a sm to remove	estimated date of plug 2475' with behind the orated cas oles. gallons of plug 2475' with behind the orated cas oles.	starting any proposed. Ran Bond 3 shots. casing. ing as follows. f 15% Acid. of oil.
other 17. Describe Proposed or C work) SEE RULE 1103 Set Cast log and 1 Set a Gar Ren Tempo 2234 - 2: On 2" Tul After set back to	iro foun nent pret 244: bing obbi 2410	n brid com rets ure 5 , 6 i set ng do ng do i em	dging pent can iner at	arly state all ling at me back 2450 ind four 2250 - packer well to based the based to be and complete and com	3075'. to 2500 and squad certer 2252, 3 at 220 at 2251 at 220 at	CASING TEST OTHER DETAILS, and give Put 40' C Serfor Hozed 50 at Came up C holes; 2 O' and aci NCF jas pe	pertinent dates pertin	s, including ug on to ing at 2 coment 1 Perfo 97. 3 h th 3500 th a sm to remove	estimated date of plug 2475' with behind the orated cas oles. gallons of plug 2475' with behind the orated cas oles.	starting any proposed. Ren Bond 3 shots. casing. ing as follow f 15% Acid. of oil. ran tubing
other 17. Describe Proposed or C work) SEE RULE 1103 Set Cast log and Set a Gar Ren Tempo 2234 - 2: On 2" Tui After set back to	iro foun nent pret 244: bing obbi 2410	n brid com rets ure 5 , 6 i set ng do ng do i em	dging pent can iner at	arly state all ling at me back 2450 ind four 2250 - packer well to based the based to be and complete and com	3075'. to 2500 and squad certer 2252, 3 at 220 at 2251 at 220 at	CASING TEST OTHER DETAILS, and give Put 40' C Serfor Hozed 50 at Came up C holes; 2 O' and aci NCF jas pe	pertinent dates pertin	s, including ug on to ing at 2 coment 1 Perfo 97. 3 h th 3500 th a sm to remove	estimated date of op of plug. 2475' with behind the orated cas oles. gallons usell amount a packer,	starting any proposed. Ren Bond 3 shots. casing. ing as follow f 15% Acid. of oil. ran tubing

CONDITIONS OF APPROVAL, IF ANY: