

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR
(Other instructi
verse side)CATE*
on reForm approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 029395 (A)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Turner "A"

9. WELL NO.

12

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

19-17S-31E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. NAME OF OPERATOR Atlantic Richfield Company	
3. ADDRESS OF OPERATOR P. O. Box 1710, Hobbs, N.M. 88240	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 330' FNL & 660' FEL	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3675' DF

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) Repair 7" production casing ☒PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

TD 3437', PBD 3410'. Presently completed OH 2960-3437'.

7" OD 20# csg set @ 2960'. Cmtd w/100 sx.

8-5/8" OD 24# csg set @ 512'. Cmtd w/50 sx.

Propose to repair hole in production string in the following manner:

1. Rig up, install BOP, pull completion assembly.
2. GIH w/RBP & pkr to locate hole in casing.
3. Squeeze hole or cut off & patch casing & cement w/volume to be determined after pump in. WOC 18 hrs.
4. Drill out & test casing to 1000#.
5. If water flow is coming from behind casing, after running tracer survey, then perf 4 squeeze holes & set open hole BP & squeeze cmt. Clean out to PBD 3410'. RIH w/completion assy & return to production.

RECEIVED
MAY - 8 1975
U.S. GEOLOGICAL SURVEY
ALBUQUERQUE, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Dist. Drlg. Supv.

DATE 5/6/75


(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side



ATLANTIC RICHFIELD COMPANY
Blow Out Preventer Program

Lease Name Turner "A"

Well No. 12

Location 330' FNL & 660' FEL
Sec 19, T17S, R31E, Eddy Co.

BOP to be tested before installed on well and will be maintained in good working condition during workover. All wellhead fittings to be of sufficient pressure to operate in a safe manner.