

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
811 South First, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, New Mexico 87505

WELL API NO. 30-015-05274
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-3627
7. Lease Name or Unit Agreement Name State BK
8. Well No. 4
9. Pool name or Wildcat Grayburg Jackson; 7 RVRs, QN, GB, SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS).	
1. Type Of Well: OIL <input checked="" type="checkbox"/> GAS <input type="checkbox"/> WELL <input type="checkbox"/> OTHER	
2. Name of Operator Mack Energy Corporation	
3. Address of Operator P.O. Box 960, Artesia, NM 88211-0960	
4. Well Location Unit Letter <u>M</u> : <u>990</u> Feet From The <u>South</u> Line and <u>906</u> Feet From The <u>West</u> Line Section <u>19</u> Township <u>17S</u> Range <u>31E</u> NMPM <u>Eddy</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Tag PBTD and spot cement plug from PBTD to 1850' (50' above 5 1/2" shoe). Tag plug @ 1850' 25'sx 17in cmt plug.
* Perforate 5 1/2" csg @ 1300'. Squeeze 30'sx Bal. Cmt Plug 100' inside, 100' outside 9 1/2" csg. Tag
2. Perforate 5 1/2" at 500' and circ cement to surface inside and out. In the event cement will not Circ. squeeze w/ 75'sx and tag top of cmt at 400'. this plug will also cover 8 5/8" shoe.
3. Spot 50' surface plug.
4. Install dry hole marker and clean location.

RECEIVED
OCD ARTESIA

* Brine gel between all cmt plugs.

* Notify NMOCD to witness Plugging Operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Crissa D. Carter

TITLE

Production Clerk

DATE

5/11/98

TYPE OR PRINT NAME

Crissa D. Carter

TELEPHONE NO. (505)748-1288

(This space for State Use)

APPROVED BY

Miss S. Whitefield

TITLE

Field Rep. II

DATE

May 22, 98

CONDITIONS OF APPROVAL, IF ANY: