

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLI
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Hondo Oil & Gas Company ✓

3. ADDRESS OF OPERATOR
P. O. Box 2208, Roswell, New Mexico 88202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
510' FSL & 660' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3780' GL

5. LEASE DESIGNATION AND SERIAL NO.
LC-029435-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
J. L. Keel "B" Federal

9. WELL NO.
39

10. FIELD AND POOL, OR WILDCAT
Grayburg Jackson

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
Sec. 5-T17S-R31E

12. COUNTY OR PARISH
Eddy

13. STATE
NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒

FRACTURE TREATMENT ☒

SHOOTING OR ACIDIZING ☒

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

6/21/88 Perforate 1JSPF @ 3258, 61, 78, 3310, 15, 17, 44, 64, 82, 3450, 60, 78, 3530, 50, 75, 76, 95, 99, 3606, 40, 42, 73, 83, 87, 89, & 3702

6/22/88 Acidize w/ 2000 gal. 15% NEFE & Fracture stimulate w/30,000 gal. 30 lb. crosslinked gel & 54,000 lbs. 16-30 sand. Set frac bomb at 3251 feet perforate 1JSPF @ 3054, 61, 76, 80, 88, 92, 95, 3118, 27, 45, 60, 61, 70, 71, 77, 82, 3202, 16, 27, 30, 33, & 38. Fracture stimulate 3054-3238 w/2000 gal. 7½% NEFE & 40,000 gal. 30 lbs. crosslinked gel w/4000 lbs. 16-30 sand & 82,000 lbs. 12-20 sand.

6/24/88 Perforate 4JSPF @ 3011-3019: Set frac bomb at 3042', acidize w/ 4000 gal. 15% NEFE & Fracture stimulate 3011-3019 w/15,000 gal. 30 lb. crosslinked gel & 18,000 lbs. 20-40 sand. Retrieve frac bombs

6/25/88 RIH w/ 2 3/8" tubing to 1300'. Well started flowing to frac tanks.

18. I hereby certify that the foregoing is true and correct

SIGNED Ron Brown

TITLE Engineer

DATE July 7, 1988

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

*See Instructions on Reverse Side