

# Hallwood Petroleum, Inc.

4610 S. Ulster Street • Suite 200 • P.O. Box 378111  
Denver, Colorado 80237 • (303) 850-7373

## PROPOSED PLUGGING PROCEDURE CATCLAW DRAW UNIT #4 1650' FEL & 1650' FNL SECTION 14-T21S-R15E EDDY COUNTY, NEW MEXICO

1. Set CIBP @ 10,400' - 5<sup>1</sup>/<sub>2</sub>" cap with 25 sacks of cement.
2. Set 200' cement plug from 9,800' - 10,000'.
3. Perforate and squeeze 5<sup>1</sup>/<sub>2</sub>" casing at 7,950' and squeeze cement in and outside casing 150' to 7,800'. Wait for cement to set up and tag.
4. Perforate and squeeze 5<sup>1</sup>/<sub>2</sub>" casing at 4,350' and squeeze cement in and outside casing 100' to 4,250'. Wait for cement to set up and tag.
5. ~~Set cement plug from 1,850' to 1,950'. Wait for cement to set up and tag.~~  
Perforate 5<sup>1</sup>/<sub>2</sub>" csg @ 1950'. Squeeze 100' cement Plug Inside & Outside Csg. TAG - Make S. O.C.D.
6. Perforate and squeeze 5<sup>1</sup>/<sub>2</sub>" casing at 430' and squeeze cement in and outside casing 100' to 330'. Wait for cement to set up and tag.
7. Set cement plug from 50' to surface.
8. Set dry hole marker.

Note: Hole will be circulated and filled with 9.5 pound/gallon mud during plugging activities.

RECEIVED

2001 MAR 13 AM 8:37

BUREAU OF LAND MGMT.  
ROSMELL OFFICE