

District I  
1625 N. French Dr., Hobbs, NM 87240

District II  
811 South First, Artesia, NM 87210

District III  
1000 Rio Brazos Rd., Aztec, NM 87410

District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

CSF  
g

WELL API NO.  
30-015-28348

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

KEYSTONE

8. Well No.  
5

9. Pool name or Wildcat  
BURTON FLAT - BONE SPRING ASSOC.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG AND ABANDON A WELL IN A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

MARALO, LLC

3. Address of Operator

P. O. BOX 832, MIDLAND, TX 79702

4. Well Location

Unit Letter B : 660 feet from the NORTH line and 1980 feet from the EAST line

Section 32 Township 20S Range 28E NMPM EDDY County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3218' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

PROPOSED

OPERATION: Plug and Abandon (work string to be furnished by plugging company)

1. Notify New Mexico Conservation Commission in Artesia, New Mexico @ (505) 748-1283.
2. RUPU. RU wireline, trip in hole w/5 1/2" CIBP set @ ± 6300'. Cap w/35' cmt.
3. PU & RIH w/work string, circ hole w/salt gel mud consisting of 10# brine w/25# gel per bbl.
4. ~~PUH, set 100' cement plug 3400 - 3300' (min 20 sx).~~ 25 sx plug @ 5085'  
25 sx plug @ 2905'
5. POH w/tbg. Determine free point, cut, pull and LD 5 1/2" casing. TOC ± 2470' (temp. survey).
6. RIH w/tbg, spot 130' cmt. plug ± 2550 - 2420' (min 40 sx) across 5 1/2" csg stub and across base 8 5/8" casing. Tag.
7. Spot 100' cement plug 580 - 480' across base 13 3/8" (min 35 sx). Tag.
8. Set 15 sx cement plug @ surface. Install dry hole marker and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dorothea Logan TITLE REGULATORY ANALYST DATE AUGUST 13, 2002

Type or print name DOROTHEA LOGAN

Telephone No. (915) 684-7441

(This space for State use)

APPROVED BY [Signature] TITLE Field Rep DATE AUG 26 2002

Conditions of approval, if any: