	130	OII Const CHV-0 11 W. Grand Ava	anus CISI		
Do not use this form for pro	Y NOTICES AND REPOR oposals to drill or to deeper ICATION FOR PERMIT—" f	n or reentry to a different	reservoir.		
SUBMIT IN TRIPLICATE			7. If Unit or CA, Agreement Designation		
I. Type of Well	- <u>,</u>	<u></u>	Com Sw 247		
Oil Well Other	······································	<u> </u>	8. Well Name and No.		
2. Name of Operator Fasken Oil and Ranch, Ltd.			Ross Federal No. 4		
3. Address and Telephone No.		<u> </u>	9. API Well No. 30-015-32076		
303 W. Wall, Suite 1800, Midla 4. Location of Well (Footage, Sec., T., R.,	D 10. Field and Pool, or Exploratory Area Undesignated Atoka				
3100' FNL, 2600' FEL of Sectio	11. County or Parish, State Eddy, NM				
2. CHECK APPROPF	RIATE BOX(s) TO INDICA	TE NATURE OF NOTIC	E, REPORT, OR OTHER DATA		
TYPE OF SUBMISSIO	Ν	TYPE OF ACTION			
Notice of Intent		Abandonment X Recompletion	Change of Plans		
Subsequent Report		Plugging Back	Non-Routine Fracturing		
		Casing Repair	Water Shut-Off		
Final Abandonment Noti		Altoring Casing Other	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)		

Comparison or Recompletion Report and give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
Fasken Oil and Ranch, Ltd. proposes to temporarily abandon the Morrow and recomplete this well to the Atoka. Please see the attached procedure.

			SEP 23	
			LES BABYA PETROLEUM ENC	1
14. I hereby certify that the foregoing is true and correct, Signat Muller	<u></u>	Pogulatory Affaire Coordinator	<u></u>	
Signed Munique and	Title	Regulatory Affairs Coordinator	Date	9/16/2002
4				
(This space for Federal of State office use) Approved by Conditions of approval, if any:	Title		Date	
(This space for Federal of State office use)		ully to make to any department or agency of th		titious or fraudulent statemen

Ross Federal No. 4 3100' FNL & 2600' FEL Sec 4, T21S R24E AFE 586 Atoka Recompletion Procedure

OBJECTIVE:	Temporarily abandon Morrow, Recomplete to Atoka
WELL DATA:	
13-3/8" 48#/ft H-40 ST&C casing:	Set at 400.77' KB Cmt w/400 sx, circ 75 sx to surf.
9-5/8" 36.0#/ft J-55 LT&C casing:	Set at 3009.60' KB, Cmt w/ 800 sx, circ 48 sx to surf.
4-1/2" 11.6# N-80 LT&C casing:	Set at 9,831.79', Cmt w/950 sx. TOC 8852' by temp survey.
	Marker jts 13.74' @ 9,321.55' and 13.74' @ 8,995.37
Perfs:	9576'-80' (16 h), 9582'-84' (8 h), 9592'-9610' (72 h), 9654'-56'
	(8 h), 9658'-62' (16 h); total 120 holes.
Packer:	4-1/2" Arrowdrill perm packer (3.75 OD x 2.688 ID) on WL @
	9350', w/2-3/8" EUE 8rd N-80 x 8' sub, 2-3/8" x 3-1/2" OD WL
	entry guide, 2-3/8" x 1.781" "R" frac hardened profile nipple.
Tubing:	297 jts 2-7/8" EUE 8rd N-80 tubing, w/2.688'OD x1.98" ID
	threaded latch seal assembly.
TD:	9,831.79'KB csg landed
PBTD:	9,783.91' KB float collar

- 1. RU slickline services and RIW with 1.781" "R" blanking plug and set in profile nipple @ 9358'. Blow down tubing to determine plug is holding.
- 2. RUPU. ND x-mas tree. NU BOP.
- 3. Receive 9400' 2-3/8" N-80 EUE 8rd tubing.
- 4. Fill tubing with 60 bbls 3% KCL water containing packer fluid and ½ gpt BJ's ClayMaster 5C.
- 5. Release tubing from latch seal assembly, POW laying down 2-7/8" N-80 8rd EUE tubing.
- 6. RIW w/4-1/2" X 2-3/8" Arrowset I 10K packer to +/-9,030', TOSSD w/1.875" "F" frac hardened profile nipple and 2-3/8" N-80 EUE 8rd tubing testing tubing to 9500 psi above slips. Set packer.
- 7. Release TOSSD. RU stimulation services and pickle tubing with 500 gal 15% HCL with corrosion inhibitor. Reverse acid to transport or tank using 3% KCL packer fluid and 0.5 gpt Claymaster 5C.. Engage TOSSD.
- 8. ND BOP, NU wellhead landing tubing with packer in 15,000 lbs compression.
- 9. RU pump truck and test 2-3/8" tubing, packer and blanking plug to 5000 psi (about 9000 psi at plug).
- 10. Swab fluid level in tubing to +/-8000'.

- 11. RU wireline with 5000 psi lubricator. Perforate Atoka sand with 1-11/16" Hyper Dome Scallop Hollow Carrier gun (0.2 EHD, 3.2 gm chg, 10.6" pen) at 9090'-9101', 2 jspf zero deg phased, total 22 holes by Schlumberger Platform Express Three Detector Litho-Density Compensated Neutron/GR log dated December 3, 2001.
- 12. Flow well to evaluate.
- 13. RDPU.
- 14. If stimulation is necessary RU BJ Services. RU tree saver. RU pump truck and trap 2000 psi on tubing/casing annulus. Pump 15,000 scf/bbl nitrogen as pad then acidize perfs 9090'-9101' with 750 gal mixture of 7-1/2% HCL +25% methanol w/1000 scf/bbl. Max surface pressure 9500 psi. Additives: 0.5 gpt Clay Master-5C, 2 gpt CI-27, 6 gpt FE-270, iron control, 2 gpt FE-271 Iron Control activator, 1 gpt NE-940 Non-emulsifier, 1 gpt Inflo-150 Surface Tension reducer. Replace 25% of the acid mix water with methanol. 1000 gallons of 7.5% HCL requires 610 gals water and 140 gals 28 Baume HCL, so mix with 457 gals water, 153 gals methanol, 140 gals raw acid. Flush with 3% kcl water containing 1 gpt clay stabilizer with 1000 scf/bbl nitrogen.
- 15. Flow and swab (if necessary) acid and load water.
- 16. Put well on sales line. Evaluate for fracture stimulation.
- 17. Run 4-point test.

cwb (Ross4 AFE586 pro 7-22-02 cwb.doc)