

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87508

NOV - 6 1991

WELL API NO.  
30-015-21526

5. Indicate Type of Lease  
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name  
Wilson Gas Com.

8. Well No.  
1

9. Pool name or Wildcat  
E. Carlsbad - Wolfcamp

SUNDRY NOTICES AND REPORTS ON OIL & GAS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator  
Union Pacific Resources Company

3. Address of Operator  
P. O. Box 7 - MS 3407, Fort Worth, TX 76101-0007

4. Well Location  
Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line  
Section 1 Township 22S Range 27E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3117' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Union Pacific Resources Company is proposing to add perfs to Wolfcamp @ 9196-9392' or P&A if unsuccessful.

Set locator sub w/bullplug in F-1 pkr @ 9400' and test to 1000#. Dump 1 SX CMT on top. SION leaving 1000# on well. Test to 4000#. Spot 1000 gals KCL & 200 gals Acid @ 9400'. Miru W/L perf 9386-92'; 9374-81'; 9310'-14' and 9196-9220'. Swab test well. If necessary, perf 9260-80' and 9228-40' and swab test well. Stimulate w/foam acid. Set Baker 'D' pkr @ 9150'. RIH w/locator seal assy on prod. tbq. and land tbq. Swab in well. If unsuccessful, P&A well as follows:

Get Between Plugs

- Set CIBP @ 9150' and dump 5 SXS CMT on plug.
- Set 10 SXS neat CMT plug 7550-7450' (2nd Bone Springs). 25sx inside & outside
- Set 10 SXS neat CMT plug 5660-5560' (top Bone Springs). 25sx " " " 5500-5800
- Set 10 SXS neat CMT plug 2650-2550' (at 8-5/8" csg shoe). 25sx " " " TAG
- Set 10 SXS neat CMT plug 2300-2200' (top Delaware). 25sx " " " 2137-2237
- Set 10 SXS neat CMT plug 1650-1550' (btm salt). 25sx " " " 330-430
- Set 10 SXS neat CMT plug 850-750' (top salt). 25sx " " " TAG
- Set 10 SXS neat CMT plug 530-430' (@ 13-3/8" csg shoe). 25sx " " " TAG
- Spot 10 SXS neat CMT plug @ surface.
- Cut off WH 3' BGL. @ weld plate tapped w/needle valve on CSG.
- Set P&A well marker 4' AGL and restore location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kris Curran TITLE Regulatory Analyst DATE 11-5-91  
TYPE OR PRINT NAME Kris Curran TELEPHONE NO. (817) 877-6000

(This space for State Use)

APPROVED BY [Signature] TITLE State Rep DATE 12/2/91

CONDITIONS OF APPROVAL, IF ANY:

Plugging