

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instruction on re-
verse side)

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR
J.C. Williamson

3. ADDRESS OF OPERATOR
P.O. Box 16 Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
990' FSL & 990' FWL

RECEIVED

SEP-8-94

ARTESIAN

5. LEASE DESIGNATION AND SERIAL NO.
NM-66824

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
NM OIL CONS COMMISSION
Drawer DD

7. UNIT OR WELL NAME
SunEx Federal

8. FARM OR LEASE NAME
SunEx Fed. Unit

9. WELL NO.
2

10. FIELD AND POOL, OR WILDCAT
North Ross Draw Delaware

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 14, T26S, R30E

12. COUNTY OR PARISH
Eddy

13. STATE
New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugging Procedure

1. Prepare location, dig pit, cut off electricity, rig down pumping unit.
2. COH w/rods, downhole pump, tbgs., tally tubing out of hole.
3. Set CIBP @ 5750', put 35' cement on plug.
4. Weld on and stretch 5-1/2" casing, determine free point.
5. Cut and pull 5-1/2" @ approximately 3600', lay down same.
6. Set 200' plug from 3400-3600', tag plug when hard, re-set if plug not holding, fill all open hole spaces with drlg mud as per BLM specifications.
7. Weld on and stretch 8-5/8" casing to determine free point.
8. Cut and pull 8-5/8" csg @ approx. 2500', lay down same.
9. Set 100' plug 50' in and out of stub, tag when hardened, reset if not holding.
10. Set 100' plug across shoe of 13-3/8" casing (850-750') tag plug when hard, reset if not holding.
11. Set 50' plug in surface.
12. Cut off all pipe at base of cellar after removing the wellhead.
13. Clean location, remove all equipment and debris, fill pit when dry.
14. Reclaim location as per BLM specifications.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE for REW, Engineer

DATE 08-15-94

(This space for Federal or State office use)

(ORIG. SGD.) JOE G. LARA

TITLE PETROLEUM ENGINEER

DATE

9/7/94

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

See attached.

*See Instructions on Reverse Side