submitted in lieu of Form 3160-5

UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on		_
	<u> </u>	
1	7mil 1145 - 5.	Lease Number
Type of Well	2001 HT 22 PM 2:	NMSF-080117 If Indian, All.
GAS	June 1 0.	Tribe Name
GAS .	070 Familiana, Ni	TITUE Name
	7.	Unit Agreement Na
Name of Operator		
BURLINGTON		
RESOURCES OIL & GAS COMPANY LP		
MESEURCES OIL & GAS COMPANY LP		Huerfanito Unit
The second secon	8.	Well Name & Number Huerfanito Unit
Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9	700 9.	API Well No.
PO Box 4209, Fallitington, NM 67499 (505) 326-9	700 9.	30-045-06148
Location of Well, Footage, Sec., T, R, M		Field and Pool
1850'FNL, 1500'FEL, Sec.34, T-27-N, R-9-W, NMPM		Basin Dakota
	11.	
	-1.	San Juan Co, NM
. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NO	TICE, REPORT, OTHER	DATA
	f Action	
<pre>X Notice of Intent</pre>	Change of Pl	
Recompletion	New Construc	
Subsequent Report Plugging Back		
Casing Repair		
Final Abandonment Altering Casi	ng Conversion t	O Injection
Other -		
procedure and wellbore diagram.		
	66780°	
	A SO	
	JUN 2004	
	·	Ť
		1
	12 Charles W.	5
	B. Dist. S	080
	Dist. S	
	1001.8 V.	
	CERTIFIE	
	ECREALIE	
	DOI.S	
	COLS V.	
	DOT. S	
I. I hereby certify that the foregoing is true	and correct.	
gned Manay Oltmanns Title Senior St		Date 6/1/04
gned Vancy Oltmans Title Senior St		Date 6/1/04
gned Vancy Oltmanns Title Senior St	aff Specialist	
gned Vancy Oltmans Title Senior St		Date 6/1/04

Huerfanito Unit #74 Sundry Procedure

Unit G, Section 34, T27N, R9W

- 1. MIRU workover rig. NU and test BOP. TOOH with tubing.
- 2. Attempt 3.875" gauge ring run to PBTD.
- 3. Plug 1: Dakota (TOC 6539', DK top 6642') If unable to get down with gauge ring (most likely case), lay in cement plug (42 sxs) from PBTD to 6539' to P&A the Dakota. WOC. Tag with work string to verify TOC. [If able to get down with gauge ring, set cement retainer at 6589' and set 100' cement plug (12 sxs) above. TOC at 6489'. WOC. Tag with work string to verify TOC.]

4. Plug 2: Gallup (5794' - 5874', GL top 5824') Pick up work string to 5874'. Lay in cement plug (12 sxs) from 5874' to 5794' to P&A the Gallup. WOC. Tag with work string to verify TOC.

- 5. Plug 3: Bad Casing (4588' 4881') TIH with packer to +/- 4470'. Set packer and test backside to 500 psi for 15 minutes. Establish injection under packer. Squeeze milled tight spots from 4588' to 4881' with 45 sxs. Release packer. TOC at 4530'. Pressure test squeeze to 500 psi for 15 minutes. WOC. Tag with work string to verify TOC.
- 6. Plug 4: Mesaverde (3748' 3848', MV top 3798') Perforate 2 squeeze holes at 3848'. Set cement retainer at 3798'. Establish injection under retainer and cement with at total of 51 sxs (39 sxs outside casing and 12 sxs inside casing). Leave 6 sxs on top of retainer to P&A the Mesaverde. TOC at 3748'.
- 7. Plug 5: Chacra (3107' 3207', CH top 3157') Perforate 2 squeeze holes at 3207'. Set cement retainer at 3157'. Establish injection under retainer and cement with at total of 51 sxs (39 sxs outside casing and 12 sxs inside casing). Leave 6 sxs on top of retainer to P&A the Chacra. TOC at 3107'₁₉₁₀
- 8. Plug 6: Pictured Cliffs/Fruitland Coal (2085' 2310', PC top 2260', FC top 1960 2135') TIH with work string to 2310'. Lay in cement plug (27 sxs) from 2310' to 1910 2085' to P&A the Pictured Cliffs and Fruitland Coal. TOOH and lay down work string.
- 9. Plug 7: Kirtland, Ojo Alamo, 8-5/8" shoe and surface (1582' to surface, KT top 1532', OA top 1278', 8-5/8" shoe 348') Perforate 2 squeeze holes at 1582'. Establish circulation out of the 4-1/2" x 7" annulus. Bullhead from surface +/- 600 sxs until good cmt returns are seen at surface. Shut well in and WOC. TOC at surface.
- 10. ND BOP and cut off casing below surface. Install dry hole marker. RDMO workover rig. Restore location.

Huerfanito Unit #74 1850' FNL , 1500' FEL Unit G, Section 34, T27N, R9W San Juan County, NM

36 Deg. 32.03 Min.

107 Deg. 46.36 Min.

G 6433

KB 6447

