Form 3160-5		UNITED STATE				
(Aagust 1998)	DE Bi	FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000				
4		NOTICES AND REPO		3	7. Lease Serial No. NMSF078431	
d	Do not use thi abandoned wel	s form for proposals to I. Use form 3160-3 (AP	drill or to re-enter an D) for such proposals.	-	6. If Indian, Allottee or	Tribe Name
	SUBMIT IN TRII			ment, Name and/or No.		
1. Type of Well Oil Well	Gas Well ☐ Oth	_ [8	8. Well Name and No. NICKSON 7			
2. Name of Opera		cophillips.com				
3a. Address P O BOX 21 HOUSTON,	197 WL 6106 TX 77252		3b. Phone No. (include area code) Ph: 832.486.2463		10. Field and Pool, or BALLARD PICT	
4. Location of W	ell (Footage, Sec., T	., R., M., or Survey Description	n)	1	11. County or Parish, a	and State
	N R8W NESE 160 Lat, 107.66412 W		SAN JUAN COUNTY, NM			
1	2. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE NATURE OF N	NOTICE, REF	PORT, OR OTHE	R DATA
TYPE OF S	UBMISSION		TYPE OF	F ACTION		
Notice of 1	Intent	□ Acidize			n (Start/Resume)	□ Water Shut-Off
☐ Subsequer		Alter Casing	Fracture Treat	_		Well Integrity
_	ndonment Notice	☐ Casing Repair ☐ Change Plans	☐ New Construction ☐ Plug and Abandon	☐ Recomplete ☐ Temporarily Abandon		□ Other
		Convert to Injection		□ Water Dis		
If the proposal Attach the Bor following com testing has bee determined tha	is to deepen directions and under which the wo pletion of the involved in completed. Final Al at the site is ready for f	ally or recomplete horizontally, rk will be performed or provide operations. If the operation re- pandonment Notices shall be final inspection.)	nt details, including estimated startin, give subsurface locations and measue the Bond No. on file with BLM/BLA sults in a multiple completion or reculed only after all requirements, included	ared and true vert A. Required subsompletion in a ne ding reclamation,	ical depths of all pertine equent reports shall be winterval, a Form 316	ent markers and zones. filed within 30 days 0-4 shall be filed once
ConocoPhil	lips plugged and a	bandoned this well effec	tive 9/15/2004. Daily Summar	y is attached.	907 007	2004 S

14. I hereby certify that th	ne foregoing is true and correct. Electronic Submission #36859 verified For CONOCOPHILLIPS COMP Committed to AFMSS for processing by ST	AŇY, s	ent to the Farmington	
Name (Printed/Typed)	CHRIS GUSTARTIS	Title	AUTHORIZED REPRESENTATIVE	
Signature	(Electronic Submission)	Date	09/29/2004	
	THIS SPACE FOR FEDERA	L OR	STATE OFFICE USE	
Approved By ACC	CEPTED		TEPHEN MASON ETROLEUM ENGINEER	Date 10/01/2004
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Farmington	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

County SAN JUAN Spud Date 3/28 d Safety Meeting ation while repairir d Safety Meeting I Equipment - Call d Safety meeting ing 55# - Blow do nge & BOP & cros tire) - @ 14:30, cured well - SDFN d Safety Meeting denhead 0# - Stra k up 5 1/2" DHS O	on JSA's - Beg on JSA's - Finited Tuboscope on JSA's and of own well - Pum as over to 1" to over to 2 3/8" to after talking wi	gan moving lish Rig repairs to prepare versions of the property of the propert	Rig and Equipme ir - Road Rig to L Work String for pi ossible job hazaro H2O down tubing re Test BOP / 25 n Work String (T	2-I s) 264" N This Rpt nt to location - R ocation - Hold Sa ck up on Monday	ig broke dow afety Meeting y AM Check Press	on possible	ed moving eque	- Spot Rig
Spud Date 3/28 d Safety Meeting ation while repairir d Safety Meeting I Equipment - Call d Safety meeting ing 55# - Blow do nge & BOP & cros t tubing - Cross o t tire) - @ 14:30, cured well - SDFN d Safety Meeting denhead 0# - Stra	on JSA's - Begong Rig on JSA's - Finited Tuboscope on JSA's and cown well - Pums over to 1" to over to 2 3/8" to after talking wo	gan moving lish Rig repare to prepare to prepare to prepare to prepare to pred 30 bbls rols - Pressu pols - Wait o	Rig and Equipme ir - Road Rig to L Work String for pi possible job hazard H2O down tubing re Test BOP / 25 n Work String (T	S) 264" N This Rpt Int to location - R ocation - Hold Sack up on Monday ds - Rig up Rig - Int to kill well - Nip	ig broke dow afety Meeting y AM Check Press	Longitude (DMS 107° 39' 50 n - Continue on possible	ed moving eque	uipment to
d Safety Meeting ation while repairing d Safety Meeting Equipment - Call d Safety Meeting 55# - Blow doing 8 BOP & crose tubing - Cross of tire) - @ 14:30, cured well - SDFN d Safety Meeting denhead 0# - Stra	on JSA's - Beging Rig on JSA's - Finited Tuboscope on JSA's and of the second s	ish Rig repare to prepare to prepare to prepare to discussed por pred 30 bbls rols - Pressu bols - Wait o	Ops Rig and Equipme ir - Road Rig to L Work String for pi possible job hazaro H2O down tubing re Test BOP / 25 n Work String (T	This Rpt Int to location - R Int to location - Hold Sack up on Monday Int - Rig up Rig - Int on the Rig up Rig - Int on Int o	ig broke dow afety Meeting y AM Check Press	n - Continue on possible	ed moving equ	- Spot Rig
d Safety Meeting d Safety Meeting Equipment - Call d Safety meeting sing 55# - Blow do nge & BOP & cros E tubing - Cross o v tire) - @ 14:30, cured well - SDFN d Safety Meeting denhead 0# - Stra	on JSA's - Finited Tuboscope on JSA's and cown well - Pumss over to 1" to over to 2 3/8" to after talking wo	ish Rig repare to prepare to prepare to prepare to discussed por pred 30 bbls rols - Pressu bols - Wait o	Rig and Equipme ir - Road Rig to L Work String for pi ossible job hazaro H2O down tubing re Test BOP / 25 n Work String (T	nt to location - R ocation - Hold Sack up on Monda ds - Rig up Rig -	afety Meeting y AM Check Press	on possible	e Job Hazards	- Spot Rig
d Safety Meeting d Safety Meeting Equipment - Call d Safety meeting sing 55# - Blow do nge & BOP & cros E tubing - Cross o v tire) - @ 14:30, cured well - SDFN d Safety Meeting denhead 0# - Stra	on JSA's - Finited Tuboscope on JSA's and cown well - Pumss over to 1" to over to 2 3/8" to after talking wo	ish Rig repare to prepare to prepare to prepare to discussed por pred 30 bbls rols - Pressu bols - Wait o	Rig and Equipme ir - Road Rig to L Work String for pi ossible job hazaro H2O down tubing re Test BOP / 25 n Work String (T	nt to location - R ocation - Hold Sack up on Monda ds - Rig up Rig -	afety Meeting y AM Check Press	on possible	e Job Hazards	- Spot Rig
d Safety meeting bing 55# - Blow donge & BOP & cros E tubing - Cross over tire) - @ 14:30, cured well - SDFN d Safety Meeting denhead 0# - Stra	on JSA's and open well - Pumss over to 1" to yer to 2 3/8" to after talking woon JSA's & dis	discussed po ped 30 bbls lols - Pressu pols - Wait o	Work String for pi possible job hazard H2O down tubing re Test BOP / 25 n Work String (T	ck up on Monday	y AM Check Press			
oing 55# - Blow doinge & BOP & cross of tubing - Cross of tire) - @ 14:30, cured well - SDFN d Safety Meeting denhead 0# - Stra	own well - Pumss over to 1" to over to 2 3/8" to after talking war	iped 30 bbls iols - Pressu ools - Wait o	H2O down tubing re Test BOP / 25 n Work String (T	to kill well - Nip	Check Press	ures / Brade		
oing 55# - Blow doinge & BOP & cross of tubing - Cross of tire) - @ 14:30, cured well - SDFN d Safety Meeting denhead 0# - Stra	own well - Pumss over to 1" to over to 2 3/8" to after talking war	iped 30 bbls iols - Pressu ools - Wait o	H2O down tubing re Test BOP / 25 n Work String (T	to kill well - Nip	Check Press	ures / Brade		
oing 55# - Blow doinge & BOP & cross of tubing - Cross of tire) - @ 14:30, cured well - SDFN d Safety Meeting denhead 0# - Stra	own well - Pumss over to 1" to over to 2 3/8" to after talking war	iped 30 bbls iols - Pressu ools - Wait o	H2O down tubing re Test BOP / 25 n Work String (T	to kill well - Nip	Check Press	ures / Brade		
denhead 0# - Stra			er again, it was de	ruck w/ tubing ha	High - Lay D	ellhead / Nip own Tubing & was waiti	ople Up Recto Hanger & 12 ng on Redbur	r Companio 4 jts of 1" n Tire for
- Sting out of Retain np Plug #1 w/ 81 sing & stinger - Shu Wireline & Tag TO ablished rate out E ulation - Assume	Cement Retaine ainer - Load & sx (112 cu/ft) T ut in Well & WC DC @ 1782' & Bradenhead - F formation brok	628' of 2 3/8 er & Trip in h circulate csg Type III cmt (OC per BLM perforate @ Pumped Plug	" tubing into hole Hole w/ 41 stands g clean w/ 75 bbls @ 14.8 ppg from Inspector - Load 450' - Rig down g #2 w/155 sx Tyl	w/ 5 1/2 " casing - Set Cement R s H2O - Attempt 2628' to 1840' (T csg w/ H2O & at Wireline - Rig up be III @ 14.8 ppg	scraper - Pi etainer @ 26 to pressure to OC 1780' w/ tempt to pres Pump Truck J - After pump	all out of hole 28' - Pressuest csg to 50 required execute test - 12 & Load csgoing 110 sx	e & lay down ure Test tog to 00# - Bled to (ccess) - Lay do Would not hol g w/ 10 bbls H pressured up	scraper - 800# / Held in 3 min - own all d - Rig up 20 & & lost
culation out Brade to surface - Circul Hot Work Permit	nhead & circul lated good cmt & Hold Safety	lated clean w t out of Brad Meeting on l	v/ 10 bbls H2O - i enhead & SIW - i	Pumped Plug #3 Rig down floor &	w/ 25 sx (35 Nipple down	cu ft) Type BOP - Rig	III cmt @ 14.8 down Pump T	ppg from
	ablished rate out I ulation - Assume bector - Shut in wo d Safety Meeting denhead w/ 1 bbl culation out Brade to surface - Circu Hot Work Permit	ablished rate out Bradenhead - I ulation - Assume formation brok bector - Shut in well & SDFN d Safety Meeting & discussed s denhead w/ 1 bbl H2O & pressu- culation out Bradenhead & circu to surface - Circulated good cm Hot Work Permit & Hold Safety	ablished rate out Bradenhead - Pumped Plugulation - Assume formation broke down at Spector - Shut in well & SDFN d Safety Meeting & discussed safety issues denhead w/ 1 bbl H2O & pressure tested to culation out Bradenhead & circulated clean with surface - Circulated good cmt out of Bradenhead expression out of Bradenhead expression out of Bradenhead expression out of Bradenhead surface - Circulated good cmt out of Bradenhead expressions.	ablished rate out Bradenhead - Pumped Plug #2 w/155 sx Tyulation - Assume formation broke down at Surface csg shoe (bector - Shut in well & SDFN) d Safety Meeting & discussed safety issues of perforating & plug for the safety for the	ablished rate out Bradenhead - Pumped Plug #2 w/155 sx Type III @ 14.8 ppg ulation - Assume formation broke down at Surface csg shoe @ 96' - Finished bector - Shut in well & SDFN d Safety Meeting & discussed safety issues of perforating & pumping cmt plug denhead w/ 1 bbl H2O & pressure tested to 300# - Held - Tagged TOC in csg culation out Bradenhead & circulated clean w/ 10 bbls H2O - Pumped Plug #3 to surface - Circulated good cmt out of Bradenhead & SIW - Rig down floor & Hot Work Permit & Hold Safety Meeting on Hot Work - Dig out & cut off Wellh	ablished rate out Bradenhead - Pumped Plug #2 w/155 sx Type III @ 14.8 ppg - After pumpulation - Assume formation broke down at Surface csg shoe @ 96' - Finished pumping plug bector - Shut in well & SDFN d Safety Meeting & discussed safety issues of perforating & pumping cmt plug - Open well denhead w/ 1 bbl H2O & pressure tested to 300# - Held - Tagged TOC in csg @ 50' w/ wire culation out Bradenhead & circulated clean w/ 10 bbls H2O - Pumped Plug #3 w/ 25 sx (35 to surface - Circulated good cmt out of Bradenhead & SIW - Rig down floor & Nipple down Hot Work Permit & Hold Safety Meeting on Hot Work - Dig out & cut off Wellhead & install	ablished rate out Bradenhead - Pumped Plug #2 w/155 sx Type III @ 14.8 ppg - After pumping 110 sx ulation - Assume formation broke down at Surface csg shoe @ 96' - Finished pumping plug & displace bector - Shut in well & SDFN d Safety Meeting & discussed safety issues of perforating & pumping cmt plug - Open well - Bradenhead w/ 1 bbl H2O & pressure tested to 300# - Held - Tagged TOC in csg @ 50' w/ wireline - Perfoculation out Bradenhead & circulated clean w/ 10 bbls H2O - Pumped Plug #3 w/ 25 sx (35 cu ft) Type to surface - Circulated good cmt out of Bradenhead & SIW - Rig down floor & Nipple down BOP - Rig Hot Work Permit & Hold Safety Meeting on Hot Work - Dig out & cut off Wellhead & install Dry Hole M	d Safety Meeting & discussed safety issues of perforating & pumping cmt plug - Open well - Bradenhead & Csg bot denhead w/1 bbl H2O & pressure tested to 300# - Held - Tagged TOC in csg @ 50' w/ wireline - Perforated @ 50' culation out Bradenhead & circulated clean w/10 bbls H2O - Pumped Plug #3 w/25 sx (35 cu ft) Type III cmt @ 14.8 to surface - Circulated good cmt out of Bradenhead & SIW - Rig down floor & Nipple down BOP - Rig down Pump T Hot Work Permit & Hold Safety Meeting on Hot Work - Dig out & cut off Wellhead & install Dry Hole Marker w 35 sx

wran.