

30-045-11296
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

I-22-IND-2772

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

UTS MOUNTAIN
TRIBES OF INDIANS

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

DANIEL HANE

9. WELL NO.

16

10. FIELD AND POOL, OR WILDCAT

Barker Creek Dakota

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREASec. 20, T-32, R-44,
N.M.P.M.

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	15. ELEVATIONS (Show whether DF, RT, GR, etc.)
2. NAME OF OPERATOR Southern Union Production Company	6082 ft. D.F.
3. ADDRESS OF OPERATOR P. O. Box 808, Farmington, New Mexico 87401	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330 ft. from the South line and 970 ft. from the East line.	
14. PERMIT NO.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐
FRACTURE TREAT ☐	MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☒
REPAIR WELL ☐	CHANGE PLANS ☐
(Other) ☐	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACTURE TREATMENT ☐	ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
(Other) ☐	

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to plug and abandon this well. The well is located low on the structure and is presently non-productive.

PLUGGING PROCEDURE:

1. Set cement plug over Dakota formation from total depth of 2275 ft. to 2098 ft. Using 40 sacks of cement. Top of cement will be 100 ft. up in bottom of 5-1/2" casing.
2. Fill 5-1/2" casing with 9.0#/gal mud from 2098 ft. to 250 ft.
3. Perforate 2 holes in 5-1/2" casing at 250 ft. Cement thru holes with 110 sacks cement to set plug in annulus behind 5-1/2" casing from 250 ft. to 100 ft. Displace cement in 5-1/2" casing down to 200 ft. leaving 50 ft. of cement above perfor. inside casing.
4. Set 5 sacks cement plug in top of 5-1/2" casing from 40 ft. to surface.
5. All 5-1/2" casing will be left in the well.
6. Erect dry hole marker, clean location and abandon well.

18. I hereby certify that the foregoing is true and correct

SIGNED GILBERT D. NOLAND, JR.

TITLE Drilling Superintendent

Gilbert D. Noland, Jr.

U. S. GEOLOGICAL SURVEY

DURANGO, COLO.

DATE March 12, 1970

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side