

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.


1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. 1149IND8471
2. Name of Operator BP AMERICA PRODUCTION CO		6. If Indian, Allottee or Tribe Name EASTERN NAVAJO
3a. Address PO BOX 3092 HOUSTON, TX 77253		7. If Unit or CA/Agreement, Name and/or No. NNNM78391C
3b. Phone No. (include area code) Ph: 281.366.4491		8. Well Name and No. GCU 176E
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 25 T28N R13W NWNE 1090FNL 1840FEL 36.63730 N Lat, 108.16724 W Lon		9. API Well No. 30-045-25175-00-C1
		10. Field and Pool, or Exploratory BASIN DAKOTA BASIN FRUITLAND COAL
		11. County or Parish, and State SAN JUAN COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Deepen
<input checked="" type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Fracture Treat
	<input type="checkbox"/> Production (Start/Resume)
	<input type="checkbox"/> Alter Casing
	<input type="checkbox"/> Reclamation
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Change Plans
	<input checked="" type="checkbox"/> Plug and Abandon
	<input type="checkbox"/> Well Integrity
	<input type="checkbox"/> Convert to Injection
	<input type="checkbox"/> Plug Back
	<input type="checkbox"/> Other
	<input type="checkbox"/> Temporarily Abandon
	<input type="checkbox"/> Water Disposal

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompletable horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletable in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

BP request permission to plug and abandon the subject well per the attached procedure.



14. I hereby certify that the foregoing is true and correct. Electronic Submission #54447 verified by the BLM Well Information System For BP AMERICA PRODUCTION CO, sent to the Farmington Committed to AFMSS for processing by STEVE MASON on 02/24/2005 (05SXM0338SE)	
Name (Printed/Typed) MARY CORLEY	Title AUTHORIZED REPRESENTATIVE
Signature (Electronic Submission)	Date 02/24/2005

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By JIM LOVATO	Title PETROLEUM ENGINEER	Date 03/08/2005
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		
Office Farmington		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

GCU 176E API #: 30-045-25175
Plug and Abandonment Procedure
February 23, 2005

1. Notify land owners with gas taps on well.
2. Check anchors. Check ID wellhead, if earth pit is required have One Call made 48 hours prior to digging.
3. Have P&S strip location and set barriers as necessary. Lock out/tag out any remaining production equipment.
4. Contact BLM and NMOCD 24 hrs prior to beginning operations.
5. Nipple up second master valve on well. Reference dispensation to rig up on well with single barrier (to be provided by wellwork team).
6. RU slickline unit or wireline unit. RIH and set tubing stop and "G" packoff with pump through plug for isolation.
7. Set two way check in BPV profile. If BPV profile is not present, set second tubing stop and "G" packoff with positive plug at +/- 100'.
8. MIRU workover rig. Hold safety meeting and perform JSA. Complete necessary paperwork and risk assessment.
9. Check and record tubing, casing, and bradenhead pressures. Ensure production casing has double casing valves installed. Double valve all casing strings. Check hold down pins on hanger.
10. Pressure test tree and hanger to 200 psi above SITP.
11. Blow down well. Kill with 2% KCL water ONLY if necessary. Check all casing strings to ensure no pressure exist on any annulus.
12. Nipple down Wellhead. Reference "No Dual Barrier in Annulus During All Well Servicing" dispensation. NU BOPs and diversion spool with 3" outlets and 3" pipe to the blow tank. Pressure test BOPs to 200 psi above BHP. Monitor flowing casing pressure with gauge (with casing flowing to blow tank) throughout workover.
13. Install stripping rubber. Pull tubing hanger up to rubber and shut pipe rams. Bleed pressure above rams. Pull stripping rubber and hanger up to floor. Remove hanger and replace stripping rubber. Open rams and TOO H w/ 2-3/8 production tubing currently set at 6231'. Use approved "Under Balance Well Control Tripping Procedure". Visually inspect tubing while POOH.
14. TIH w/ bit & scraper to top of perforations and clean out if necessary.
15. TIH with CIBP on tubing. Set CIBP at 6100' to abandon the DK.

GCU 176E API #: 30-045-25175
Plug and Abandonment Procedure Cont'd

16. Spot 12 sxs cement plug to fill from 5950' – 6100' to isolate the Dakota.
17. POOH to 5250'. Use approved "Under Balance Well Control Tripping Procedure".
18. Spot 8 sxs cement plug to fill from 5250' – 5150' to isolate the Gallup.
19. POOH to 2500'. Use approved "Under Balance Well Control Tripping Procedure".
20. Spot 8 sxs cement plug to fill from 2500' – 2400' to isolate the Mesa Verde.
21. TIH with CIBP on tubing. Set CIBP at ^{1432'}~~1400'~~ to abandon the FC. Fill hole with water.
22. Spot 20 sxs cement plug to fill from ^{1432'}~~1150' – 1400'~~ to isolate the Fruitland/Pictured Cliffs.
~~1128' – 1432'~~
23. POOH to 550'. Use approved "Under Balance Well Control Tripping Procedure".
24. Spot 42 sxs cement plug to fill from 550' – surface to isolate the Kirtland/Ojo Alamo.
25. Perform underground disturbance and hot work permits. Cut off tree.
26. Install 4' cement well marker and identification plate per NMOCD requirements.
27. Restore location.



Gallegos Canyon Unit 176E
Dakota/Fruitland Coal
API # 30-045-25175
T-28N, R-13-W, Sec. 25
San Juan County, New Mexico

G.L. 5865'
K.B. 5878'

