Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resource	WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II	OH CONGERNATION DUMON	20.020.20456
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd, Aztec, NM 87410	1220 South St. Francis Dr.	STATE ☑ FEE □
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505		E-289-36
(DO NOT USE THIS FORM FOR PROPO	ICES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH	1
1. Type of Well: Oil Well	Gas Well 🛛 Other	8. Well Number 60
2. Name of Operator		9. OGRID Number
ConocoPhillips Company		217817
3. Address of Operator	25.400.4000	10. Pool name or Wildcat
P.O. Box 4289, Farmington, NM	57499-4289	Blanco Mesaverde
4. Well Location		
Unit Letter A: 109		
Section 32	Township 29N Range 5W	NMPM Rio Arriba County
	11. Elevation (Show whether DR, RKB, RT, GI 6516' GR	R, etc.)
12 Check	Appropriate Box to Indicate Nature of No	tice Report or Other Data
12. Check 1	ippropriate Box to indicate rvature or rvo	nice, Report of Other Data
NOTICE OF IN	ITENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL	_
TEMPORARILY ABANDON		E DRILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CE	EMENT JOB
DOWNHOLE COMMINGLE		
OTHER: Tubing Re	epair 🛭 OTHER: 🗀	· ·
		ils, and give pertinent dates, including estimated date
	ork). SEE RULE 1103. For Multiple Completion	ns: Attach wellbore diagram of proposed completion
or recompletion.		
ConocoPhillins requests permission	to performs tubing repair on the subject wall in o	rder to comply with the NMOCD letter reference:
	attached procedure and current wellbore schemati	
The same with the transfer of the	and current were or seriental.	10111213742
	,	A 36
		6
		\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
		RECEIVED 88 PR 2011 88
		OIL CONS. DIV. DIST. 3
Spud Date: 3/11/1972	Rig Released Date:	4/3/1972 Kn UIL CONS. 511. 514.
I hereby certify that the information	above is true and complete to the best of my known	wledge and belief.
		ululary
SIGNATURE	TITLE Staff Regu	llatory Technician DATE 9/11/201
Type or print name Crystal Tafov	ya E-mail address: crystal.tafoya@c	conocophillips.com PHONE: 505-326-9837
For State Use Only		R Gas Inspector,
	•	trict #3
APPROVED BY: Brandon	TITLE	DATE 7/29/11
Conditions of Approval (if any):		

ConocoPhillips San Juan 29-5 Unit 60 Expense - Repair Tubing

Lat 36° 41' 10.866" N

Long 107° 22' 28.164" W

PROCEDURE

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig
- 2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with 2% KCl, if necessary.

Note: Secondary Seal Test indicated test port plug had pressure. There maybe pressure in the intermediate annulus from being charged.

- 4. ND wellhead and NU BOPE PU and remove tubing hanger and tag for fill, adding additional joints as needed (tubing currently landed @ 7861 7', PBTD @ 7949'). Record fill depth in Wellview.
- 5. TOOH with tubing (details below).

Number	Description
253	2-3/8" 4.7# J-55 EUE tubing joints (7,849 18')
1	2-3/8"x1 780" ID F-Nipple (1.0')
1	Expendable Check Valve (1.0')

Use Tuboscope Unit to inspect tubing and record findings in Wellview Make note of corrosion, scale, or paraffin and save a sample to give to the engineer for further analysis. LD and replace any bad joints. If needed, contact Rig Superintendent or engineer for acid, volume, concentration, and displacement volume.

- 6. RIH with a bit and string mill, cleanout to PBTD of 7949' Save a sample of the fill and contact engineer for further analysis. TOOH. LD tubing bailer (if applicable), if fill could not be CO to PBTD, please call Production Engineer to inform how much fill was left and confirm/adjust landing depth.
- 7. PU packer and retrievable bridge plug for 4 1/2" 11.6# K-55 casing. RIH and set retrievable bridge plug at approximately **7670'KB (40' above top perforation)**. PU up one stand and set packer to test retrievable bridge plug.
- 8. Pressure test retrievable bridge plug with packer, if test fails unset retrievable bridge plug and reset/retest. POOH with packer and reload well with 2% KCl water
- 9. Confirm two barriers have been established. Remove tubing head and inspect secondary seals. If no seal is found, contact Cameron to repair wellhead and install secondary seal. (Confirm 4 1/2" casing sealing with casing hanger). NU tubing head and close intermediate/bradenhead valves. Keep shut in and monitor pressure.
- 10. Rig up Weatherford Wireline Services and log well for GR/CCL/CBL to confirm production casing cement top. (TOC at 4895.37 using 75% eff Calc)
- 11. Casing Pressure Test. Load well with 2% KCl water. Pressure test the 4 1/2" casing to 560 psl for 30 min on a chart recorder with a maximum two hour clock and maximum 1000 pound spring with the intermediate and bradenhead valves open. (Chart recorder calibrated within the six months prior conducting casing integrity test) If the casing does not test, contact the rig superintendent and production engineer for instruction.
- 12. RIH with tubing and cleanout fluid to prevent fallback on to perforations/formations once retrievable bridge plug is removed. Equalize pressure across the retrievable bridge plug, then release retrievable bridge plug and POOH with retrievable bridge plug.
- 13. TIH with tubing using Tubing Drift Procedure. (detail below).

Recommended		
1.901"		
7862'		
7860'		

Number	<u>Description</u>
1	2-3/8" mule shoe/expendable check
1	2-3/8"x1.780" ID F-Nipple
1	2-3/8" 4 7# J-55 EUE tubing joints (31.5')
1	2-3/8" 4.7# J-55 EUE tubing pup joints (2')
248	2-3/8" 4.7# J-55 EUE tubing joints (7793')
X	2-3/8" 4.7# J-55 EUE tubing pup joints (Pup Joints as necessary to achieve proper landing depth)
1	2-3/8" 4.7# J-55 EUE tubing joints (31.5')

- 14. If there is an air package on location, skip to the next step. Run standing valve on shear tool, load tubing, and pressure test to 500#. Monitor pressure for 15 mins, and make a swab run to remove the fluid from the tubing. Retrieve standing valve.
- 15. Perform/Document a BH Test on location and contact the rig superintendent and production engineer with test results.
- 16. ND BOPE, NU Wellhead. Pressure test tubing slowly with an air package as follows: pump 3 bbls pad, drop steel ball, pressure tubing up to 500 psi, and bypass air. Monitor pressure for 15 mins., then complete the operation by pumping off the expendable check. Note in Wellview the pressure in which the check pumped off. Notify the MSO that the well is ready to be turned over to Production Operations. Make swab run to kick-off the well, if necessary, then RDMO.

Tubing Drift Check

Procedure

- 1. Set flow control in tubing. With air, on location, use expendable check. With no air on location, use wire line plug.
- 2. RU drift tool to a minimum 70' line. Drift tool will have an OD of at least the API drift specification of 1.901" for the 2 3/8",4.7# tubing, and will be at least 15" long. The tool will not weigh more than 10# and will have an ID bore the length of the tool, so fluids may be pumped through the tool if it becomes stuck.
- 3. Drop the tool into the tubing string and retrieve it after every 2 joints of tubing ran in hole. If any resistance to the tool movement is noticed, going in or out, that joint will be replaced.
- 4. In order to stimulate the plunger lift operation, all equipment must be kept clean and free of debris.

The drift tool should be measured with calipers before each job, to ensure the OD is the correct size for the tubing being checked. The maximum allowable wear of the tool is .003".

