Submit 3 Copies To Appropriate District Office	State of New	Mexico	Form C-103		
District I	Energy, Minerals and N	latural Resources	Jun 19, 2008		
1625 N French Dr , Hobbs, NM 88240 District II			WELL API NO.	45_35126	
1301 W. Grand Ave , Artesia, NM 88210	OIL CONSERVATION		30-045-35126 5. Indicate Type of Lease		
<u>District III</u> 1000 R10 Brazos Rd , Aztec, NM 87410	1220 South St. F		STATE FEE		
District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505			B-1	0644-84	
SUNDRY NOT (DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	7. Lease Name or Unit Agreement Name Mar Vista SWD				
1. Type of Well: Oil Well	Gas Well Other		8. Well Number 1		
2. Name of Operator		-	9. OGRID Number	•	
Burlington Resources Oil Gas C	ompany LP			4538	
3. Address of Operator	27400 4200		10. Pool name or V	Ť	
P.O. Box 4289, Farmington, NM 8	57499-4289		SWD/	Mesaverde	
4. Well Location	fort form the G. A.	11 1 2400		NV 4 12	
Unit Letter N : 290 Section 2					
Section 2	11. Elevation (Show whether			ian County	
	,	592' GR			
12. Check A	Appropriate Box to Indicate	e Nature of Notice,	Report or Other D	Data	
NOTICE OF IN PERFORM REMEDIAL WORK ☑ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ DOWNHOLE COMMINGLE ☐	ITENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	SUB REMEDIAL WOR COMMENCE DR CASING/CEMEN	ILLING OPNS. F	ORT OF: ALTERING CASING PAND A	
OTHER:		OTHER:			
13. Describe proposed or comp	leted operations. (Clearly state ork). SEE RULE 1103. For Mu	all pertinent details, an	tach wellbore diagran	n of proposed completion	
Burlington Resources requests perm schematic.	ission to stimulate the reservoir	for the subject well per ${\cal S}$	the attached procedur	12 14 16 16 17 18 19 20 3 16 16 17 18 19 20 3 16 16 17 18 19 20 11	
Spud Date: 9/29/2010	Rig F	Released Date: 10/0		OIL CONS. DIV. DIST. 3	
Spud Date: 9/29/2010	i Kig i	TU/	09/2010	17	
I hereby certify that the information	above is true and complete to the	e best of my knowledg	e and belief.	OIL CONS. DIV. DIST. 3	
SIGNATURE Stal	2 Taloya TITLE	Staff Regulatory	<u>Technician</u> DATE	= 9/14/11	
Type or print name Crystal Tafoy	/a E-mail address <u>:</u>	crystal.tafoya@conoco	ophillips.com PHO	NE: 505-326-9837	
For State Use Only		Deputy Oil & Ga	as Inspector.	•	
APPROVED BY: Sconditions of Approval (if any):	TITLE	D:	: #3	DATE 1026-11	

ConocoPhillips Mar Vista #1 SWD

Capital - Reservoir Stimulation

Lat 36° 44' 54.085"

Long 107° 57' 38.689"

PROCEDURE

- 1. Test rig anchors prior to MOL. Flow well back into flowback tanks prior to MOL to bleed off tubing pressure. Engineering anticipates a shut in wellhead pressure of 400 to 600 psig. Kill fluid calculations are based on 600 psig.
- 2 RU slickline and GIH with a 1.75" gauge ring and tag PBTD. Make note of this depth in WellView. Set a FWE plug in the 2.56" F nipple at 3620'. RD slickline.
- 3. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations.
- 4. MOL & RU workover rig and BOP equipment. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 5 Release tubing and seal assembly from packer. Circulate well bottoms up with 11.5 CaCl weighted fluid. Capacity of tubing and tubing/casing annulus is 123 bbls. When well is dead, TOOH with injection string (details below). Stand pipe back in the derrick

Number	Description
1	3-1/2" 9.3# J-55 EUE 8rd (IPC) tubing (32.56')
1	3-1/2" 9 3# J-55 EUE 8rd (IPC) pup joint (4.20')
109	3-1/2" 9 3# J-55 EUE 8rd (IPC) tubing (3533 15')
1	2.56" ID F-nipple (1.53')
1	3-1/2" 9.3# J-55 EUE 8rd (IPC) pup joint (8.12')
1	Seal Assembly (5.00')

Note: Tubing is internally plastic coated. Make note of any abnormal findings concerning the condition of the tubing.

- 6. RU slickline and pull the FWE plug from the F nipple at 3620' that was set in Step #2. RD slickline.
- 7. GIH with a workstring as follows and sting into the Baker FA-1 packer at 3600':

Number	Description		
1	2-3/8" 4.7# N-80 EUE 8rd tubing *		
1	X-over (seal assembly thread x 2-3/8" EUE pin)		
1	Baker 80-40 seal assembly		
1	X-over (3-1/2" EUE box x seal assembly thread)		
1	2 75" F profile nipple (Set FWE test plug inside nipple)		
~114	3-1/2" 9 3# N-80 EUE 8rd tubing		
As required	3-1/2" 9 3# N-80 EUE 8rd pup joints		

- * Note. The bottom joint of 2-3/8" tubing will require the upset on the pin to be cut off and a muleshoe guide cut on the end. The seal assembly will extend 2' into the packer. From this point to the bottom of the lowermost R nipple is 28.59'. Make sure that the modified joint of 2-3/8" tubing is of sufficient length (along with the x-over) to isolate the lowermost R nipple.
- 8 Pressure test the tubing to 6500 psig. RU slickline unit and pull test plug
- 9. RU frac crew and NU 10,000 psi frac valve to 3-1/2" workstring. Hold pre-job safety meeting Complete and review JSA. Pressure test surface lines to 6500 psig (Maximum treating pressure expected is 5016 psig at 50 bpm.)
- 10. Fracture treat the Cliffhouse formation with 118,550 gallons x-link gel, 320,000 lbs. 16-30 and 60,000 lbs. 20-40 mesh sand per the following schedule Mark the beginning of the flush stage when the densiometer reads 7 ppg concentration Flush to the top perforation

	вн				Clean	Stage	Stage	
	Sand		Stage	Slurry	Liquid	Clean	Slurry	Stage
	Conc.	Sand	Sand	Rate	Volume	Rate	Volume	Time
Stage	paq	Mesh	<u>lbs</u>	mad	gallons.	bom	gallons	h:mm:ss
Pad				50.D	35,050	50.0	35,050	0:16:40
1	1.0	20/40	10,000	50.0	10,000	47.8	10,454	0:04:58
2	2.0	20/40	20,000	50 0	10,000	45.9	10,903	0:05:11
3	30	20/40	30,000	50.0	10,000	44.0	11,357	0:05:24
4	4.0	16/3D	48,000	50.D	12,000	42.3	14,171	0:06:44
5	60	16/30	180,000	50.0	30,000	39.3	38,140	0:18:09
6	80	16/30	92,000	50.0	11,500	36.7	15,662	0:07:27
Flush				45.0	1,302	45.0	1,302	0:00:41
			380,000		119,852			1:05:14

- 11 RU coiled tubing unit and BOP. NU flow tee and flow lines to flow back tank NU injector. GIH with 1-1/4" coiled tubing with a mule shoe cut on the end and clean out to PBTD with injection water. Monitor returns for frac sand. Circulate until returns are free of sand. POOH & RD coiled tubing unit. (Note: If clean up is not responding to water circulation, nitrogen can be used to assist in this operation.)
- 12 Unlatch seal assembly from packer and TOOH, laying down the 3-1/2" workstring and isolation tools
- 13. GIH with a re-dressed seal assembly and all other equipment that was pulled in Step #4. Run tubulars and other equipment in the reverse order as pulled. Use API modified thread compound or equivalent.
- 14 Prior to latching into the sealbore of the packer, mix ~58 gallons of Champion Cortron R-2264 packer fluid with 91 barrels 2% KCl and pump into the tubing/casing annulus.
- 15. Land seal assembly and tubing.
- 16. RU slickline and set a test plug in the R nipple at 3629'. Pressure test the tubing and seals to 1000 psig for 30 minutes. Conduct a mechanical integrity test on casing-tubing annulus, pressuring up to **400 psig for 30 min on a 1 hour chart recorder with a 1000# spring**. **Contact NMOCD/BLM to witness MIT**. Record all test results in WellView.
- 17 GIH with slickline and pull R profile test plug from R nipple at 3629'. RD slickline
- 18 ND BOPs and NU wellhead. RD and move off location Notify SWD supervisor and production engineer when the well is ready to be returned to normal injection operations.

