submitted in lieu of Form 3160-5

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	Sundry Notices and Reports on Wells			
	Type of Well GAS	RECEIVED	5. 6.	Lease Number SF-078863 If Indian, All. or Tribe Name Unit Agreement Name
		MAR 26 2012	7.	
•	Name of Operator  ConocoPhillips	Farmington Field Office Bureau of Land Managemen		
	Address & Phone No. of Operator		- 8.	Well Name & Number Krause WN Federal 4E
	PO Box 4289, Farmington, NM 87499 (505) 326-	-9700	9.	API Well No.
<b>4</b> .	Location of Well, Footage, Sec., T, R, M Unit P (SESE), 1025' FSL & 975' FEL, Section 33, T28N, R11W, NMPM			30-045-24486
•			10.	Field and Pool Basin Dakota
			11.	County and State San Juan, NM
2.	CHECK APPROPRIATE BOX TO INDICATE  Type of Submission  X Notice of Intent Subsequent Report Final Abandonment Final Abandonment Type of Action Abandonmen Recompletion Plugging Casing Repai Altering Casi	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut off		DATA Other - Plugback DK / TA wel
13. Describe Proposed or Completed Operations  ConocoPhillips Company requests permission to plugback the Dakota formation and temporary aban uphole potential per the attached procedure, current and proposed wellbore schematics.  The approved war: 1 4/1/13			/ abando	n the subject well for future  RCVD MAR 29'12  DIL CONS. DIV.  DIST. 3
lig		Orrect.  Crystal Tafoya Title Staff Regul	atory Te	chnician Date 3/26/20
	is space for Federal or State Office use) PROVED BY Original Signed: Stephen Mason NDITION OF APPROVAL, if any:	Title		Date MAR 2 7 2012

## ConocoPhillips KRAUSE WN FEDERAL 4E Expense - Plugback

Lat 36° 36' 51.012" N

Long 108° 0' 9.72" W

## **PROCEDURE**

This project requires a NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU work over rig. Check casing and bradenhead pressures and record them in Wellview.
- 3. When an existing primary valve (i.e. casing valve) is to be used, the existing piping should be removed and replaced with the appropriate piping for the intended operation.
- 4. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with water, as necessary.
- 5. ND wellhead and NU BOPE. Function test BOP.
- 6. PU with tubing and tag for fill (if necessary), adding additional joints as needed. If fill is tagged, utilize air package. TOOH with tubing (per Pertinent Data sheet0.

 Rods:
 No
 Size:
 Length:

 Tubing:
 Yes
 Size:
 2 3/8"
 Length:
 6227"

 Packer:
 No
 Size:
 Depth:

7. TIH with workstring and tag for fill. Report fill volumes to engineer and record in Wellview. Based on fill volumed clean out may be necessary. Round trip casing scraper through deepest perforation or as deep as possible.

All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Type II mixed at 15.6 ppg with a 1.18 cf/sk yield.

- 8. Plug 1 (Dakota, 5999-6099', 12 Sacks Class B Cement)
- RIH and set CIBP at 6099'. TIH with 2 3/8" tubing. Pressure test tubing to 1000 psi. Load casing with water and attempt to establish circulation. Mix and pump 12 sx Type II cement to isolate the Dakota perforations and formation top.
- 9. Circulate well clean with water. Pressure test (MIT) casing to 560 psi for 30 minutes and record on a 2-hour chart with 1000# spring. (NMOCD requires a 30 minute test, with no more than 10% pressure loss and rate must be stabilized.) If casing does not test, contact the Production Engineer. Spot and tag subsequent plugs as necessary.
- 10. Pump corrosion Inhibiting fluid ("packer fluid") until water is displaced. Contact Scott Basanko (505-793-4954) at Nalco for treatment details, TOOH and LD tubing. Add additional packer fluid as necessary.

