

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED
OMB No 1004-0137
Expires July 31, 2010

APR 2 2012

Serial No

N00 C-14-20 4323

6. If Indian Allottee or Tribe Name

Navajo Indian

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

2. Name of Operator

ConocoPhillips Company

3a. Address

PO Box 4289, Farmington, NM 87499

3b. Phone No (include area code)

(505) 326-9700

7. If Unit of CA/Agreement, Name and/or No

8. Well Name and No

Chaco Plant 28

9. API Well No

30-045-22156

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit I (NESE), 1850' FSL & 800' FEL, Sec. 13, T26N, R12W

10. Field and Pool or Exploratory Area

Gallegos Fruitland Sand PC

11. Country or Parish, State

San Juan, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation. Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

3/20/2012 Notified BLM (Jim Lovato) & OCD (Brandon Powell) of Plug 2 change. Perf'd @ 285' w/ no circulation. Requested permission to perf @ 200' & circ to surface. BLM requested perf @ 235'. OCD requested CBL be performed if unable to circulate @ 235'. Notified BLM (Jim Lovato) & OCD (Brandon Powell) of Perf @ 235' and no circulation. Requested to pump thru tbg @ 285' and bring up to 235' then bullhead. WOC & Tag. Perf @ 146' and set inside/outside plug. CBL shows bridges at 179' - 194' & 148' - 156'. Verbal approval received.

The subject well was P&A'd on 3/21/2012 per the above notifications and attached report.

RCVD APR 4 '12
OIL CONS. DIV.
DIST. 3

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)

Crystal Tafoya

Staff Regulatory Technician

Title

Signature

Crystal Tafoya

Date

3/30/2012

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

APR 8 2012

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FARMINGTON FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979
Farmington, New Mexico 87499
505-325-2627 *fax: 505-325-1211

Conoco Phillips
Chaco Plant #28

March 21, 2012
Page 1 of 1

1850' FSL and 800' FEL, Section 13, T-26-N, R-12-W
San Juan County, NM
Lease Number: N00 C-14-20-4323
API #30-045-22156

Plug and Abandonment Report Notified NMOCD and BLM on 3/16/12

Plug and Abandonment Summary:

Plug #1 with CIBP at 1045', spot 16 sxs (18.88 cf) class B cement inside casing from 1045' to 465' to isolate the Fruitland Coal top.

Plug #2 with 44 sxs (23.6 cf) class B cement from 357' to surface to cover the Kirtland top.

Plug #3 with 40 sxs (47.2 cf) class B cement inside casing from 111' to cover the Ojo Alamo and casing shoe to surface.

Plug #4 with 20 sxs (23.6 cf) and install P&A marker.

Plugging Work Details:

- 3/16/12 Travel to location. SI well. SDFD.
- 3/19/12 Open up well and blow down 35# casing pressure. Pump 10 bbls of water down tubing to kill well. ND wellhead, PU on 1 1/4" tubing and remove slips. Strip on 4 1/2" casing collar. NU BOP, test OK. TOH and tally 34 joints 1-1/4" EUE tubing, total 1100'. Round trip 2-7/8" gauge ring to 1050'. RIH with 2 7/8" CIBP and set at 1045'. Pressure test 2 7/8" casing to 800#. Spot Plug #1. TOH with tubing. Perforate 3 squeeze holes at 285'. Attempt to establish circulation out bradenhead. Pressured up to 500#. Hook up to BH valve; has "I" valve with nipple. Pressured up to 300#. Hook back to casing. Pressured up to 750# and bled down to 500# and held. SI well. Wait on orders. SDFD.
- 3/20/12 Open up well; no pressures. B. Powell, NMOCD and Farmington BLM approved procedure change. Perforate 3 HSC holes at 235'. unable to establish circulation out bradenhead. Pump 10 bbls at 1 1/2" bpm at 500 psi. Pump 10 bbls of water at 500#; no blow. Hook up to BH and pump 1/2 bbl, pressure up to 700#. NMOCD/BLM required CBL. RU Basin Wireline. RIH and tag TOC at 552'. Run CBL; TOC at 140'. BLM/NMOCD approved procedure change. Spot Plug #2. TOH. SI well. SDFD.
- 3/21/12 Check well pressures: casing 10 psi, tubing 0 and bradenhead 0. Tag TOC at 112'. Perforate 3 HSC holes at 111'. Unable to establish circulation. Clean out casing head and circulate out sand and black water. Circulate clean with 6 bbls. Spot Plug #3. ND BOP and flanges. Dig out wellhead. Monitor well. issue Hot Work Permit. Cut off wellhead. Found cement at surface. Spot Plug #4. Install P&A marker. RD and MOL.