Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resource	ces Jun 19, 2008
1625 N. French Dr , Hobbs, NM 88240		WELL API NO.
District II	OIL CONSERVATION DIVISION	N 30-039-07929
1301 W. Grand Ave., Artesia, NM 88210 District III		5. Indicate Type of Lease
1000 Rio Brazos Rd , Aztec, NM 87410	1220 South St. Francis Dr.	STATE 🛛 FEE 🗌
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St Francis Dr, Santa Fe, NM 87505		E-346
	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	A San Juan 31-6 Unit
DIFFERENT RESERVOIR. USE "APPLI	CATION FOR PERMIT" (FORM C-101) FOR SUCH	San Guan 51 G Chit
PROPOSALS.)	6 W II M 64	8. Well Number 10
1. Type of Well: Oil Well	Gas Well Other	
2. Name of Operator ConocoPhillips Company		9. OGRID Number 217817
3. Address of Operator		10. Pool name or Wildcat
P.O. Box 4289, Farmington, NM	87400 4280	Blanco Mesaverde
		Dianco Mesaverde
4. Well Location		
Unit Letter N : 930		
Section 32	Township 31N Range 6W	NMPM Rio Arriba County
	11. Elevation (Show whether DR, RKB, RT, C	GR, etc.)
	6452' GR	
12. Check	Appropriate Box to Indicate Nature of N	otice, Report or Other Data
NOTICE OF IN	ITENTION TO	CURCEOUENT REPORT OF
<u> </u>	ITENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL	
TEMPORARILY ABANDON		CE DRILLING OPNS.☐ P AND A ☐
PULL OR ALTER CASING	MULTIPLE COMPL	EMENT JOB
DOWNHOLE COMMINGLE		
OTHER:	OTHER:	
OTHER: 13 Describe proposed or comp		ᆸ ails, and give pertinent dates, including estimated dat
		ons: Attach wellbore diagram of proposed completion
or recompletion.	31k). SEE KOLE 1103. For Multiple Completic	ons. Attach welloofe diagram of proposed completion
or recompletion.		
Burlington Resources requ	ests permission to P&A the subject well per the	attached procedure, current and proposed
wellbore schematics.		
	Notify NMOCD 24 hrs	
	prior to beginning operations	
	r ,	
Spud Date:	Rig Released Date:	
I hereby certify that the information	above is true and complete to the best of my known	owledge and belief.
	0 /2	
SIGNATURE XILLU	Lusse TITLE Staff Regu	ulatory Technician DATE 5/21/12
	,	
	se E-mail address: dollie.l.busse@cone	ocophillips.com PHONE: 505-324-6104
For State Use Only	Deputy C	Dil & Gas Inspector,
ADDROVED BY	<i>/ //</i>	District #3 DATE $5/ag//2$
APPROVED BY: 124. 124. Conditions of Approval (if any):	TITLE	DATE 1/29/12
Conditions of Approval (If any):		
	i V	mu one sine the things of the sing
		RCVD MAY 21 '12
		ari antir itili

OIL COMS. DIV.

ConocoPhillips SAN JUAN 31-6 UNIT 10 Expense - P&A

Lat 36° 51' 4.787" N

Long 107° 29' 22.2" W

PROCEDURE

Note: All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Type II mixed at 15.6 ppg with a 1.18 cf/sk yield Plugs subject to change per CBL. This project requires a NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU P&A rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. When an existing primary valve (i.e. casing valve) is to be used, the existing piping should be removed and replaced with the appropriate piping for the intended operation.
- 4. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with water, as necessary, and at least pump tubing capacity of water down tubing.
- 5. ND wellhead and NU BOPE. Pressure and function test BOP. PU and remove tubing hanger.
- 6. TOOH with tubing.

Tubing: Yes **Size**: 2-3/8" **Length**: 5,780

- 7. TIH and tag for fill, adding additional joints as needed. If fill is tagged, utilize air package to 5,300'. TOOH with 2-3/8" tubing (per pertinent data sheet).
- 8. RIH with 5", 10.5# CR and set at 5,300'. Load 5" casing and hold at 500# during CBL. Run a CBL to confirm top of cement (3,546' from 75% eff. calc). Contact engineer with new TOC.

9. Plug #1 (Mesa Verde perforations & formation top, 5,300' - 5,200'):

Pressure test tubing to 1,000#. Mix 15 sx Class B cement and spot a plug inside the casing above CR to isolate the Mesa Verde perforations and formation top. PUH.

10. Plug #2 (Chacra formation top, 4,580' - 4,480'):

Mix 15 sx Class B cement and spot a cement plug inside casing to isolate the Chacra formation top. WOC and POOH.

- 11. RU free-point and cut production casing at 3,350. POOH and LD cut 5" production casing. If casing does not cut low or won't POOH, call Rig Superintendent and Area 8 Production Engineer for plan forward.
- 12. Run 7" mill to top of 5" liner. If unable to reach top of liner, contact Rig Superintendent and Area 8 Production Engineer for plan forward.
- 13. Hold the 7" casing at 500# during the CBL. Run a CBL to confirm top of cement (2,445' from 75% eff. calc) and pull to surface. Contact engineer with new TOC. TOOH.

14. Plug #3 (Intermediate Shoe, Liner top, and Pictured Cliffs formation top, 3,672' - 3,220'):

Mix 97 sx Class B cement and spot a cement plug inside the casing to isolate the Intermediate Shoe, Liner top, and Pictured Cliffs formation top. PUH.

15. Plug #4 (Fruitland formation top, 2,980' - 2,880'):

Mix 29 sx Class B cement and spot a cement plug inside casing to isolate the Fruitland formation top. PUH.

16. Plug #5 (Kirtland formation top, 2,540' - 2,445'):

Mix 28 sx Class B cement and spot a cement plug inside casing to isolate the Kirtland formation top, POOH,

17. Plug #6 (Oio Alamo formation and top. 2.445' - 2.320'):

Perforate 3 HSC holes at 2,445'. Set CR at 2,370'. TIH with tubing and sting into CR. Establish injection rate into squeeze holes. Mix 66 sx Class B cement. Sqz 32 sx Class B cement into HSC holes and leave 34 sx cement inside casing to isolate the Ojo Alamo formation top. POOH.

18. Plug #7 (Nacimiento formation top, 1,116' - 1,016):

Perforate 3 HSC holes at 1,116'. Set CR at 1,066'. TIH with tubing and sting into CR. Establish injection rate into squeeze holes and attempt to circulate to surface. If circulation to surface is established, mix 297 sx Class B cement and squeeze 268 into the HSC holes and leave 29 sx inside the casing. If unable to establish circulation to surface, Mix 58 sx Class B cement and squeeze 29 sx Class B cement into HSC holes and leave 29 sx cement inside casing to isolate the Nacimiento formation top. POOH.

19. Plug #8 (Surface casing shoe and surface plug, 264' - Surface):

If circulation was established in step 18 and cement was pumped to surface, connect the pump line to the bradenhead valve and attempt to pressure test the BH annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix 61 sx Class B cement and spot a balanced plug inside the casing from 264' to surface, circulate good cement out casing valve. If unable to establish circulation in step 18, perforate 3 HSC holes at 264'. Establish circulation out bradenhead with water and circulate BH annulus clean. Mix 136 sx Class B cement and pump down production casing to circulate good cement out bradenhead. Shut in well and WOC.

21. Nipple down BOP and cut off casing below the casing flange. Pour cement down bradenhead annulus until filled with cement to surface. Install P&A marker with cement to comply with regulations. Rig down, move off location, cut off anchors, and restore location to its natural state.



