District I
1625 N. French Dr , Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

					OPERA	ГOR							
Name of Co					Contact: Je	ff Peace							
Address: 2	00 Energy	Court, Farm	IM 87401		Telephone No. (505) 326-9479								
Facility Name: Nye LS 1A						Facility Type: Natural Gas Well							
Surface Ow	ner: Feder	al	Mineral C	wner:	Federal			API No. 3004523047					
				LOCA	TIO	N OF REI	LEASE						
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/W	est Line	County			
0	23 31N 11W 1080 Sou		South		1590	East		San Juan					
	<u></u>	Lati	itude	_36.87987		Longitud	ngitude 107.95668						
				NAT	URE	OF RELI	EASE						
Type of Rele	ase: Conde	ensate			Volume of Release: unknown Volume Recovered: None								
Source of Re	lease: holes	in the bottom	Date and Hour of Occurrence: Date and Hour of Discounknown 11:00 AM						: 5/2	21/2012			
Was Immedi	ate Notice (If YES, To Whom?										
By Whom?			Date and Hour:										
Was a Water	course Read	ched?	If YES, Volume Impacting the Watercourse.										
If a Watercou	irse was Im	pacted, Descr	ibe Fully.	k	RCVD JUN 13'12								
	DIST. 3												
				·						EFI-UT:			
Describe Cause of Problem and Remedial Action Taken.* The existing condensate tank was inspected for shell integrity and was found to be below the desired wall thickness. When the tank was removed for further inspection evidence of possible condensate leaks below the tank were found. Blagg Enginering took samples 2 feet below the surface which resulted in a GRO TPH of 3500. Excavation of impacted soil will take place and an estimate of release volume will be made. The well is shut in and the condensate tank will be replaced after the remediation is completed.													
Describe Area Affected and Cleanup Action Taken.* Evidence of condensate was found two feet deep in the soil directly below the tank. Blagg Engineering will conduct an investigation to determine the vertical and lateral extent of the impacts. Soil removal and other remediation actions will be taken in response to the impacts.													
regulations a public health should their or or the environ	I operators or the envi operations hament. In a	are required to ronment. The nave failed to a	o report ar acceptand adequately OCD accep	e is true and complete is true and complete of a C-141 report investigate and restance of a C-141 report investigate and restance of a C-141 report investigate.	elease n ort by the emediat	otifications are e NMOCD me e contaminati	nd perform correct arked as "Final R on that pose a thr	tive action eport" do eat to gro	ons for rele oes not reli ound water	eases which ieve the oper , surface wa	may er ator of ter, hu	ndan f liab man	ger oility health
Signature: Peff Peace						OIL CONSERVATION DIVISION							
Printed Name	: Jeff Peac	e		Approved by Environmental Specialist:									
Title: Field E			Approval Date: 0/20/2012 Expitation Date:										
E-mail Address: peace.jeffrey@bp.com						Conditions of Approval:			_				
Date: May	24, 2012		Phone:	(505) 326-9479					Attached				
Attach Addi		ets If Necess					MK	, 0 1-	1240	142			
							NJK	10-11	10 10	110			