## RECEIVED

Form 3160-5 (August 2007)

# UNITED STATES DEPARTMENT OF THE INTERIOR JUN 28 2012

FORM APPROVED
OMB No 1004-0137
Expires: July 31, 2010

BUREAU OF LAND MANAGEMENT 20 2012					Expires: July 31, 2010		
			Farmington Fig	eld Of	5 Lease Serial No	078999	
SUP	NDRY NOTICES AND REPO	ORTS O	Real of Land N	/lanag	6. If Indian, Allottee or Tribe Na	me	
Do not us	e this form for proposals t	to drill d	or to re-enter ar	า	·		
abandoned	l well. Use Form 3160-3 (A	PD) for	such proposa	ls.			
	tructions o	on page 2.		7 If Unit of CA/Agreement, Name and/or No.			
1. Type of Well Oil Well X Gas Weil Other					San Juan 31-6 Unit		
Oıl Well			8. Well Name and No.  San Juan 31-6 Unit 30				
2. Name of Operator		<u> </u>		9 API Well No.			
ConocoPhillips Company					30-039-21807		
3a Address PO Box 4289, Farmington, NM 87499  4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)		3b Phone No. (include area code) (505) 326-9700		10 Field and Pool or Exploratory Area  Blanco Mesa Verde			
					11. Country or Parish, State		
	T A, 800' FNL & 900' FEL,	Sec. 35,	, T31N, R6W		Rio Arriba ,	New Mexico	
12. CHECK	THE APPROPRIATE BOX(ES)	TO IND	ICATE NATURE	OF NO	TICE, REPORT OR OTHE	R DATA	
TYPE OF SUBMISSION TYPE OF AC					TION		
X Notice of Intent	Acidize	Deep	oen .	P	roduction (Start/Resume)	Water Shut-Off	
	Alter Casing	Fract	ure Treat	R	eclamation	Well Integrity	
Subsequent Report	Casing Repair	New	Construction	R	ecomplete	Other	
$\underline{\hspace{0.1cm}}$	Change Plans	Plug	and Abandon	X T	emporarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug	Back	W	Vater Disposal		
current wellbore schema	permission to temporary abo atic. TA approved vi	ondon tr	e subject well to	or furur	e uphole potential per ti	ne attached procedu	ıre
					RCVD JUL 5'12		
Notify NMOCD 24 prior to beginn operations			1116		OIL CONS. DIV.		
					DIST. 3		
14. I hereby certify that the foregoing	is true and correct Name (Printed/Typ	ed)	Γ				
DENISE JOURNEY		,	Title		REGULATORY TECHNICIAN		
> . 1					6/28/2012		
Signature Denus	e ourney		Date		0/20/2012		
	THIS SPACE FO	R FED	ERAL OR STAT	E OFF	ICE USE		
Approved by				<del></del>			
Original Sig	gned: Stephen Mason					JUN 2	9 20
Conditions of approval, if any, are atta	ched Approval of this notice does not	warrant or		tle		Date	
that the applicant holds legal or equita entitle the applicant to conduct operati	ble title to those rights in the subject le			ffice			
Title 18 U S.C Section 1001 and Title	43 U.S C Section 1212, make it a crir	ne for any	person knowingly and	willfully	to make to any department or age	ency of the United States an	y

(Instruction on page 2)

false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

## ConocoPhillips SAN JUAN 31-6 UNIT 30 Expense - TA

Lat 36° 51' 40.685" N

Long 107° 25' 32.124" W

#### **PROCEDURE**

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview If there is pressure on the BH, contact engineer to review complete BH history and get a gas analysis done.
- 3. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with produced water, if necessary.
- 4. ND wellhead and NU BOPE. PU and remove tubing hanger and tag for fill, adding additional joints as needed. Record fill depth in Wellview.
- 5. TOOH with tubing (per pertinent data sheet). Tubing will be laid down.

Use Tuboscope Unit to inspect tubing and record findings in Wellview. Make note of corrosion, scale, or paraffin and save a sample to give to the engineer for further analysis.

- 6. Round trip gauge ring with wireline for 4.5" 10.5# J-55 casing (ID: 4.052").
- 7. Use wireline to set CIBP for 4.5" 10.5 J-55 casing Set CIBP at 5,404' (50' above top MV perfations 5,454').
- 8. Perform MIT (Mechanical Integrity Test) above the CIBP to 600 psig for 30 minutes on a 2 hour chart. If pressure test fails, test CIBP and notify engineer
- 9. If MIT is good, TIH with tubing and displace KCI with packer fluid. TOOH and lay down tubing.
- 10 ND BOP, NU wellhead, and notifiy engineer and lead that the operation is complete. RDMO.

### **Tubing Drift Check**

#### **Procedure**

- 1 Set flow control in tubing. With air, on location, use expendable check. With no air on location, use wire line plug.
- 2. RU drift tool to a minimum 70' line. Drift tool will have an OD of at least the API drift specification of 1 901" for the 2 3/8",4.7# tubing, and will be at least 15" long. The tool will not weigh more than 10# and will have an ID bore the length of the tool, so fluids may be pumped through the tool if it becomes stuck
- 3. Drop the tool into the tubing string and retrieve it after every 2 joints of tubing ran in hole. If any resistance to the tool movement is noticed, going in or out, that joint will be replaced.
- 4. In order to stimulate the plunger lift operation, all equipment must be kept clean and free of debris.

The drift tool should be measured with calipers before each job, to ensure the OD is the correct size for the tubing being checked. The maximum allowable wear of the tool is .003".

