RECEIVED

Form 3160-5

UNITED STATES

FORM APPROVED

(August 2007)	DEPARTMENT OF THE BUREAU OF LAND MAN				. 1004-0137 uly 31, 2010
Farmington Field C SUNDRY NOTICES AND REPORTS ON WELL's and Mana				6 If Indian, Allottee or Tribe Name	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				RCVD SEP 11'12	
	IBMIT IN TRIPLICATE - Other ins			7 If Unit of CA/Agreement, Na	
1. Type of Well				8. Well Name and No	
Oil Well X Gas Well Other				Sheets 4	
2 Name of Operator Burlington Resources Oil & Gas Company LP				9 API Well No. 30-045-24297	
3a Address	3b Phone No (include area co	No (include area code) 10 Field and Pool or Exploratory Area			
PO Box 4289, Farmingt	(505) 326-9700)	Blanco PC / Basin DK		
4. Location of Well (Footage, Sec., T., F. Surface Unit O (S	FEL, Sec. 28, T31N, R9	W	11. Country or Parish, State San Juan ,	New Mexico	
12. CHECK	THE APPROPRIATE BOX(ES)	TO INDICATE NATURE	OF NO	TICE, REPORT OR OTHE	R DATA
TYPE OF SUBMISSION		TYPE OF ACTIO			
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	<u> </u>	Production (Start/Resume)	Water Shut-Off Well Integrity
X Subsequent Report	Casing Repair	New Construction	=	Recomplete	Other
Final Abandonment Notice	Change Plans Convert to Injection	X Plug and Abandon Plug Back	===	`emporarily Abandon Vater Disposal	
Attach the bond under which the v following completion of the involv Testing has been completed Final determined that the site is ready fo	onally or recomplete horizontally, give work will be performed or provide the I red operations. If the operation results Abandonment Notices must be filed or final inspection.) Mason/BLM & Brandon Po	subsurface locations and measu Bond No. on file with BLM/BIA in a multiple completion or reco only after all requirements, inclu-	red and tr Require empletion ding recla	rue vertical depths of all pertinent ed subsequent reports must be file in a new interval, a Form 3160-4 amation, have been completed and	markers and zones ad within 30 days must be filed once d the operator has
@ 1795', no cmt. Press	on Powell/OCD (BLM Rep ured to 1500#. Temp surve ceived verbal approval.				
could not circulate. Ra	on Powell/OCD (BLM Rep n CBL. Requested permise circ. If unable to circ, set in	sion to run inside plug	g from	1638'-1807'. (Plug #8)	requested permission
	&A'd on 7/31/12 per the at		the at	tached report.	
14. I hereby certify that the foregoing is	s true and correct Name (Printed/Typ	ed)			
Dollie L. Busse		Title Staff I	Title Staff Regulatory Technician		
Signature All.	& Burno	Date 8/3	3//	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

Approved by Title

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

FARMANGTON FIELD CO-HI Office MY

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources
Sheets #4

July 31, 2012 Page 1 of 3

1100' FSL and 1530' FEL, Section 28, T-31-N, R-9-W San Juan County, NM Lease Number: SF-080376-A API #30-045-24297

Plug and Abandonment Report Notified NMOCD and BLM on 7/12/12

Plug and Abandonment Summary:

- **Plug #1** pump 20 sxs (23.6 cf) Class B cement inside casing from 7325' to 7055' to cover the Dakota perforations.
- Plug #2 pump 20 sxs (23.6 cf) Class B cement with 2% CaCl inside casing from 6586' to 6316' to cover the Gallup top.
- **Plug #3** pump 20 sxs (23.6 cf) Class B cement inside casing from 5644' to 5374' to cover the Mancos top.
- Plug #3a with 50 sxs (59 cf) Class B cement inside casing from 5644' to 4969' to cover the Mancos top.
- **Plug #4** pump 40 sxs (47.2 cf) Class B cement inside casing from 4810' to 4270' to cover the Mesaverde top.
- **Plug #5 & 6 combined** pump 73 sxs (86.14 cf) Class B cement inside casing from 3779' to 3070' to cover the Chacra top, intermediate shoe and top of liner.
- **Plug #7** pump 80 sxs (94.4 cf) Class B cement inside casing from 2970' to 2543' to cover the Pictured Cliffs and Fruitland top.
- Plug #8 pump 15 sxs (17.7 cf) Class B cement inside casing from 1870' to 1790' to cover the Kirtland top.
- **Plug #9** pump 42 sxs (49.56 cf) Class B cement inside casing from 1807' to 1583' to cover the Kirtland and Ojo Alamo tops.
- Plug #10 pump 55 sxs (64.9 cf) Class B cement squeeze 26 out 7" casing, 9 sxs below CR and 20 sxs above CR from 420' to 266' to cover the Nacimento top.
- **Plug #11** pump 105 sxs (123.9 cf) Class B cement with 54 sxs inside 7" casing and 51 sxs outside csing with approximately 10 sxs of good cement in returns to pit.
- Plug #12 pump 20 sxs Class B cement to install P&A marker.

Plugging Work Details:

7/16/12 Travel to location. Spot in. Check well pressures: tubing 220 PSI, casing 225 PSI and bradenhead 5 PSI. RU and pump 40 bbls of water down tubing to kill well. ND wellhead and NU BOP. Pressure test BOP, OK. TOH and tally 242 joints 2-3/8" tubing with SN and BP. Note: pipe was dragging coming out of hole and had to work free every 40' until 1000' was out of hole. RIH with 4.5" bit and string mill to 3116'. SI well. SDFD.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources
Sheets #4

July 31, 2012 Page 2 of 3

Plugging Work Details (continued):

- 7/17/12 Check well pressures: tubing 135 PSI, casing 130 PSI and bradenhead 0 PSI. TIH with string mill to 7367'. TOH and LD string mill. PU 1 -4 ½" DHS CR and TIH to 7325'; set CR. Pressure test tubing to 1100 PSI no bleed off. Circulate total of 230 bbls water circulate clean. Spot plug #1. LD joints to 7044' and TOH. SI Well. SDFD.
- 7/18/12 Open up well; no pressures. TIH and tag plug #1 at 7086'. LD tubing to 6586'. Spot plug #2. TOH to 5362' pulled wet string. Attempt to pump water down tubing pressure up to 2000 PSI unable to pump. RIH and perforate 3 1- 9/16" circular shots. TIH and tag cement at 5927'. TOH with 36 stands. SI well. SDFD.
- 7/19/12 Open up well; no pressures. BLM required drill out on Plug #2. TOH with tubing; last 15 joints cemented up. PU 1 3-7/8" blade bit and x-over sub. TIH to 1560'. Wait on air package and flow back tank. RU Weatherford air package. Circulate with air to blow dry. TIH to 3178'. Circulate with air. SI well. SDFD.
- 7/20/12 Check well pressures: casing 150 PSI, tubing 50 PSI and bradenhead 0 PSI. Circulate with air with 8 bph mist to 3178' with no fluid returns. TIH and tag cement at 5739'. RU power swivel. Circulate wellbore and unload 30 bbls water with air and 12 bph mist. Drill 2' through. Tag cement at 5927'. Circulate well bore with air at 12 bph mist unload. Continue in hole; drilled 2' and fell through. Tag plug at 6481'. Circulate well bore with air at 8 bph mist. Stand back power swivel. TOH to 3116'. SI well. SDFD.
- 7/23/12 Check well pressures: casing 40 PSI, tubing 55 PSI and bradenhead 0 PSI. Finish TOH and LD BHA. TIH open ended to 5644'. Circulate well clean. Spot plug #3. TOH to 2243'. SI well. SDFD.
- 7/24/12 Open up well; no pressures. TIH to 5644'; no tag on plug #3. Load casing with 70 bbls water and circulate. Spot plug #3. LD tubing to 4924'. TOH and WOC. TIH and tag plug #3 at 5252'. LD to 4810'. Circulate well. Spot plug #4. LD joints to 4237'. SI well. SDFD.
- 7/25/12 Open up well; no pressures. TIH and tag plug #4 at 4539'. Circulate well. R. Chavez, BLM and NMOCD approved procedure change. Spot plug #5 & #6 combined. TOH and WOC. TIH and tag plug #5 & #6 at 3106'. SI Well. SDFD.
- 7/26/12 Open up well; no pressures. RIH with 5-3/4" ground ring to 2970'; stacked out. POH with green cement. TIH to 2970' with bit and stringer mill. Tag cement to 2980'. Circulate well shut in casing valve. Pressure test casing to 850 PSI for 15 min no bleed off. Wait on orders. S. Mason, BLM and NMOCD, approved procedure change. TIH open ended to 2970'. Spot plug #7 and #8. Note: S. Mason, BLM, changed Plug #8 from 1850' to 1807'. Reverse circulate well clean. SI well. SDFD.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources
Sheets #4

July 31, 2012 Page 3 of 3

Plugging Work Details (continued):

- Open up well; no pressures. RIH with wireline and perforated 3 HSC holes at 1795' and tag plug #8 at 1807'. POH. Attempt to establish rate pressure up to 1300 PSI for 15 min. Wait on orders. RIH with CBL and log 7" casing from 1800' to surface. Found top of cement at 1050' with stringers throughout well to 230'. SI Well. SDFD.
- 7/30/12 Open up well; no pressures. TIH open ended to 1807'. S. Mason, BLM and B. Powell, NMOCD approved procedure change. Spot plug #9. RIH and perforate 3 HSC holes at 420'. Unable to establish circulation. Reverse circulate down bradenhead. Wait on orders. BLM and NMOCD approved procedure change. TIH with 7" DHS CR to 373' and set CR. Establish rate of 3 bpm at 900 PSI. Spot plug #10. Reverse circulate and TOH. RIH and perforate 3 HSC holes at 220'. Establish circulation out bradenhead and circulate well clean. TIH with tubing to 278'. Establish circulation out bradenhead and casing. Spot plug #11. LD all tubing. Pump additional 20 sxs to fill 7" casing. SI well. SDFD.
- 7/31/12 Open up well; no pressures. ND BOP. Dig out wellhead. Fill out Hot Work Permit and cut off wellhead. Found cement at surface. Spot Plug #12 and install P&A marker. RD & MOL.

A. Rodriguez and R. Bixler, BLM representatives, were on location. Ronald Chavez, BLM representative, was on location.