Submit 3 Copies To Appropriate District Office	fice State of New Means and Netwerl Decourses			Form C-103 Jun 19, 2008	
District I	N French Dr , Hobbs, NM 88240 ct II W Grand Ave., Artesia, NM 88210 ct III Rio Brazos Rd., Aztec, NM 87410 ct IV S St. Francis Dr , Santa Fe, NM		WELL API NO.	119, 2000	
District II			30-045-08709		
1301 W Grand Ave., Artesia, NM 88210			5. Indicate Type of Lease		
District III 1000 Rio Brazos Rd Aztec NM 87410			STATE FEE		
District IV			6. State Oil & Gas Lease No.		
1220 S St. Francis Dr , Santa Fe, NM 87505			FEE		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name McGrath		
1. Type of Well: Oil Well Gas Well Other			8. Well Number 3		
2. Name of Operator			9. OGRID Number		
Burlington Resources Oil Gas Company LP			14538		
3. Address of Operator			10. Pool name or Wildcat		
P.O. Box 4289, Farmington, NM 87499-4289			Basin Fruitland Coal		
4. Well Location			- · · · · · · · · · · · · · · · · · · ·		
Unit Letter J: 1650	feet from theSouth	line and165	feet from the East	line	
Section 3		inge 12W	NMPM San Juan County		
	11. Elevation (Show whether DR			14	
	5845				
12. Check Ap	ppropriate Box to Indicate N	Vature of Notice,	Report or Other Data		
NOTICE OF INT	ENTION TO:	l CHD	SEQUENT REPORT OF:		
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WOR				NIC 🗆	
· · · · · · · · · · · · · · · · · · ·	= 1				
 -	MULTIPLE COMPL	CASING/CEMEN			
DOWNHOLE COMMINGLE	MOETIFEE COMITE	CASING/CLIVIEN	1 30B		
OTHER:		OTHER:			
			d give pertinent dates, including esting tach wellbore diagram of proposed controls.		
Burlington Resources request	s permission to P&A the subject	well per the attached	d procedure, current and proposed		
wellbore schematics.	•	•	• • •	7	
ion to haginning					
	oper	rations	OIL CONS. DIV	н	
Spud Date:	Dia Pale	eased Date:	DIST. 3		
Spau Date.	Kig Kek	eased Date.			
I hereby certify that the information ab	give is true and complete to the b	est of my knowledg	e and belief.		
SIGNATURE Sellie X	Dusse TITLE	Staff Regulatory	Technician DATE 9/24/	1/2	
Type or print name Dollie L. Busse	E-mail address: dollie.	l.busse@conocophil	lips.com PHONE: 505-324-6104	ļ	
For State Use Only	_			-	
	<i>2.771</i>	Deputy Oil & C	ias inspector,	, _	
APPROVED BY:	TITLE_	Distric	ot #3 DATE 10/1/	12	
Conditions of Approval (if any):	^				

A

ConocoPhillips MCGRATH 3 Expense - P&A

Lat 36°45' 8.28" N

Long 108°4' 55.956" W

PROCEDURE

This project requires a NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. When an existing primary valve (i.e. casing valve) is to be used, the existing piping should be removed and replaced with the appropriate piping for the intended operation.
- 4. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with water, as necessary, and at least pump tubing capacity of water down tubing.
- 5. ND wellhead and NU BOPE. Function and pressure test BOP. PU and remove tubing hanger.
- 6. TOOH with tubing (per pertinent data sheet).

Tubing:

Yes

Size:

1.9"

Set Depth:

1908

Round trip casing scraper just above top perforation at 1872'. A CBL has been run and is on file for this well.

All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Type II mixed at 15.6 ppg with a 1.18 cf/sk yield.

7. Plug 1 (Fruitland Coal and Pictured Cliffs Perforations, 1722-1822', 10 Sacks Class B Cement)

TIH and set 3-1/2" cement retainer at 1822'. Load hole with water and circulate well clean. Pressure test tubing to 1000#. Pressure test casing to 800#. If the casing does not test, then spot or tag subsequent plugs as appropriate. Mix 10 sxs Class B cement and spot inside the casing above the CR to isolate the Pictured Cliffs and Fruitland Coal intervals. TOOH.

8. Plug 2 (Intermediate Plug, 1410-1510', 39 Sacks Class B Cement)

Perforate 3 squeeze holes at 1510'. RIH and set 3-1/2" CR at 1460'. Establish rate into squeeze holes. Mix 39 sxs Class B cement; squeeze 32 sxs behind casing leaving 7 sxs inside casing to cover the intermediate shoe. TOOH with tubing.

9. Plug 3 (Fruitland Coal Top, 1282-1382', 38 Sacks Class B Cement)

Perforate 3 squeeze holes at 1382'. RIH and set 3-1/2" CR at 1332'. Establish rate into squeeze holes. Mix 38 sxs Class B cement; squeeze 31 sxs behind casing leaving 7 sxs inside casing to cover Fruitland Coal top. TOOH with tubing.

10. Plug 4 (Ojo Alamo & Kirtland Tops & Surface Shoe, 524-729', 74 Sacks Class B Cement)

Perforate 3 squeeze holes at 729'. RIH and set 3-1/2" CR at 679'. Establish rate into squeeze holes. Mix 74 sxs Class B cement; squeeze 62 sxs behind casing leaving 12 sxs inside casing to cover Ojo Alamo & Kirtland formation tops & surface casing shoe. TOOH with tubing.

11. Plug 5 (Surface Plug, 0-100', 38 Sacks Class B Cement)

Perforate 3 squeeze holes at 100'. Establish circulation out bradenhead with water and circulate the BH annulus clean. Mix 38 sx Class B cement and pump down production casing to circulate good cement out intermediate and bradenhead if possible. Top off cement in casing annulus. Shut in well and WOC.

12. Nipple down BOP and cut off casing below the casing flange. Install P&A marker with cement to comply with regulations. Rig down, move off location, cut off anchors, and restore location.



