Form 3160-5 (August 1999)

#### **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

5. Lease Serial No.

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

### SUNDRY NOTICES AND REPORTS ON WELLS

SUNDRY NOTICES AND REPORTS ON WELLS			NMSF78417A
Do not use ti abandoned w	his form for proposals to drill or to vell. Use Form 3160-3 (APD) for suc	h proposals UN 6 AM	1 %. (If Indian, Allottee or Tribe Name
1. Type of Well	IPLICATE - Other instructions of	n reverse side 070 FARMINGT	7. If Unit or CA/Agreement, Name and/or No.
Oil Well  Gas Well	_l Other		8. Well Name and No. San Juan 28-7 Unit #54
2. Name of Operator ConocoPhillips Co.		A BUILDING ST	9. API Well No.
3a. Address		ne No. (include area code)	(2) 30-039-07347
P.O. Box 2197, WL3-6081 Houston Tx 77252 (832)486-2  4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		50-2403 O O O O O O O O O O O O O O O O O O O	Field and Pool, or Exploratory Area Blanco Mesaverde/Pictured Cliffs
Sec 22 T28N R7W SESW	800FSL 1840FWL		County or Parish, State Rio Arriba
12. CHECK AP	PROPRIATE BOX(ES) TO INDICA	TE NATURE OF NOTICE,	RÉPORT, OR OTHER DATA
TYPE OF SUBMISSION		TYPE OF ACTION	
<ul> <li>□ Notice of Intent</li> <li>□ Subsequent Report</li> <li>□ Final Abandonment Notice</li> </ul>	Casing Repair New C	re Treat Reclamation onstruction Recomplete and Abandon Temporarily Ab	□     Well Integrity       Other     Workover       Operations
If the proposal is to deepen dire	ctionally or recomplete horizontally, give sub	surface locations measured and true v	any proposed work and approximate duration thereof. vertical depths of all pertinent markers and zones.
following completion of the inv	olved operations. If the operation results in a rall Abandonment Notices shall be filed only af	nultiple completion or recompletion i	ed subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once action, have been completed, and the operator has
ConocoPhillips moved a workover rig onto this well in order to do bradenhead/casing repair. A log was run on 5/9/05 which indicated that the gas in intermediate was from Lewis Shale. Charlie Perrin from the OCD noted that there was no indication of zone to zone communication and that no remedial work was required after all. Bad tubing and tubing collars were replaced with end of tubing now @ 5,694'. Daily summary is attached.			
	·		
	,		
		·	
14. I hereby certify that the foregoin Name (Printed/Typed)	g is true and correct	Title	
Christina Gustartis		Regulatory Analyst	<del> </del>
Signature V	lonte	Date 06/03/2005	ACCEPTED FOR RECORD
THIS SPACE FOR FEDERAL OR STATE OFFICE USE, JUN 2 1 2005			
Approved by		Title	PARMINGTON FIELD OFFICE
	attached. Approval of this notice does not w		BY HATTER STATE OF THE STATE OF
which would entitle the applicant to			

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or

fraudulent statements or representations as to any matter within its jurisdiction.

# ConocoPhillips

## Regulatory Summary

### SAN JUAN 28-7 UNIT 054

Repair Downhole Failure, 05/02/2005 00:00

API/Bottom UWI County State/Province

300390734700 RIO ARRIBA NEW MEXICO

Surface Legal Location NMPM-28N-7W-22-N N/S Dist (ft) N 800.00

N/S Ref E/W Dist (ft) S 1,840.00

07/10/1956

E/W Ref

Ground Elevation (ft) 6.783.00 Latitude (DMS) 36° 38' 29.508" N Longitude (DMS) 107° 33' 46.8" W Spud Date

Rig Release Date

05/02/2005 07:00 - 05/02/2005 15:00

Last 24hr Summary

TO MUDDY TO MOVE RIG, SHUT DOWN RIG MOVE, TRY NEXT DAY.

05/03/2005 07:00 - 05/03/2005 15:00

Last 24hr Summary

TOO MUDDY TO MOVE RIG

05/04/2005 07:00 - 05/04/2005 15:00

Last 24hr Summary

CHECK OUT ROADS, TOO MUDDY TO MOVE RIG.

05/05/2005 07:00 - 05/05/2005 18:00

Last 24hr Summary

PRE JOB SAFETY MTG WITH RIG CREW & TRUCKING, LOAD OUT EQIPMENT, MOVE RIG AND EQUIPEMNT TO NEW LOCATION SPOT IN EQUIPMENT & RIG UP RIG. CHECK PRESSURES, TBG 225 PSI, CAS 220 PSI, INTERMEDIATE 900 PSI, BLOW DOWN TUBING & CASING, PUMP 10 BBLS 2% KCL DOWN TUBING INSTALL BPV, NIPPLE DWN WELL HEAD & NIPPLE UP BOP. PRESSURE TEST BOP, AS PER CONOCOPHILLIPS REQUIREMENTS TEST GOOD. PULL DONUT, REMOVE BPV, SHUT IN SECURE WELL FOR NIGHT.

05/06/2005 07:00 - 05/06/2005 17:00

Last 24hr Summary

PRE JOB SAFETY MTG. CHECK PRESSURE 200 PSI ON TUBING & CASING, BLOW DWN CASING, PUMP 20 BBLS 2% DOWN TUBING, POOH TALLY TUBING. MAKE UP SCRAPER ON TUBING, GO IN HOLE WITH SCRAPER TO 5080', POOH, LAY DWN SCRAPER MAKE UP PACKER & BRIDGE PLUG ON TUBING, PACKER WAS NOT WORKING CORRECTLY, REMOVED PACKER, MAKE UP BRIDGE PLUG ON TUBING, GO IN HOLE TO 5000'. LOAD HOLE WITH 2% KCL, PRESSURE TEST CASING TO 500 PSI, HELD GOOD, BLEED OFF PRESSURE. SHUT IN SECURE WELL FOR NIGHT.

05/09/2005 07:00 - <End Date?>

Last 24hr Summary

PRE JOB SAFETY MTG PULL OUT OF HOLE WITH RETRIEVING HEAD & 2 3/8 " TUBING RIG UP BLUE JET WIRELINE, RUN CBL. RUN ECHO LOG E-MAIL LOGS TO ENGINEER WAIT ON ORDERS. RIG DOWN RELEASE BLUE JET. STAND BY WHILE ENGINEER TALKED WITH OCD STEVE HADEN CONFIRMED GAS IN INTERMEDIATE WAS FROM LEWIS SHELL, CHARLIE PERRIN NOTED THAT THEIR WAS NO INDICATION OF ZONE TO ZONE COMMUNICATION AND THAT NO REMEDIAL WORK WAS REQIRED, SHUT IN AND SECURE WELL FOR NIGHT.

05/10/2005 07:00 - 05/10/2005 17:00

Last 24hr Summary

PRE JOB SAFETY MEETING. MAKE UP RETRIEVING HEAD, RUN IN HOLE TO 5000'. UNLOAD HOLE WITH AIR COMP. LATCH ONTO BRIDGE PLUG, OPEN BYPASS, LET WELL EQULISE, UNSET PLUG , POOH LAY DOWN BRIDGE PLUG. GO IN HOLE WITH EXP CHECK, F-NIPPLE & 2-3/8" TBG, DRIFT TBG WHILE GOING IN HOLE, LAY DOWN BAD JTS, CHANGE OUT BAD TBG COLLARS. SHUT IN SECURE WELL FOR NIGHT.

05/11/2005 07:00 - 05/11/2005 08:00

Last 24hr Summary

PRE JOB SAFETY MEETING WAIT ON TBG TO BE DELIVERED. PICK UP 12 JTS NEW TBG, RUN IN HOLE, PICK UP TBG, TAG FILL AT 5890', CLEAN OUT TO 5940' WITH AIR/MIST, CIRCULATE WELL CLEAN ON BOTTOM. LAY DOWN EXTRA TBG, LAND TBG WITH F-NIPPLE AT 5694', EXP CHECK AT 5695', NIPPLE DOWN BOP BEGIN TO INSTALL WELL HEAD AND NOTICED THAT API RING WOULD NOT FIT IN RING GROOVE ON TOP OF TUBING HANGER, WAIT ON WELL HEAD SERVICE HAND, INSPECTED WELL HEAD, RING GROOVE NOT CUT RIGHT ON NEW TUBING HANGER, SHUT IN SECURE WELL FOR NIGHT.