Form 3160-5 (August 1999)

# **UNITED STATES**

DEPARTMENT OF THE INTERIOR JUN 23

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

FARMINGTON FIELD OFFICE

Sm

BY

Lease Serial No. NMSF078908

If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an CEIVED

abandoned well. Use Form 3160-3 (APD) for such proposals MINGTON

apangoneg w	/eii. Use Foffii 3160-3 (AF	D) for such propos	also wing for the		
	IPLICATE - Other instr	uctions on revers	e side	7. If Unit or	CA/Agreement, Name and/or No.
<ol> <li>Type of Well</li> <li>☐ Oil Well</li> <li>☑ Gas Well</li> </ol>	Other	A COL	(1202003)	8. Well Nam	ne and No.
2. Name of Operator			D. 11 3 03	Lindrith B	Unit #103
ConocoPhillips Co.			- 20 - S	9. API Well 30-039-25	
3a. Address P.O. Box 2197, WL3-6081 Houston Tx 77252  3b. Phone No. (include area tode) (832)486-2463  4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				10. Field and	Pool, or Exploratory Area allup-Dakota, West
Sec 18 T24N R2W NENE	330FNL 330FWL	(on)	Stell Styll Bar	11. County o Río Arriba NM	r Parish, State
12. CHECK AF	PPROPRIATE BOX(ES) 7	TO INDICATE NAT	URE OF NOTICE, R	EPORT, OR	OTHER DATA
TYPE OF SUBMISSION		7	YPE OF ACTION		
☐ Notice of Intent	☐ Acidize ☐ Alter Casing	☐ Deepen ☐ Fracture Treat	☐ Production (Star	t/ Resume)	☐ Water Shut-Off ☐ Well Integrity
X Subsequent Report	Casing Repair	New Construction	_ *		Other Pumping Unit
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	☐ Plug and Abandor☐ Plug Back	☐ Temporarily Aba	andon	& Tubing Change
	nal Abandonment Notices shall by for final inspection.)	e filed only after all requi	rements, including reclama	ation, have been	•
14. I hereby certify that the foregon Name (Printed/Typed)	ing is true and correct	Title	<del></del>		
Christina Gustartis			ulatory Analyst		r
Signature Chuic S	Instartie	Date 06/2	2/2005		
	THIS SPACE	FOR FEDERAL OR	STATE OFFICE USE	AO	CEPTED FOR RECORD
Approved by			Title	Da	ate JUN 2 9 2005

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. MMOCD

Office

Conditions of approval, if any, are attached. Approval of this notice does not warrant or

certify that the applicant holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon.

## ConocoPhillips

### Regulatory Summary

### **LINDRITH B UNIT 103**

<Type?>, 06/07/2005 00:00

E/W Dist (ft) State/Province N/S Dist (ft) N/S Ref E/W Ref API/Bottom UWI Surface Legal Location County 300392572200 RIO ARRIBA **NEW MEXICO** NMPM-24N-2W-18-D 330.00 330.00 W Ground Elevation (ft) Latitude (DMS) Longitude (DMS) Spud Date Rig Release Date 36° 19' 1.056" N 107° 5' 51" W 7,112.00 03/04/1998

#### 06/07/2005 07:30 - 06/07/2005 17:30

#### Last 24hr Summary

Key safety meeting, Location safety meeting. Rig down all equipment. Clean out rig pit. Move to location and rig up and spot in equipment. Secure location and shut down.

#### 06/08/2005 07:30 - 06/08/2005 17:30

#### Last 24hr Summary

Safety meeting. Rig over to pull rods. Unhang the well & remove horse head. Pull up on rods, never did see pump unseat and can not stack out. Rods have a lot of parefin on the rods. Pull out with rods before pumping hot fluid to see if we have the pump. The 299th rod was parted. Pulled 105 7/8 rods and 194 3/4. NU fishing tool and run and get on fish. Load & test tbg. to 500#. Good test. Try to unseat pump. Secure location and shut down.

#### 06/09/2005 07:30 - 06/09/2005 17:30

#### Last 24hr Summary

Safety meeting. Try to unseat pump. Could not work pump free. Rig up floor and tongs. Back off rods. Wait on safety trailer to lay rods down. Pull out laying down rods. Pulled 100 7/8 and 77 3/4 rods. Secure location and shut down.

#### 06/10/2005 07:30 - 06/10/2005 17:00

#### Last 24hr Summary

Safety meeting. Rig up floor. ND well head. Install nipple and back pressure valve. Stop work and stay in safe area while pumping unit beam is being removed. ND well head and nu bop. Test bop. Rig up blue jet, run in and punch 4 holes in tbg. @ 4610' - 4612'. Rig down blue jet. Pull out with 2 7/8 tbg. to 4610'. Run back one stand. Secure location and shut down.

#### 06/13/2005 07:30 - 06/13/2005 17:30

#### Last 24hr Summary

Safety meeting. Pull out laying down 121 3/4 rods and 4 k bars. Pull rod on pump broke. Rig up to swab fluid in tbg. Swab tbg. down and rig down swab. Tally out with tbg. Nu 2 7/8 tail jt. is swedged down to 1 1/2" with 1.1/2" notch collar on bottom (Total length 33.59'), .80 X 2.25 F - nipple, 3 jts. of 2 7/8 tbg., 2.75' tbg. anchor and 238jts. of 2 7/8 tbg. Secure location and shut down.

#### 06/14/2005 07:30 - 06/14/2005 17:30

#### Last 24hr Summary

Safety meeting. Switch out safety trailers with rods. Pick up 4 jts. of tbg. one 10', one 4' pup jts., set anchor with 10 pts. tension and land tubing @ 7817.16' KB. (Note this is where tbg. was landed) Rig down floor and bop, nu well head. Hot oil down tbg. Rig up floor and rig over to run rods. Run in with 2 1/2 X 1 1/4 X 20' RHAC pump with 1" X 12" dip tube, 4 - 1 1/2" sinker bars, 170 new 3/4" T-54 rods. Shut down and move to safe area while Weatherford Installs beam on pumping unit. Secure location and shut down.

#### 06/15/2005 07:30 - 06/15/2005 15:30

#### Last 24hr Summary

Safety meeting. Run in with the rest of 3/4 rods (196 total) and 110 7/8 rods. Rig down floor, space out, hang head on and hang the well on. Load and test tbg. to 500 #. Long stroke pump and test to 500 #. Good tests. Rig down rig and equipment. Move to next location.