Form 3160-5 UNITED STATE (August 2007) DEPARTMENT OF THE BUREAU OF LAND MAN		INTERIOR	5 Lease Serial 1	FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010		
		J. Lease Schart	NMSF-078387			
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an				ottee or Tribe Nar	me	
	l well. Use Form 3160-3 (A					
	UBMIT IN TRIPLICATE - Other ins	tructions on page 2.	7. If Unit of CA	/Agreement, Nar	ne and/or No.	
1. Type of Well						
Oil Well X Gas Well Other			8. Well Name a	8. Well Name and No. Howell D 4		
2. Name of Operator	<u> </u>		9. API Well No.			
Burlington Resources Oil & Gas		Company LP           3b. Phone No. (include area cod)	e) 10 Field and Po	<b>30-045-10139</b> Pool or Exploratory Area		
PO Box 4289, Farmington, NM 87499		(505) 326-9700				
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)         Surface       Unit G (SWNE), 1650' FNL & 1650'		FEL, Sec. 33, T31N, R8		11. Country or Parish, State San Juan , New Mexico		
12. CHECK	THE APPROPRIATE BOX(ES)	TO INDICATE NATURE C	DF NOTICE, REPOR		R DATA	
TYPE OF SUBMISSION	, <u>, , , , , , , , , , , , , , , </u>		F ACTION			
Notice of Intent	Acidize	Deepen	Production (Start/I	Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation		Well Integrity	
X Subsequent Report	Casing Repair	New Construction	Recomplete	[	Other	
B	Change Plans	X Plug and Abandon	Temporarily Aban	don		
Final Abandonment Notice 13. Describe Proposed or Completed O	Convert to Injection	Plug Back	Water Disposal			
Testing has been completed. Fina determined that the site is ready for 11/17/12 Notified Jim L 3194' to 3044'. Verbal a 11/20/12 Notified Bran- approval rec'vd. 11/21/12 Notified Bran- permission to perf @ 2 rec'vd. The subject well was P	ovato/BLM & Brandon Po approval rec'vd. don Powell/OCD (M.Gilbre don Powell/OCD (M.Gilbre 15', 50' above shoe, and p &A'd on 11/26/12 per the r	only after all requirements, includi well/OCD of plug chan oth/BLM onsite). Reque oth/BLM onsite). Pressu ump cmt. If doesn't wo notifications above and	ng reclamation, have bee ge. Requested pe st permission to red up, held, car rk will use 1″ and	ermission to combine Pl n't pump thr d fill up w/ci RC	the operator has o run inside plug from ugs 6&7. Verbal rough. Requested	
14. I hereby certify that the foregoing is	s true and correct. Name (Printed/Type					
Dollie L. Busse Title Staff Regulat				an		
Signature	1 Buse	Date 12	119/12		The second se	
	THIS SPACE FO	R FEDERAL OR STAT	E OFFICE USE	AMER	INTERNAL	
Approved by	·	Title	e	DE		
Conditions of approval, if any, are attact that the applicant holds legal or equitabe entitle the applicant to conduct operation	ble title to those rights in the subject lea	ise which would Offi		P.Y.		
Title 18 U.S.C. Section 1001 and Title false, fictitious or fraudulent statements			villfully to make to any de	partment or agen	acy of the United States any	
(Instruction on page 2)		MMUCH A				

-

¢

NMUCH
-------

.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 \*fax: 505-325-1211

# Burlington Resources Howell D #4

November 27, 2012 Page 1 of 2

1650' FNL and 1650' FEL, Section 33, T-31-N, R-8-W San Juan County, NM Lease Number: NMSF-078387 API #30-045-10139

Plug and Abandonment Report

Notified NMOCD and BLM on 11/12/12

### Plug and Abandonment Summary:

**Plug #1** with 40 sxs (47.2 cf) Class B cement inside casing from 5278' to 4751' to cover the Mesaverde top and intermediate casing shoe.

- Plug #2 with 20 sxs (23.6 cf) Class B cement with 2% CaCl inside casing from 3935' to 3672' to coverthe Chacra top.
- Plug #3 with 20 sxs (23.6 cf) Class B cement inside casing from 3210' to 2947' to cover the Pictured Cliffs top.
- Plug #4 with 24 sxs (28.32 cf) Class B cement inside casing from 2963' to 2647' to cover the Fruitland top.
- Plug #5 with 135 sxs (159.3 cf) Class B cement inside casing from 2151' to 1768', squeeze 72 sxs outside, 33 sxs in 4.5" x 7", 4 sxs below, 26 sxs on top of CR to cover the Kirtland and Ojo Alamo tops.
- Plug #5a with 64 sxs (75.52 cf) Class B cement inside casing from 2110' to 1267' to cover the Kirtland and Ojo Alamo tops.
- Plug #6 (combined #6 & #7) with 117 sxs (138.06 cf) Class B cement inside casing from 693' to surface to cover the Nacimiento and surface casing shoe.
- **Plug #8** with 72 sxs Class B cement found cement in 4.5" full, down 30' in 4.5" x 7" casing 30' and 6' down annulus and install P&A marker.

## **Plugging Work Details:**

- 11/13/12 Road rig and equipment to location. RU. Check well pressures: tubing 165 PSI, casing 105 PSI and bradenhead 0 PSI. Dig out intermediate valve. X-over to rod tools. Blow down well. PU on rods. Unseat pump. LD 1 polish rod, 1-4, 1-6' 1-8 ¼ pony rod 110 ¼ guided rods 103 ¼ plain rods, 1-3/4 guided rod, 1- sinker bar and 1 pump. ND wellhead. NU BOP. SI well. SDFD.
- 11/14/12 Check well pressures: tubing 160 PSI, casing 160 PSI and bradenhead 0 PSI. Pressure test BOP to 300 PSI. Pump 20 bbls of fresh water down tubing to kill well. PU on tubing, LD hanger. POH and tally 85 stands, LD 2 joints, SN 1-10', 1-6' sub, 1-6' perf sub, 1 joint. Total tally 173 joints 2-3/8" EUE tubing (5421'). PU 1-4.5" A-Plus watermelon mill, 1 stand, 1-4' marker joint. TIH with 84 stands to 5330'. POH and LD tubing with mill. PU 4.5" Select Tool CR TIH and set at 5278'. Attempt to pressure test tubing, no test. Circulate well clean. Attempt to pressure test casing, pipe ram rubber leaking. SI well. SDFD.
- 11/15/12 Open up well; no pressures. TIH and LD setting tool. Pressure test casing to 800 PSI. Bled down to 100 PSI. Attempt 3 to 4 times. Change out pipe ram rubber. PU tubing hanger. Pressure test spool and pipe rams to 300 PSI, OK. RU Basin Wireline. Ran CBL from 5278' to surface. Found cement from 5278' to 3120'. No cement from 3120' to 1520'. Pressure test tubing to 1000 PSI, OK. SI well. SDFD.

# A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 \*fax: 505-325-1211

Burlington Resources
Howell D #4

November 27, 2012 Page 2 of 2

### Plugging Work Details (continued):

- 11/16/12 Open up well; no pressures. Pressure test tubing while TIH. Found hole in tubing change out. Pressure test tubing to 1000 PSI, OK. TIH. RU fishing tools. RIH and pull standing valve. RD fishing tool. Wait on orders. M. Gilbreath, BLM, B. Powell, NMOCD and J. Yates, COPC approved procedure change. Spot plug #1 with estimated TOC at 4751'. SI well. WOC. SDFD.
- 11/17/12. Open up well; no pressures. TIH. Tag top of cement at 4730'. PUH. Attempt to pressure test casing, small leak. Spot plug #2 with estimated TOC at 3672'. SI well and WOC. TIH and tag cement at 3615'. PUH. Spot plug #3 with estimated TOC at 2947'. SI well. WOC. SDFD.
- 11/19/12 Open up well; no pressures. TIH and tag cement at 2963'. LD tubing to 2837'. Pressure test casing, small leak. Perforate 3 HSC holes at 2867'. Attempt to establish rate, leak. Pressured up to 1000 PSI 2 times, same leak. Wait on orders. B. Powell, NMOCD and M. Gilbreath, BLM approved procedure change. Spot plug #4 with estimated TOC at 2647'. SI well. WOC. SDFD.
- 11/20/12 Open up well; no pressures. TIH and tag top of cement at 2660'. LD tubing to 2075'. Attempt pressure test, same small leak. Perforated 3 HSC holes at 2151'. Establish rate thru squeeze holes at 1 bpm at 800 PSI. PU 1 Select Tool 4.5" CR set at 2110'. TIH tubing started blowing, pump 30 bbls fresh water and establish circulation out casing. Establish rate at 1 bpm at 500 PSI. Spot plug #5 with estimated TOC at 1768'. Note: Had pressure at 100 PSI on 4.5" casing. Pressured up to 600#. PU tubing to top of CR and circulate casing clean. Casing continued blowing gas. Circulate well clean. Spot plug #5a with estimated TOC at 1267'. SI well. SDFD.
- 11/21/12 Open up well; no pressures. Pressure test casing to 800 PSI, no test leak. B. Powell, NMOCD and J. Yates, COPC approved procedure change. Perforate 3 HSC holes at 314'. Attempt to establish circulation out bradenhead. Pressure up to 1000 PSI. Pump fresh water down casing and bradenhead pressure up to 300 PSI, held. B.Powell, NMOCD and J.Yates, COPC approved procedure change. Perforate 3 HSC holes at 214'. Establish circulation. TIH to 693'. Spot plug #6 with TOC at surface. Circulated good cement out casing and bradenhead. LD all tubing. Squeeze 12 sxs and SI well with 500# pressure. SDFD.
- 11/26/12 Attempt to check pressure, valves cemented up. Remove valve slowly, no pressure. Attempt to pull tubing hanger, cemented up. Dig out wellhead. Wait on backhoe. Found cement at 4' deep. Monitor wellhead. Cut off wellhead. Found cement in 4.5" full, down 30' in 4.5" x 7" casing 30' and 6' down annulus. Spot plug #8 and install P&A marker. SDFD.

11/27/12 Travel to location. RD & MOL.

Jim Yates, COPC representative, was on location. Mike Gilbreath, BLM representative, was on location.