Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB No. 1004-0137

BUREAU OF LAND MANAGEMENT Expires: July 31, 2010 Lease Serial No. Farmington Field () ffice SF-078385-A SUNDRY NOTICES AND REPORTS ON WELPS Land Mana Grafilidian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well Oil Well X Gas Well Other 8. Well Name and No. Howell L 1 2. Name of Operator 9. API Well No. **Burlington Resources Oil & Gas Company LP** 30-045-09277 10. Field and Pool or Exploratory Area 3a. Address 3b. Phone No. (include area code) PO Box 4289, Farmington, NM 87499 (505) 326-9700 Blanco Mesaverde 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. Country or Parish, State Surface Unit N (SESW), 990' FSL & 1650' FWL, Sec. 23, T30N, R8W San Juan **New Mexico** 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Alter Casing Fracture Treat Reclamation Well Integrity X Subsequent Report Casing Repair New Construction Recomplete Other Change Plans Plug and Abandon Temporarily Abandon Plug Back Final Abandonment Notice Convert to Injection Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has

The subject well was P&A'd on 4/4/13 per the attached report.

determined that the site is ready for final inspection.)

RCVD MAY 9 '13 **NTL CONS. DIV.**

DIST. 3

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)	T		· · · · · · · · · · · · · · · · · · ·
Dollie L. Busse	Title	Staff Regulatory Technician	n
Signature Mile Bersse	Date	5/3/13	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE		MARTIN ROAD	
Approved by		Tid	MAY 0 6 2013
Conditions of approval, if any, are attached. Approval of this notice does not warrant of	or certify	Title	PAPANKGION FIELD OFFICE
that the applicant holds legal or equitable title to those rights in the subject lease which entitle the applicant to conduct operations thereon.		Office	THE ST.
Title 19 H.C.C. Section 1001 and Title 42 H.C.C. Section 1212 make it a mine for an		and all and millfullers and a second	

itle 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources
Howell L 1

April 4, 2013 Page 1 of 2

990' FSL and 1650' FWL, Section 23, T-30-N, R-8-W San Juan County, NM Lease Number: SF-078385A API #30-045-09277

Plug and Abandonment Report Notified NMOCD and BLM on 3/26/13

Plug and Abandonment Summary:

- Plug #1 with CR at 4700' spot 22 sxs (25.96 cf) Class B cement inside casing from 4700' to 4410' to cover the Mesaverde top.
- Plug #2 with 12 sxs (14.16 cf) Class B cement inside casing from 3711' to 3553' to cover the Chacra top.
- Plug #3 with 17 sxs (20.06 cf) Class B cement inside casing from 3064' to 2840' to cover the Pictured Cliffs top.
- Plug #4 with 36 sxs (20.06 cf) Class B cement inside casing from 2725' to 2501' to cover the Fruitland top.
- Plug #5 with 27 sxs (31.86 cf) Class B cement inside casing from 2079' to 1724' to cover the Ojo

 Alamo-and-Kirtland-tops.
- Plug #6 with CR at 598' spot 55 sxs (64.9 cf) Class B cement inside casing from 650' to 474' 11 sxs above, 4 sxs below and 40 sxs outside SI with 500 PSI to cover the Nacimiento top.
- **Plug #7** with 93 sxs (109.74 cf) Class B cement inside casing from 375' to surface to cover the surface casing shoe.
- Plug #8 with 50 sxs Class B cement found cement in 4.5" casing and 9-5/8" x 7" annulus at surface, down 10' in 4.5" x 7" annulus and install P&A marker.

Plugging Work Details:

- 3/26/13 Rode rig and equipment to location. Spot in rig and equipment. Check well pressures: casing 500 PSI, tubing 7 PSI, 7" IMM 350 PSI and bradenhead 0 PSI. Bradenhead valve is about 4' down with gate valve open. RU. SI well. SDFD.
- 3/27/13 Check well pressures: tubing 7 PSI, casing 500 PSI and bradenhead 0 PSI. RU relief lines and blow down well. ND wellhead. NU BOP and function test. Test pipe rams 500 PSI low and 1000 PSI on high. Tally and TOH with 2-3/8" tubing EUE 8 rod, 152 joints, LD 21 joints with total of 173 joints on location (1 joint, 6' pup, 171 joints, 2' pup, 1 joint, F-nipple, exp check), total tally 5340'. TIH with 4.5" string mill to 4733'. LD 1 joint. TOH with 152 joints. LD string mill. TIH with 4.5" DHS CR and set at 4700'. Pressure test tubing to 1000 PSI, OK. Establish circulation and circulate well clean. Pressure test casing to 800 PSI, OK. TOH and LD setting tool. SI well. SDFD.
- 3/28/13 Open up well; no pressures. RU Basin Wireline. Ran CBL from 4700' to TOC at 3840', falls out to 3010'. Good bond to surface. TIH open-ended to 4700'. Establish circulation. Spot plug #1 with estimated TOC at 4410'. LD 32 joints. SI well. SDFD.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211.

Burlington Resources
Howell L 1

April 4, 2013 Page 2 of 2

Plugging Work Details (continued):

- Check well pressures: tubing, casing and bradenhead 0 PSI and 7" IMM 100 PSI. RU relief lines. Spot plugs #2, #3, #4 and #5. Open up 4.5" casing x 7" casing and monitor pressure. Wait on orders. Check well pressures: IMM 21 PSI and bradenhead 0 PSI. Open up IMM to pit. SI well. SDFD.
- 4/2/13 Check well pressures: tubing, casing and bradenhead 0 PSI and 7" IMM 92 PSI. RU relief lines. Note: V. Montoya, MVCI, B. Powell, NMOCD and W. Weatherford, BLM approved perf at 650'. Perforate 3 HSC squeeze holes (SQH) at 650'. Establish rate of 1.5 bpm at 2000 PSI. Pressure dropped to 750 PSI and lost 100 PSI per minute. TIH with DHS CR and set at 598'. Establish circulation. Spot plug #6 with estimated TOC at 474'. Reverse circulation with 10 bbls. SI well. SDFD.
- 4/3/13 Check well pressures: tubing, casing and bradenhead 0 PSI and 7" IMM 2 PSI. RU relief lines. Note: S. Mason, BLM, C. Perrin, NMOCD approved procedure change. Perforate 3 HSC squeeze holes (SQH) at 319'. Establish circulation. Spot plug #7 with estimated TOC at surface. Top off casing with 2 sxs and SI in bradenhead. Pressured up to 350 PSI. SI well. WOC overnight. Dig out wellhead with backhoe. SDFD.
- 4/4/13 Open up well; no pressures. High Desert filled out Hot Work Permit and cut off wellhead. Found cement 4.5" casing and 9-5/8" x 7" annulus at surface, down 10' in 4.5" x 7" annulus. Spot plug #8 and install P&A marker. RD & MOL.

Wanda Weatherford, BLM representative, was on location. Vic Montoya, MVCI representative, was on location.