Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

5. Lease Serial No.

_	_	^	 	•	
		.11			C

				31-0777	JU	
Do not use	DRY NOTICES AND REPO this form for proposals t well. Use Form 3160-3 (A	o drill or to re-enter an		ee or Tribe Name		
	BMIT IN TRIPLICATE - Other inst				3.1	
1. Type of Well	BINIT IN TRIPLICATE - Other Inst		منابست	greement, Name and/o	or No.	
Oil Well	Gas Well Other	FEB 24 20		No. Sunray I	—————————————————————————————————————	
2. Name of Operator		- William Eige	9. API Well No.	- Juniay .		
Burling	ton Resources Oil & Gas	Company LPand No.		30-045-208	353	
3a. Address		3b. Phone No. (include area code	10. Field and Pool	or Exploratory Area		
PO Box 4289, Farmingto		(505) 326-9700		Blanco PC		
4. Location of Well (Footage, Sec., T., R.	,M., or Survey Description)	_	11. Country or Par	rish, State		
	WNE), 1500' FNL & 1840' F	FEL, Sec. 9, T30N, R10\			ew Mexico	
12. CHECK T	HE APPROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, REPORT	OR OTHER DAT	A	
TYPE OF SUBMISSION		TYPE OF AC				
Notice of Intent	Acidize	Deepen	Production (Start/Re	sume) W	ater Shut-Off	
	Alter Casing	Fracture Treat	Reclamation	⊢⊓w	ell Integrity	
X Subsequent Report	Casing Repair	New Construction	Recomplete	=	ther	
BP	Change Plans	X Plug and Abandon	Temporarily Abando	on .		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	_		
Attach the bond under which the war following completion of the involve	nally or recomplete horizontally, give ork will be performed or provide the E ed operations. If the operation results Abandonment Notices must be filed o	subsurface locations and measure Bond No. on file with BLM/BIA. I in a multiple completion or recom	d and true vertical depths o Required subsequent report pletion in a new interval, a	of all pertinent markers ts must be filed within a Form 3160-4 must be	s and zones. 30 days c filed once	
surface plug. Will Run T	s for Perfs on plug 3 to be a Tbg & do inside to surface & w/ OCD and got a verbal ap	then 150' to surface. Da				
				RCUD FF	B 27 '14	
		t ·		OIL CON		
The subject well was P8	&A'd on 2/5/14 per the attac	hed report.		DIST		

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)		
Kenny Davis	Title Staff Regulatory Tech	nician
Signature	Date	2/24/2014
THIS SPACE FOR FE	DERAL OR STATE OFFICE USI	ACCEPTED FOR RECEIVED
Approved by	Title	EB 2 6 2014
Conditions of approval, if any, are attached. Approval of this notice does not warrant that the applicant holds legal or equitable title to those rights in the subject lease white entitle the applicant to conduct operations thereon.		Farmington field office By:

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources
Sunray E #4

February 5, 2014 Page 1 of 2

1500' FNL and 1840' FEL, Section 9, T-30-N, R-10-W San Juan County, NM Lease Number: SF-077730 API #30-045-20853

Plug and Abandonment Report Notified NMOCD and BLM on 1/29/14

Plug and Abandonment Summary:

- Plug #1 with CIBP at 3032' spot 18 sxs (21.24 cf) Class B cement inside casing from 3032' to 2379' to cover the Pictured Cliffs and Fruitland tops. Tag TOC at 2493'.
- Plug #2 with 10 sxs (11.8 cf) Class B cement inside casing from 1888' to 1525' to cover the Kirtland and Ojo Alamo tops.
- Plug #3 with 77 sxs (90.86 cf) Class B cement inside with 10 sxs inside 2-7/8" casing, 57 sxs outside casing and 10 sxs good cement circulate to pit from 358' to surface, LD11 jnts tubing. RD floor and ND BOP. PU pump to 2-7/8" master valve mix and pump 24 sxs with cement returns out bradenhead valve shut in bradenhead valve with shut in pressure at 300 PSI.
- Plug #4 with 25 sxs Class B cement top off casings and weld on P&A marker.

Plugging Work Details:

- 1/30/14 Rode rig and equipment to location. Spot in and RU. RU relief lines. Check well pressures: casing 350 PSI and bradenhead 0 PSI. NU BOP and function test. X-over pipe ram to 1-1/4". SI well. SDFD.
- 1/31/14 Bump test H2S equipment. Check well pressures: casing 350 PSI and bradenhead 0 PSI. RU relief lines and blow well down. Pump 10 bbls of water down casing to kill well. RU wireline. RIH with 2.25" GR to 3050'. RIH with CIBP and set at 3032'. PU and tally 93 jnts 1-1/4" IJ 2.3# A- Plus workstring and tag CIBP. Establish circulation. Circulate well clean. Attempt to pressure test casing to 800 PSI, drop 100 PSI per minute, no test. Bleed off pressure. LD 5 jnts tubing to 2865' to displace fluid from wellhead. SI well. SDFD due to high winds.
- 2/3/14 Bump test H2S equipment. Open up well; no pressures. TOH with 88 jnts 1-1/4" IJ 2.33# tubing. RU pump to 2-7/8" 6.4# casing and load with 3.5 bbls of water. RU Blue Jet wireline. Ran CBL from 3028' to surface, calculated TOC at 160'. RD wireline. TIH open-ended to 3032'. Establish circulation pit casing. Spot plug #1 with calculated TOC at 2379'. WOC. SI well. SDFD.
- Open up well; no pressures. Bump test H2S equipment. TIH open-ended and tag plug #1 at 2493'. Pressure test casing to 800 PSI, OK. Spot plug #2 with calculated TOC at 1525'. LD all tubing. Perforate 4 1-11/16" bi-wire holes at 150'. Establish circulation. Circulate well clean. Estimated rate of 4 bpm at 0 PSI. TIH open-ended to 358'. Spot plug #3 with 77 sxs (90.86 cf) Class B cement inside with 10 sxs inside 2-7/8" casing, 57 sxs outside casing and 10 sxs good cement circulate to pit from 358' to surface, LD11 jnts tubing. RD floor and ND BOP. PU pump to 2-7/8" master valve mix and pump 24 sxs with cement returns out bradenhead valve shut in bradenhead valve with shut in pressure at 300 PSI. WOC overnight. SI well. SDFD.

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Burlington Resources
Sunray E #4

February 5, 2014 Page 2 of 2

Plugging Work Details (continued):

2/5/14 Open up well; no pressures. Monitor well. Fill out Hot Work Permit. Dig out wellhead with air hammer. Cut off wellhead. Remove wellhead. Top off casings. Spot plug #4 and weld on P&A marker. RD and MOL in the AM.

Josh Jacobs, COPC representative, was on location. Darren Halliburton, BLM representative, was on location.