		· ·							
Form 3160-5	res			FORM APPROVED					
(August 2007)		RIOR		OMB No. 1004-0137					
	NAGEMENT			Expires: July 31, 2010					
						SF-078999			
	SUNDRY NOTICES AND REP			а в 3 ^т	OMB No. 1004-0137 Expires: July 31, 2010 5. Lease Serial No. SF-078999 6/If Indian, Allottee or Tribe Name 7. Highin of CA/Agreement, Name and/or No. San Juan 31-6 Unit 8. Well Name and No. Sologo-30718 10. Field and Pool or Exploratory Area Rosa PC 11. Country or Parish, State Rio Arriba New Mexico TICE, REPORT OR OTHER DATA TION roduction (Start/Resume) Water Shut-Off teclamation Well Integrity tecomplete Other Well Integrity Other remporarily Abandon Vater Disposal my proposed work and approximate duration thereof. ue vertical depths of all pertinent markers and zones. ed subsequent reports must be filed within 30 days in a new interval, a Form 3160-4 must be filed once amation, have been completed and the operator has report. RECORD				
						News and/a Ne			
1. Type of Well		••••							
Oil Well	X Gas Well Other								
		N(V 05 201	4		uan 31-6 Unit 101			
2. Name of Operator	HE INTERIOR (ANAGEMENT OMB No. 1004-0137 (Expires: July 31, 2010 St. Lense Serial No. SF-078999 St. dorill or to re-eintenan St. Unsee Serial No. St. dorill or to re-eintenan St. Unsee Serial No. St. dorill or to re-eintenan St. Unsee Serial No. St. dorill or to re-eintenan St. Unsee Serial No. St. dorill or to re-eintenan St. Unsee Serial No. St. dorill or to re-eintenan St. Unsee Serial No. St. dorill or to re-eintenan St. Unsee Serial No. St. dorill or to re-eintenan St. Unsee Serial No. OIL CONS. DIV DIST. 3 St. Unsee Serial No. St. dorill or to re-eintenan St. Unsee Serial No. Div Fonce No. (melude area code) 10. Field and Pool or Exploratory Area St. DO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF ACTION Beepen Production (Start/Resume) Water Shut-Off Well made abandon Production (Start/Resume) Water Shut-Off Breachmainted starting date of three world offsho of all period markers and zones, tate is an unside consolito and measured and true world offsho of all period markers and zones, tate is an unside consolito and measured and true world offsho of all period markers and zones, tate is an unside consolito and measured and true world offsho of all period markers and		•						
3a. Address		No. (include area	a code)						
PO Box 4289, Farn	ington, NM 87499					•			
4. Location of Well (Footage, Se									
Surface UL [): (NVVNVV), 900' FNL & 1170'	FWL, Sec	. 35, 131N,	K6W	Rio Arriba	, New Mexico			
	ECK THE APPROPRIATE BOX(E)		CATE NATUE						
TYPE OF SUBMISSIO			·						
		<u> </u>							
Notice of Intent	Acidize				. ,				
X Subsequent Report	Casing Repair								
Jabsequent Report	Change Plans				•				
Final Abandonment Noti						· · · · · · · · · · · · · · · · · · ·			
13. Describe Proposed or Comple	ted Operation: Clearly state all pertinent d	letails, includir	ng estimated start	ting date of a	ny proposed work and approx	simate duration thereof.			
Testing has been completed determined that the site is re	. Final Abandonment Notices must be filed eady for final inspection.)	d only after all	requirements, in	cluding recla	amation, have been completed				
	CCEPTED FOR RECORD								
			NA	N 13 3	2014				
			-						
			OY:	PORCH					
			0 · 1						
14. I hereby certify that the fore	going is true and correct. Name (Printed/T	"yped)	<u></u>						
Karana Davia			Title Stat	ff Regula	tory Technician				
Kenny Davis				II Regula	tory reclinician				
X	en la				10/21/20	14			
Signature									
	THIS SPACE F	FOR FEDE	RAL OR ST	TATE OF	FICE USE				
Approved by									
		•		Title		Date			
Conditions of approval, if any, a	re attached. Approval of this notice does not	ot warrant or c	ertify						
	equitable title to those rights in the subject	lease which w	ould	Office					
entitle the applicant to conduct of Title 18 U.S.C. Section 1001 and		rime for any n	erson knowingly	and willfully	v to make to any department of	r agency of the United States any			
	ements or representations as to any matter								
(Instruction on page 2)		IVI	NUUNA	/					

ï

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Conoco Phillips San Juan 31-6 Unit 101

October 9, 2014 Page 1 of 1

900' FNL and 1170' FWL, Section 35, T-31-N, R-6-W Rio Arriba County, NM Lease Number: SF-078999 API #30-039-30718

Plug and Abandonment Summary:

Plug and Abandonment Report Notified NMOCD and BLM on 10/3/14

- Plug #1 with CR at 3300' spot 37 sxs (43.66 cf) Class B cement inside casing from 3300' to 2813' to cover the Pictured Cliffs and Fruitland top.
- **Plug #2** with 23 sxs (27.14 cf) Class B cement inside casing from 2694' to 2391' to cover the Kirtland and Ojo Alamo tops.
- Plug #3 with 12 sxs (14.16 cf) Class B cement inside casing from 1281' to 1123' to cover the Nacimiento top.
- **Plug #4** with 36 sxs (42.48 cf) Class B cement inside casing from 287' to surface to cover surface casing shoe. Tag TOC at 10'.
- **Plug #5** with 34 sxs Class B cement top off casings and install P&A marker with coordinates N 36° 51.655'/W 107° 26.233'.

Plugging Work Details:

- 10/6/14 Rode rig and equipment to location. Spot in and RU. Open up well; no pressures. RU relief lines. TOH and LD 128 ¾" rods, 2-8' pony, 6 sinker bars, 8' guided pony and rod pump. SI well. SDFD.
- 10/7/14 Bump test H2S equipment. Check well pressures: tubing-0-PSI, casing-30-PSI and bradenhead TSTM. RU relief lines. Blow well down. ND wellhead. RU Cameron pressure equipment. NU kill spool and BOP. Pressure test BOP, blinds, 2-3/8" pipe rams to 300 PSI and 1300 PSI, OK. Pull tubing hanger. TOH and tally 1 jnt 8', 53 stds, 1 jnt, SN MA 2-3/8" tubing total 3414' EUE tubing (109 total jnts). PU 4-1/2" string mill to 3319'. PU 4-1/2" DHS CR and set at 3300'. Pressure test tubing to 1000 PSI, OK. Establish circulation. Pressure test casing to 800 PSI, OK. TOH and LD setting tool. SI well. SDFD.
- 10/8/14 Bump test H2S equipment. Open up well; no pressures. Function test BOP. RU A-Plus wireline. Ran CBL from 3300' to surface, found TOC at 40'. Establish circulation. Spot plugs #1, #2, #3 and #4. Dig out wellhead. SI well. SDFD.
- 10/9/14 Bump test H2S equipment. Open up well; no pressures. Tag TOC at 10'. ND BOP and kill spool. Finish dig out wellhead. RU High Desert. Cut off wellhead. Found cement down 2' in 4-1/2" casing and 6' in annulus. Spot plug #5 and top off casings and install P&A marker with coordinates N 36° 51.655'/W 107° 26.233'. RD and MOL.

Jim Morris, MVCI representative, was on location. Walter Gates, BLM representative, was on location.