

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

5. Lease Serial No.
NMSF077123

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

8. Well Name and No.
WARREN LS 10

9. API Well No.
30-045-20280-00-S1

10. Field and Pool, or Exploratory
AZTEC PICTURED CLIFFS

11. County or Parish, and State
SAN JUAN COUNTY, NM

1. Type of Well
 Oil Well Gas Well Other

2. Name of Operator
BP AMERICA PRODUCTION CO. Contact: TOYA COLVIN
E-Mail: Toya.Colvin@bp.com

3a. Address
200 ENERGY CT.
FARMINGTON, NM 87401

3b. Phone No. (include area code)
Ph: 281.366.7148

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Sec 13 T28N R9W SESE 1180FSL 0830FEL
36.658051 N Lat, 107.733185 W Lon

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

BP America Production Company respectfully requests to P&A the subject well.

Please see the attached procedure including the BLM required reclamation plan documents.

In accordance with NMOCD Pit Rule 19.15.17.9 NMAC, BP will use a closed-loop system during P&A operations.

**Notify NMOCD 24 hrs
prior to beginning
operations**

OIL CONS. DIV DIST. 3

AUG 28 2015

14. I hereby certify that the foregoing is true and correct.

**Electronic Submission #312921 verified by the BLM Well Information System
For BP AMERICA PRODUCTION CO., sent to the Farmington
Committed to AFMSS for processing by JACK SAVAGE on 08/26/2015 (15JWS0014SE)**

Name (Printed/Typed) TOYA COLVIN

Title REGULATORY ANALYST

Signature (Electronic Submission)

Date 08/17/2015

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By JACK SAVAGE

Title PETROLEUM ENGINEER

Date 08/26/2015

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Farmington

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

NMOCD

*KC
3*

PLUG AND ABANDONMENT PROCEDURE

August 17, 2015

Warren LS #10

Aztec Pictured Cliffs

1180' FSL, 830' FEL, Section 13, T28N, R9W, San Juan County, NM

API 30-045-20280 / Long _____ / Lat: _____

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.

1. Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary. ND wellhead and NU BOP. Function test BOP.

Note: Check with BP (Kirk Taylor – (970) 946-4407) in case of doubt about where to send any dismantled equipment off the well.

2. Rods: Yes _____, No X, Unknown _____.
Tubing: Yes _____, No X, Unknown _____, Size _____,
Packer: Yes _____, No X, Unknown _____, Type _____.

Note: No tubing in well. Will need 1-1/4" tubing workstring. RU A-Plus wireline truck. Round trip gauge ring to 2194' or as deep as possible.

Note: RU A-Plus Wireline truck and run CBL from 2194' to surface. This procedure is prepared with the understanding that it may be modified based on the TOC from the CBL.

3. **Plug #1 (Pictured Cliffs perforation, PC top and Fruitland top 2194' – 1860')**:
TIH and set 2-7/8" wireline CR at 2194'. TIH with tubing and tag CR. Pressure test tubing 500#. Load casing with water and circulate well clean. Pressure test casing to 500#. If the casing does not test, then spot or tag subsequent plugs as appropriate. Mix 10 sxs Class B cement and spot a balanced plug inside the casing above the CR to isolate the Pictured Cliffs interval and cover the Fruitland top. TOH with tubing.
4. **Plug #2 (Kirtland and Ojo Alamo tops, 1400' – 1110')**: Perforate 3 squeeze holes at 1400'. Set 2-7/8" wireline set cement retainer at 1350'. Mix 92 sxs Class B cement squeeze 83 sxs outside casing and leave 9 sxs inside casing to cover the Kirtland and Ojo Alamo tops. TOH and LD tubing.
5. **Plug #3 (Nacimiento and 8-5/8" surface casing shoe, 340' - Surface)**: Perforate 3 squeeze holes at 340'. Establish circulation out bradenhead with water and circulate the BH annulus clean. Mix approximately 120 sxs Class B cement and pump down the 2-7/8" casing to circulate good cement out bradenhead. Shut in well and WOC.
6. ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install above grade marker. Note: leave vent hole in casing/marker to avoid trapping any residual pressure in the casing. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM stipulations.

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
FARMINGTON DISTRICT OFFICE
6251 COLLEGE BLVD.
FARMINGTON, NEW MEXICO 87402

Attachment to notice of
Intention to Abandon:

Re: Permanent Abandonment
Well: Warren LS 10

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

Operator will run a CBL to verify cement top. Submit the electronic copy of the log for verification to the following addresses: tsalyers@blm.gov Brandon.Powell@state.nm.us

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.