

submitted in lieu of Form 3160-5

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
Sundry Notices and Reports on Wells

RECEIVED

JUN 30 PM 12:45

070 Farmington, NM

1. Type of Well  
Gas

2. Name of Operator  
Norman L. Gilbreath

3. Address & Phone No. of Operator  
P.O. Box 208, Aztec, NM 87410

Location of Well, Footage, Sec., T, R, M  
820' FSL and 1750' FEL, Sec. 7, T-29-N, R-12-W,

5. Lease Number  
SF-080390  
6. If Indian, All. or  
Tribe Name  
7. Unit Agreement Name  
8. Well Name & Number  
McIlroy #1  
9. API Well No.  
30-045-08452  
10. Field and Pool  
Fulcher-Kutz PC  
11. County & State  
San Juan County, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment

Type of Action

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other -

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

Norman L. Gilbreath plugged and abandoned this well on May 15, 2003 per the attached plugging report.

14. I hereby certify that the foregoing is true and correct.

Signed

Norman L. Gilbreath

Title

Operator

Date 5/22/03

(This space for Federal or State Office use)

APPROVED BY

Title

Date

CONDITION OF APPROVAL, if any:

ACCEPTED FOR RECORD

JUN 02 2003

FARMINGTON FIELD OFFICE

NMOCD

# A-PLUS WELL SERVICE, INC.

P.O. BOX 1979  
FARMINGTON, NM 87499  
505-325-2627 • FAX: 505-325-1211

---

Norman L. Gilbreath

## **McIlroy #1**

820' FSL & 1750' FEL, Section 7, T-29-N, R-12-W  
San Juan County, NM  
Lease Number: SF-080390  
API Number: 30-045-08452

May 16, 2003

Page 1 of 1

## **Plug & Abandonment Report**

### **Cementing Summary:**

**Plug #1** with 52 sxs cement inside casing from 1541' to 1093' to fill Pictured Cliffs perforations and cover top.

**Plug #2** with retainer at 310', mix and pump 53 sxs cement, squeeze 30 sxs outside 5-1/2" casing at 350' and leave 23 sxs inside casing to cover Ojo Alamo top.

**Plug #3** with cement retainer at 93', mix and pump 68 sxs cement: 1<sup>st</sup> from squeeze holes at 110' to surface, circulate good cement out 5-1/2" casing through holes at 50'; 2<sup>nd</sup> sting out of retainer and fill 5-1/2" casing with good cement to surface; 3<sup>rd</sup> TOH and LD tubing; 4<sup>th</sup> squeeze 12 sxs down 5-1/2" casing, then shut in the well with 400# pressure.

### **Plugging Summary:**

Notified BLM

5/14/03 MOL. Held JSA. RU rig. Pressure test tubing to 500#. POH with rods, no pump - 3/4" rods. Found rods parted. Dig out wellhead, found no surface casing or bradenhead outlet, just 5-1/2" casing. Install and test BOP. TOH with 40 joints 2-3/8" tubing, total 1255'. Found parted rod, strip rods and tubing out of well. Total 49 joints 2-3/8" tubing. TIH with tubing to 1541'. V. Jamison, BLM representative, required extra cement for plug. Plug #1 with 52 sxs cement inside casing from 1541' to 1093' to fill Pictured Cliffs perforations and cover top. PUH and WOC.

5/15/03 Held JSA. TIH and tag cement at 1090'. Circulate well clean with 30 bbls of water. Pressure test casing to 500#. TOH and LD tubing. Perforate 3 squeeze holes at 350'. Pump 35 bbls of water 1-1/2 bpm at 500# with no circulation to surface outside casing. BLM required: TIH and set 5-1/2" DHS cement retainer at 310'. Perforate at 50' and attempt to establish circulation to surface 1-1/2 bpm at 500#. Plug #2 with retainer at 310', mix and pump 53 sxs cement, squeeze 30 sxs outside 5-1/2" casing at 350' and leave 23 sxs inside casing to cover Ojo Alamo top. TOH and LD tubing. BLM required: Perforate at 110'. TIH and set 5-1/2" DHS cement retainer at 93'. Pump below CR at 93' and establish circulation out squeeze holes at 50', 1-1/2 bpm at 400#. Plug #3 with cement retainer at 93', mix and pump 68 sxs cement: 1<sup>st</sup> from squeeze holes at 110' to surface, circulate good cement out 5-1/2" casing through holes at 50'; 2<sup>nd</sup> sting out of retainer and fill 5-1/2" casing with good cement to surface; 3<sup>rd</sup> TOH and LD tubing; 4<sup>th</sup> squeeze 12 sxs down 5-1/2" casing, then shut in the well with 400# pressure. WOC. Open up well, no pressure. ND BOP. RD rig. Cutoff wellhead. Found cement at surface in 5-1/2" casing. Mix 10 sxs cement and install P&A marker. MOL. V. Jamison, BLM representative, was on location.