Form 3160- 5 (August 2007) JUL 07 2016

UNITED STATES DEPARTMENT OF THE INTERIOR FORM APPROVED

OMB No	1	004-	013	7
Conican	T1	21	201	n

BUREAU OF LAND MANAGEMENT Farmington Field Office Expires: July 31,2010 Bureau of Land Mar signesseserial No. SUNDRY NOTICES AND REPORTS ON WELLS Jicarilla Contract 451 Do not use this form for proposals to drill or to re-enter an If Indian, Allottee, or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. Jicarilla Apache Tribe If Unit or CA. Agreement Name and/or No. SUBMIT IN TRIPLICATE - Other Instructions on page 2. 23931 Type of Well Well Name and No. Oil Well ✓ Gas Well Jicarilla 451-03 #41 Name of Operator API Well No. Black Hills Gas Resources, Inc. 03-039-29247 3a. Address Phone No. (include area code) 10. Field and Pool, or Exploratory Area Cabresto Cny Tert/ P.O. Box 249 Bloomfield, NM 87413 (505) 634-5104 Location of Well (Footage, Sec., T., R., M., or Survey Description) Basin Fruitland Coal / East Blanco Pictured Cliffs 870' FSL & 455' FWL SW/SW Section 3, T29N R3W (UL: M) 11. County or Parish, State Rio Arriba County, New Mexico 12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION ✓ Notice of Intent Water Shut-off Production (Start/Resume) Acidize Deepen Altering Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Recomplete Other Subsequent Report Change Plans Plug and abandon Temporarily Abandon

13. Describe Proposed or Completed Operation Clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

Plug back

Black Hills Gas Resources intends to plug and abandon Jicarilla 451-03 #41 per attached procedure. Black Hills will be using a close loop system

Convert to Injection

Attachments:

Procedure

Current wellbore diagram Proposed wellbore diagram Reclamation plan

Final Abandonment Notice

BLM'S APPROVAL OR ACCEPTANCE OF THIS **ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS** ON FEDERAL AND INDIAN LANDS.
Notify NMOCD 24 hrs

prior to beginning operations

Water Disposal

SEE ATTACHED FOR CONDITIONS OF APPRO

OIL CONS. DIV DIST. 3 JUL 21 2016

14. I hereby certify that the foregoing is true and correct. Name (Printed Typed) **Daniel Manus** Regulatory Technician II Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by avoice PE Title Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable till to those rights in the subject lease which would Office FFO opplicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

PLUG AND ABANDONMENT PROCEDURE

June 29, 2016

Jicarilla 451-03 #41

East Blanco Pictured Cliffs/Basin	n Fruitland Coal /Cabresto Canyon Tertia	ary
870' FSL, 455' FWL, Section	n 3, T29N, R3W, Rio Arriba County, NM	
API 30-039-29247 / Long	g:/ Lat:	

- Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.
- 2. This project will use an A-Plus steel tank to handle waste fluids circulated from well and cement wash up.
- 3. Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.

4.	Rods:	Yes_	,	No_X	, Unknown					
	Tubing:	Yes	X	, No	, Unknown	, Size _	2-3/8"	, Length _	3663'	
	Packer:	Yes_	Χ_,	No	, Unknown	_, Type _	Baker A	Baker AR-1 pkr @ 2826'		
	Packer:	Yes	Χ .	No	. Unknown	, Type	Baker H	ornet pkr@ 34	195'	

NOTE: This well has 2 packers. PU on tubing and release packer(s). TOH and LD packer(s). If packer dragged coming out of hole then RIH with scraper. If packer(s) came out of hole free then proceed to Plug #1.

- 5. Plug #1 (Pictured Cliffs interval, Fruitland, Kirtland and Ojo Alamo interval, 3752' 3110'): Mix 95 sxs Class B cement (30% excess, long plug) and spot plug to fill the Pictured Cliffs and Fruitland Coal perforations and cover the Fruitland, Kirtland and Ojo Alamo tops. PUH and WOC. TIH and tag cement 50' above top of Ojo Alamo. If necessary top off cement and go to Plug #2.
- 6. Plug #2 (Nacimiento perforations and top, 2826' 2032'): Round trip 5.5" gauge ring or mill to 2826'. TIH and set 5.5" CR or CIBP at 2826'. _Mix 117 sxs Class B cement (30% excess, long plug) and spot to isolate the lower Nacimiento perforations and fill the upper Nacimiento perforations then cover through the top. TOH with tubing and WOC. TIH and tag cement 50' above Nacimiento top. If necessary top off cement and go to Plug #3.
- 7. Plug #3 (8-5/8" Surface casing shoe, 330' Surface): Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 40 sxs cement and spot a balanced plug from 330' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the casing from 330' and the annulus from the squeeze holes to surface. Shut in well and WOC.
- ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A marker to comply with regulations. Record GPS coordinate for P&A marker on tower report. Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM stipulations.

Jicarilla 451-03 #41 Current

East Blanco Pictured Cliffs / Basin Fruitland Coal /Cabresto Canyon Tertiary 870' FSL & 455' FWL, Section 3, T-29-N, R-3-W, Rio Arriba County, NM

/ Lat: / API 30-039-29247 Today's Date: 6/29/16 Spud: 10/15/04 Comp: 3/13/05 Elevation: 7052' GI 8-5/8" 24#, K-55 Casing set @ 280' Cement with 175 sxs, circulated to surface 12-1/4" Hole 7065' KB 2-3/8" 4.7# J-55 tubing at 3663' (Baker AR-1 pkr at 2826' and Baker Hornet pkr at 3495') with WL re-entry guide at 3663' Nacimiento @ 2082' Nacimiento Perforations: 2246' - 2248' Baker AR-1 Pkr (COE fullbore 1.91") 2826' Nacimiento Perforations: 2876' - 2885' Nacimiento Perforations: 3066' - 3141', sqz'd with 80 sxs (2005) Ojo Alamo Perforations: Ojo Alamo @ 3160' 3162' - 3166', sqz'd with 80 sxs (2005) Ojo Alamo Perforations: 3251' - 3278', sqz'd with 50 sxs, 35 sxs (2005) Kirtland @ 3399' Baker Hornet Pkr (COE) 3495' Fruitland @ 3527' Fruitland Coal Perforations: 3536' - 3598' Pictured Cliffs Perforations: Pictured Cliffs @ 3649' 3648' - 3702' 7-7/8" Hole 5.5" 15.5#/17#, J-55 Casing @ 3760' Cement with 650 sxs, circulate 5 bbls to surface 3760' TD

3760' TD 3760' PBTD

Jicarilla 451-03 #41 Proposed P&A

East Blanco Pictured Cliffs / Basin Fruitland Coal /Cabresto Canyon Tertiary 870' FSL & 455' FWL, Section 3, T-29-N, R-3-W , Rio Arriba County, NM

	Long:	/ Lat:	/ API 30-039-29247	
Today's Date: 6/29/16 Spud: 10/15/04 Comp: 3/13/05 Elevation: 7052' GI 7065' KB	12-1/4" Hole		8-5/8" 24#, K-55 Casing set @ 280' Cement with 175 sxs, circulated to surface	
			Plug #3: 330' – 0' Class B cement, 40	sxs
Nacimiento @ 2082'			Nacimiento Perforations: 2246' – 2248' Plug #2: 2826' – 20 Class B cement, 11' (30% excess, long p	7 sxs
			Set CR @ 2826'	
		3000- 3000- 3000-	Nacimiento Perforations: 2876' – 2885'	
			Nacimiento Perforations:	
			3066' - 3141', sqz'd w/ 80 sx (2005) Plug #1: 3752' – 31	1402
Ojo Alamo @ 3160'		W	Class B cement, 95 (30% excess, long p	SXS
			3162' – 3166', sqz'd w/ 80 sx (2005)	
Kid1 @ 2222			Ojo Alamo Perforations: 3251' – 3278', sqz'd w/ 50 sx, 35 sx (2005)	
Kirtland @ 3399'				
Fruitland @ 3527'				
			Fruitland Coal Perforations: 3536' – 3598'	
Pictured Cliffs @ 3649'			Pictured Cliffs Perforations: 3648' – 3702'	
	7-7/8" Hole			
	7-770 11016		5.5" 15.5#/17#, J-55 Casing @ 3760' Cement with 650 sxs, circulate 5 bbls to su	urface
		3760' TD		
		3760' PBTD		

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon: Re: Permanent Abandonment Well: Jicarilla 451-03 #41

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) Bring the top of plug #2 to 1860 ft. to cover the Nacmiento top. BLM picks top of Nacimiento at 1910 ft. Adjust cement volume accordingly.

 H_2S has not been reported at this location, however, low concentrations of H_2S (2 ppm – 46 ppm GSV) have been reported in wells within a 1 mile radius of this location.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.