

RECEIVED

JAN 12 2017

Form 3160-5  
(August 2007)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB No. 1004-0137  
Expires: July 31, 2010

Farmington Field Office

SF-079266

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

Oil Well  Gas Well  Other

2. Name of Operator

**Burlington Resources Oil & Gas Company LP**

3a. Address

**PO Box 4289, Farmington, NM 87499**

3b. Phone No. (include area code)

**(505) 326-9700**

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

**Surface Unit D (NWNW), 940' FNL & 1190' FWL, Sec. 29, T26N, R6W**

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.

**Vaughn 32**

9. API Well No.

**30-039-23923**

10. Field and Pool or Exploratory Area

**Blanco MV / Basin DK / Ensenada GL**

11. Country or Parish, State

**Rio Arriba, New Mexico**

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION				
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off	
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity	
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other <u>Water Shut Off</u>	
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon		
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal		

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

**Burlington Resources requests permission to perform remedial work on the subject well per the attached procedure and current wellbore schematic.**

**BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS**

OIL CONS. DIV DIST. 3

JAN 20 2017

Notify NMOCD 24 hrs prior to beginning operations

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

**Dollie L. Busse**

Title **Regulatory Technician**

Signature

Date

1/12/2017

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title **PE**

Date **1/18/17**

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office **FFO**

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

NMOCD

3 elv

**ConocoPhillips  
VAUGHN 32M  
Expense - Repair Casing**

Lat 36° 27' 42.228" N

Long 107° 29' 44.448" W

**PROCEDURE**

1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. If a base beam cannot be utilized, Test rig anchors prior to moving in rig. Before RU, run slickline to check for and remove any downhole equipment. If an obstruction is found and cannot be recovered, set a locking 3-slip-stop above the obstruction in the tubing.
2. MIRU workover rig. Check casing, tubing, and bradenhead pressures and record them in Wellview. **If there is pressure on the BH, contact Wells Engineer.**
3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with 2% KCl as necessary. Ensure well is dead or on vacuum.
4. ND wellhead and NU BOPE. Pressure and function test BOP to 250 psi low and 1,000 psi over SICP high to a maximum of 2,000 psi held and charted for 10 minutes as per COPC Well Control Manual. PU and remove tubing hanger and tag for fill, adding additional joints as needed. Record pressure test and fill depth in Wellview.
5. RU Tuboscope Unit to inspect tubing. TOOH with tubing (per pertinent data sheet). LD and replace any bad joints and record findings in Wellview. **Make note of corrosion, scale, or paraffin and save a sample to give to CIC/engineering for further analysis.**
6. PU 3-3/4" string mill and bit and CO to PBTD at 7,504' using the air package. TOOH. LD mill and bit. If fill could not be CO to PBTD, call Wells Engineer to inform how much fill was left and confirm/adjust landing depth.
7. RIH with a RBP and Packer in tandem. Set the RBP and test the WH, contact the well s engineer with the WH test. RIH and set the RBP at 5,200', load the hole and pressure test the CSG to 560 psi.. Contact the wells engineer with the results and plan forward to hunt for the source of water in the well. If squeeze work is required, **notify the BLM and OCD at least 24 hours prior to performing squeeze work.**
8. If a casing leak is confirmed, Locate the casing leak using a packer. After casing leak(s) is located, contact the wells engineer to determine economics for repair. If a repair attempt is made Squeeze cement as discussed with engineer.**notify the BLM and OCD at least 24 hours prior to performing squeeze work.** WOC. Drill out cement. Pressure test casing to 560 psi. Contact engineer with results and discuss plan forward. If test passes, pressure test the wellbore to 560 psig for 30 minutes on a 2 hour chart with 1000# spring.
9. TIH with tubing using Tubing Drift Procedure. (detail below).

Tubing W/Grade: 4.7 ppf, J-55  
Tubing Drift ID: 1.901"

Land Tubing At: 7,626'  
KB: 12'

**Tubing and BHA Description**

1	2-3/8" Exp. Check
1	1.78" ID "F" Nipple
1	full jt 2-3/8" tubing
1	pup joint (2' or 4')
+/-228	jts 2-3/8" tubing
As Needed	pup joints for spacing
1	full jt 2-3/8" tubing

10. Ensure barriers are holding. ND BOPE, NU Wellhead. Pressure test tubing slowly with an air package as follows: pump 3 bbls pad, drop steel ball, pressure tubing up to 500 psi, and bypass air. Monitor pressure for 15 mins., then complete the operation by pumping off the expendable check. Note in Wellview the pressure in which the check pumped off. Purge air as necessary. Notify the MSO that the well is ready to be turned over to Production Operations. RDMO.

**Tubing Drift Procedure**

**PROCEDURE**

1. Set flow control in tubing. With air, on location, use expendable check. With no air on location, use wire line plug.
2. RU drift tool to a minimum 70' line. Drift tool will have an OD of at least the API drift specification of the drift diameter of the tubing to be drifted, and will be at least 15" long. The tool will not weigh more than 10# and will have an ID bore the length of the tool, so fluids may be pumped through the tool if it becomes stuck.
3. Drop the tool into the tubing string and retrieve it after every 2 joints of tubing ran in hole. If any resistance to the tool movement is noticed, going in or out, that joint will be replaced.

NOTE: All equipment must be kept clean and free of debris. The drift tool will be measured with calipers before each job, to ensure the OD is the correct size for the tubing being checked. The maximum allowable wear of the tool is 0.003".



Schematic - Current

VAUGHN #32M

District SOUTH	Field Name BSN DK(PRO GAS) #0068	API UWI 3003923923	County RIO ARRIBA	State/Province NEW MEXICO
Original Spud Date 11/4/1985	Surface Legal Location 029-026N-006W-D	East/West Distance (ft) 1,190.00	East/West Reference FWL	North/South Distance (ft) 940.00
North/South Reference FNL				

Original Hole, 12/19/2016 3:23:33 PM

