Distribution: O+4 (BLM);	1-Accounting; 1- Lan	nd; 1-File			/1		
Form 3160-5 UNITED STATES (September 2001) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT						FORM APPROVED OMB No. 1004-0135 Expires January 31, 2004 Lease Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS						SF-080384-B	
/\$	not use this form for prop abandoned well. Use Fo		=			5. If Indian, Allottee or Tribe Name	
	T IN TRIPLICATE - C	Other instruction	ons on rev	erse side		7. If Unit or CA, Agreement, Name and/o	or No
1. Type of Well						3. Well Name and No.	
Oil Well X Gas Well Other  2. Name of Operator						HICCUP A No. 2	
MERRION OIL & GAS CORPORATION						O. API Well No.	
1			No. (include area code)			30-045-30257	
610 Reilly Ave., Farmington, NM 87401 (505) 327-  4. Location of Well (Footage, Sec., T., R., M., or Survey Description			01			10. Field and Pool, or Exploratory Area	
						BASIN FRUITLAND	
1820' FSL & 820' FWL (NW SW)						11. County or Parish, State	
SECTION 3, T26N, R12W						SAN JUAN COUNTY, NM	
12. C	HECK APPROPRIAT	E BOX (ES) TO II	NDICATE N	ATURE OF NOTICE,	REPORT	, OR OTHER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION					
	Acidize	Deepen		Production (Start/Resume)		Water Shut-Off	
Notice of Intent		Fracture Treat		Reclamation		Well Integrity	
r'es:	Casing repair	New Construc	tion 📮	Recomplete		Other Testing	
Subsequent Report			ndon 🛄	Temporarily Abandon			
Final Abandonment Notice	Convert to Injection	Plug Back		Water Disposal			
If the proposal is to deepe Attach the Bond under wh following completion of th testing has been completed determined that the site is  5/16/03 Tubing 0 psi	n directionally or recomplete ich the work will be perform e involved operations. If the firm Abandonment shall	e horizontally, give sui ned or provide the Bo e operation results in be filed only after all i casing to atmosph	bsurface location and No. on file a multiple com requirements, in	ons and measured and true of with BLM/BIA. Required so pletion or recompletion in a ncluding reclamation, have b	vertical dept ubsequent ro a new interv peen comple		
5/19/03 Tubing 0 psi, Casing 0 psi. With a very light blow of gas on casing. Shut well in to build pressure.							
5/20/03 Tubing 0 psi, Casing 62 psi. 5/21/03 Tubing 0 psi, Casing 82 psi.							
• • • • • • • • • • • • • • • • • • • •	II Service Rig No. 1 on 5/	22/03. Tubing 0 psi	i, Casing 93 p	si. Found rods stuck in	the tubing	backed rods off.	
	s with 53 x 3/4" plain rod	=				260 70 CT CU 77 25%	
1" of stretch	. Worked tubing did not			THER SIDE***	i. RDMOL.	2003	
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)							12
CONNIE S. DINNING			Title ENG	INEER		1 0 . O X	Ž
Signature			Date	August 12, 2003	,	<u> </u>	<i>y</i>
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						CCEPTED FUR RECURS	
						AUG.1 82003	
Approved by  Conditions of approval, If any, are attached. Approval of this notice does not warrant or			Title			Date	
certify that the application holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Offic	e		FARMINGTON FIELD OFFICE	
Title 18 U.S.C. Section 1001 and Ti States any false, fictitious or fraud					epartment or	agency of the United	

7/31/03 MIRU Professional Well Service Rig 3 on 7/31/03. ND WH, pulled 70,000 psi on tubing, tubing did not come free. MIRU Wireline Specialties, found top of sucker rod @ 1335', the tubing was free at that point, found tubing collar @ 1304', moved down to the approx. middle of the joint and cut the tubing off @ 1319' KB. TOH with 40 joints of tubing, shut well in. SDON.

A REMARK TO THE SERVICE OF THE

**通过其外的** 66

- 8/01/03 TIH with overshot, bumper sub and 4 x 3-1/8" drill collars began jarring. Lost 8" length into hole then began making some hole. Jarred until we had made approx. 3' of hole, began pumping water down casing at a rate of 1/2 BPM with the formation taking the water very slowly. The water did not help the jarring. After we had made a total of 4' of hole with no travel up and down we stopped jarring and attempted to release the overshot and could not. Shut well in. SDON.
- Jarred on overshot and it released the first time we jarred. TOH with jarring tools. TIH with wash over pipe and "T-dog overshot" which is a collar catcher. RU power swivel, pump and began pumping down the tubing to establish circulation. Pumping in at a rate of 2 BPM, only getting 1/2 BPM returns which was not sufficient to circulate fill out of the hole. Pumped 38 bbls with returns not getting any better, shut down pumping, called and set up Halliburton nitrogen truck for 8 AM on Monday (8/4) to wash over and CO the fill. SD for weekend.
- RU Halliburton nitrogen truck began pumping nitrogen and drilling on fill, drilled approx. 12' and the power swivel hydraulic pump blew a seal. SD drilling pulled up above stuck pipe 10', CO hole with nitrogen, shut nitrogen truck down. Waited 4 hours for replacement of hydraulic pump began pumping operation again. Drilled approx. 4" in 10 mins and found that the returns were almost all metal shavings. Shut cleanout operation down, released Halliburton, LD 40 joints of tubing, washover pipe and kutrite shoe. Shut well in. SDON.
- 8/5/03 NU WH, shut well in. RDMOL.